124-5

FIRE SERVICE INCORPORATED

27006

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	AREA'S		CABLE	XTUNE	SENS TEST	S/D
21	PASS ELEV.		1	020	2.8	BLK
	COMM A		1	204	3.0	BLK
	ELECT A		1	204	3.0	BLK
	TELEPH A		1	204	3.0	BLK
	FREIGHT ELEV.		1	020	3.0	BLK
	ELECT B		1	204	2.8	BLK
	COMM B		1	204	3.0	BLK
	TELEPH B		1	204	3.0	BLK
21	ELECT C		1	205	3.0	BLK
	COMM C		1	205	3.2	BLK
	TELEPH C		1	205	3.0	BLK
	TELEPH D		1	205	3.0	BLK
	COMM D		1	205	3.2	BLK
	ELECT D		1	205	3.0	BLK
21	CORE HER D/D		1	008	3.2	Hochiki
(C)	CORE HER D/D		1	008	8.2	Hochiki
	– TO BE REPLACE		(UNIT DEFECTIVE)			
21	RETURN D/D SOUTH		1	007	3.0	Hochiki
	RETURN D/D NORTH		1	007	3.2	Hochiki
13	STROBE PANEL AFC 101 (B COMM)					
	(2) BATTERIES REPLACED – (20W)					
	TROUBLE / BATTERIES					

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 8-22-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: FSN2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	12 VOLTS BATTERIES	69.95

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE: Miguel Rivera

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME X

SERVICE PERFORMED & REMAINING: S/CONTRACT – PREVENTIVE MAINTENANCE SMOKE DETECTOR CHECKS – SENSITIVITY TEST AS (SHOWN ABOVE) — LOCATIONS ON 21ST FL. – ALSO TROUBLE SHOOTER 21ST FL. DUCT DETECTOR CORE HER (1) FIRST TO BE REPLACED (SENSITIVITY OUT RANGE). – UNIT SIF24 HOCHIKI TYPE. –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

:27007

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	AREA'S		CABLE	XTNDR	TST SENS	S/D.
20	COMM A		1	203	2.8	BLK
	ELECT A		1	203	3.0	BLK
	TELEPH A		1	203	3.0	BLK
	ELECT B		1	203	3.0	BLK
	COMM B		1	203	3.0	BLK
	TELEPH B		1	203	3.2	BLK
	ELEV. PASS		1	019	3.0	BLK
	ELEV. FREIGHT		1	019	2-8	BLK
	—		—			
	COMM C		1	202	3.0	BLK
	ELECT C		1	202	2-8	BLK
	TELEPH C		1	202	3.0	BLK
	ELECT D		1	202	3.0	BLK
	COMM D		1	202	3.2	BLK
	TELEPH D		1	202	3.0	BLK
	CORE HEL D/D		1	006	3.2	Hochiki
	CORE HEL D/D		1	006	3.2	Hochiki
	RETURN D/D.		1	005	3.2	Hochiki
20	RETURN D/D.		1	005	3.0	Hochiki
	RETURN D/D EAST		3	045	3.2	D13
46	STROBE PNL 'B' COMM. Trouble					STATUS
	Repaired 'A' circuit — AS F.S.D					—
	Panel Restored to normal. —					

INVOICE TO: 7W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 8-28-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LJN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe.

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: S/CONTRACT. — S/DETECTORS Check. Also Testing Sensitivity / Clogging Semiannual Service. — Also repairs on 46 floor STROBE PNL AFC100 - 'A' Loop Circuit Correcting. — SYSTEM OK / RESTORED. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. or representative that it may be necessary to interrupt the fire protection service by discontinuing the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME

DATE

TIME

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

27064

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	Area		Cable	Xmdr	S/D	Tst Sens
23	Pass Elev.		2	000	Blk	2.8
	Comm B		2	169	Blk	3.0
	Elect B		2	169	Blk	3.0
	Teleph B		2	169	Blk	3.0
	Elect A		2	169	Blk	3.2
	Comm A		2	169	Blk	3.0
	Teleph A		2	169	Blk	2.8
	Freight Elev		2	000	Blk.	3.0
	Core Hea D/D		2	228	Hochiki	3.2
23	Core Hea D/D		2	228	Hochiki	3.2
	Elect C		2	168	Blk	3.0
	Comm C		2	168	Blk	3.0
	Teleph C		2	168	Blk	3.2
	Comm D		2	168	Blk	3.0
	Elect D		2	168	Blk	3.0
	Teleph D		2	168	Blk	3.0
	Return D/D	Ladies	2	227	Hochiki	3.4
	Return D/D	North	N/A - As previous			
23	Return D/D	South	N/A - As previous			
13	Strobe Pnl Trouble Condition 101 Model Cleared. - Status -					
14	Sub System Pnl Trouble - (Unit in Trouble / Computer Area - 14th Fl) Zone wires lifted TTB (15th Fl) - (TB6 2-8)					
	To restore, Supv. wires TTB when SS is restored to normal condition					

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. [illegible] / F. Rosario	F.S.D.
	DATE SCHEDULED: 8-29-01
CONTRACT #: 5/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Sensitivity Test / Maintenance as per Contract on 23rd Fl (Silverstein Area D/D) - As listed above & Repairs on 13th/14th Fl. Sub Systems — as per F.S.D.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

TIME
DATE
NAME

FIRE SERVICE INCORPORATED

27065

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS: Corridors.		DEVICES: Cable	XTNDR	S/D	TST SENS.
19	ELECT A		1	201	BLK	3.0
	COMM A		1	201	BLK	3.0
	TELEPH "A"		1	201	BLK	2.8
	ELECT B		1	201	BLK	2.8
	COMM B		1	201	BLK	3.0
	TELEPH B		1	201	BLK	3.0
	ELEV LBBY PASS		1	018	BLK	3.0
19	FREIGHT ELEV.		1	018	BLK	3.2
	ELECT C		1	200	BLK	3.0
	COMM C		1	200	BLK	2.8
	TELEPH C		1	200	BLK	2.8
	CORE HEL D/D		1	004	Hochiki	3.4
19	CORE HEL D/D		1	004	Hochiki	3.2
	PLENUM RETURN D/D		1	003	Hochiki	3.2
	PLENUM RETURN D/D		1	003	Hochiki	3.2
	ELECT D		1	200	BLK	3.0
	COMM D		1	200	BLK	3.0
	TELEPH D		1	200	BLK	3.0

(*) 47 WATERFLOW S/W Z OH2 ALARM - CHECK / TROUBLE SHOOTING DEVICE / TTB INPUT - DEVICE ISOLATED FROM TTB - TO BE MONITORED - (POSSIBLE DEFECTIVE S/W DEVICE)

(*) 14" SMOKE PANEL SUB SYSTEM TROUBLE / TRACING / CHECK - INTO A SUB SYSTEM CODE 842 IN TROUBLE STATUS / PANEL DISABLED FOUND SEVERAL ZONES DISMANTLED BY TENANT - (MOVE-OUT) -

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED: 9-4-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:00 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): D. GIACOMAZZA
CUSTOMER SIGNATURE: [signature] 9/5/01
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE / SMOKE DETECTOR UNITS SENSITIVITY CHECK ON 19TH FL AS PER SCHEDULE AT LISTED AREAS

(*) ALSO CHECK / TROUBLE SHOOTING FLOOR 47 W/FLOW (112) ALARM DEVICE ISOLATED FROM SYSTEM - TO BE MONITORED CLASS "E" SYSTEM - TO BE FOLLOW UP. AND 14TH FL SUB SYSTEM - TO BE RESTORE TO NORMAL BY TENANT (SOLOMON BROTHERS)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

(INPUT LIFTED ON TTB SYSTEM, UNTIL S.SYSTEM - RESTORE NORMAL STATUS

FIRE SERVICE INCORPORATED

27066

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		CABLE	XTNDR	S/D	TEST SENS
18	COMM A		1	199	BLK	3.2
	ELECT A		1	199	BLK	3.0
	TELEPH A		1	199	BLK	3.0
	PASS ELEV.		1	017	BLK	3.0
18	FREIGHT ELEV.		1	017	BLK	3.0
	ELECT B		1	199	BLK	3.0
	COMM B		1	199		2.8
	TELEPH B		1	199		3.0
	ELECT C		1	198	BLK	3.0
	TELEPH C		1	198		3.2
	COMM C		1	198		3.0
	ELECT D		1	198	BLK	2.8
	COMM D		1	198		2.8
18	TELEPH D			198		3.0
	PLENUM RETURN D/D-N		1	001	Hochiki	3.2
	PLENUM RET. D/D SOUTH		1	001	Hochiki	3.2
	CORE HEX D/D		1	002	Hochiki	3.2
	CORE HER D/D		1	002	Hochiki	3.4
17	PASS ELEV.		1	016	BLK	3.0
	FREIGHT ELEV.		1	016	BLK	3.0
	ELECT A-B	(2)	1	197	BLK	3.0/3.2
	COMM A-B	(2)	1	197	BLK	3.0
	TELEPH A-B	(2)	1	197	BLK	3.0/2.8
	CORE HER D/D		1	000	Hochiki	3.4
	CORE HER D/D		1	000	Hochiki	3.4
	ELECT C		1	196		
	COMM C		1	196		
	TELEPH C		1	196		
	TELEP D		1	196		
	COMM D		1	196		
	ELECT D		1	196		
17 FL (*)	RETURN D/D	NOT	AVAILABLE AS			
	PREVIOUS	REPORTED				

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRE / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 9-05-01
CONTRACT #: S/C 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #: -	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): D GIACOMAZZA
CUSTOMER SIGNATURE: [signature] FSD 9/5/01
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: PREVENTIVE MAINTENANCE - CLASS E FIRE SYSTEM - SMOKE DETECTOR AREAS ABOVE LISTED 18th/17th FLOOR'S SENSITIVITY TESTED. —

(*) NOTE RETURN D/DETECTOR NOT AVAILABLE - NO ACCESS PROVIDED CEILING SOLID - 17th FLOOR

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SEPVICE INCORPORATᴱD

102313

SUBSIDIARY OF FIRE ... M INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 699-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		09-05-01	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE CONTRACT -		

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 09-05-01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature] 9/5/01

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED

Service Maintainance

SERVICE PERFORMED

assisting Jimmy T. on the performing of the Service Maintainance.

WORK REMAINING

FCI 155

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name   Date

FIRE SERVICE INCORPORATED

102312

SUBSIDIARY OF FIRE[illegible] INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7 W T C Nao York 1024.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		3C00818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		09-04-01	A.M.			Fo... R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE CONTRACT		

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 A.M.	9:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ OTHER
- ☐ PARTIAL
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 09-04-01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature] 9/5/01

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED

Service Maintenance

SERVICE PERFORMED

Assisting Jimmy T. on the performing of the service maintenance.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ______ Date ______

FIRE SEP'VICE INCORPORAT"D 97685

SUBSIDIARY OF FIRE ...M INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, NY.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	F.I. #	P.O. #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		08/15/01	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F.C.I. NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ OTHER
- ☐ PARTIAL
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 08/15/01

WILL RETURN ON

CUSTOMER SIGNATURE: Soxrette

SERVICEMAN SIGNATURE: Frank R.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Rossa on the Performing of the Service Contract, Cleaning, Test, Clean, and Sensitivity of the Smoke Detectors, on 24th Floor, etc.

WORK REMAINING

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

97687

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
710 T G
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		Sc00818				F.S.D.
PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		08/22/01	AM.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800 AM.	430 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 08/22/01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

[illegible] per the [illegible] of the Service Contract.

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

97688

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		08/21/01	AM.			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE CONTRACT		

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 08/21/01

WILL RETURN ON:

CUSTOMER SIGNATURE: Miguel Rivera

SERVICEMAN SIGNATURE: Frank L.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Testing [illegible] per the [illegible] of the Service Contract!

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ____________ Date ____________

X

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

97689

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
	SC00818				F.S.I.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		8/29/01	A.M.	

MATERIAL RECORD

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

- ☐ MAT REQD
- ☐ OTHER
- ☐ PARTIAL
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 8/29/01

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: [illegible]

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy T. Dee the Performing of the Service Contract.

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the [redacted] precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

97690

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		Sc008 18				F. S. D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		8/28/01	A.M.			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
					PREVENTIVE MAINTENANCE CONTRACT	

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 8/28/01

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: Frank L.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Office Supply I. On the Performing of the Service Contract

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name ______ Date ______

X

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

23499

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR	AREAS	CLOSET		XTNDR	CABLE	SENS	S/D
24	PASS	ELEV.		001	2	2.8	BLK
	FREIGHT	ELEV		001	2	2.8	BLK
	COMM	A CLOSET		171	2	3.0	BLK
	ELECT	A "		171	2	3.0	BLK
	TELEPH	A "		171	2	3.0	BLK
	COMM	B "		171	2	3.0	BLK
	ELECT	B		171	2	2.8	BLK
	TELEPH	B		171	2	3.0	BLK
24	ELECT	C		173	2	3.0	BLK
	COMM	C		173	2	3.2	BLK
	TELEPH	C		173	2	3.0	BLK
	ELECT	D		173	2	2.8	BLK
	COMM	D		173	2	3.0	BLK
	TELEPH	D		173	2	3.0	BLK
	RETURN DUCT DET. NORTH			230	2	3.2	Hochiki
	RETURN DUCT DET. SOUTH			230	2	3.2	Hochiki
	BREEZER D/D			231	2	3.2	Hochiki
25	BREEZER D/D			231	2	3.0	Hochiki
16	STROBE PNL Repairs AFL 100						
	A-B LOOPS - / BATTERIES NEEDED						
	(2) 12 VLTS. -						
	TO Replace. -						

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F-5-9
	DATE SCHEDULED: 8-15-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): S. Keefe

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME: X.

SERVICE PERFORMED & REMAINING: As per Contract — Preventive Maintenance on Smoke Detectors 24 Fl. - as Listed above. Sensitivity Test Sensing All Areas / Closets - MER's - Elevator Lobbies. - System Blk Ready Back to Operation. —
Also Repairs on 16 Fl AFL 100 Panel - as per F-5-9. Trouble / Reality (B) NEEDED (2) BATTERIES 12 VLTS. - TO Replace. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OT

FIRE SERVICE INCORPORATED 23500

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS: Area's -		DEVICES: Qty	Zone	Tst Sens	Cleaned
22	Elev. lbby		1	021	3.0	✓
	Elect A		1	207	3.2	✓
	Comm A		1	207	3.0	✓
	Teleph A		1	207	3.0	✓
	Teleph B		1	207	3.0	✓
	Elect B		1	207	2.8	✓
	Comm B		1	207	3.0	✓
22	Freight Elev		1	021	3.2	✓
	Elect C		1	206	3.0	✓
	Comm C		1	206	3.0	✓
	Teleph C		1	206	3.0	✓
	Teleph D		1	206	2.8	✓
	Elect D		1	206	2.8	✓
	Comm D		1	206	3.0	✓
	Return Duct Det. S.		1	009	3.2	✓
	Return D/D North		1	009	3.2	✓
	Core Mer D/D		1	010	3.0	✓
22	Core Mer D/D		1	010	3.2	✓

16 Strobe Panel (AFC 100) Core Mer.
Replaced (2) Batteries 12 Volts.
- Back up Pwr. -

44 Security (Solomon Brothers) Office Fan
Unit Check for operation / running
as per Request. -

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.
22nd Fl

SERVICEMAN ASSIGNED: J. Torres / F. Rosario	SEE AT JOB SITE: F.S.D.
	DATE SCHEDULED: 8-21-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2001
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	12 Volts Batteries	69.95

CUSTOMER NAME (PRINT)
CUSTOMER SIGNATURE Miguel [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING S/Contract. -
Preventive Maintenance & Sensitivity Test Performed on Smoke Detectors
Areas Above Listed on 22nd Floor's - (Silverstein Spaces) -
Also Performed Repair on 16th Fl. (2) Batteries 12 Volts Replaced. -
For Strobe Pnl AFC 100 - (Old Batt's Defective). -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

23498

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	Area Closet			Cable	XTND	S/D	SENS TEST
25	Pass Elev.			2	002	BRK	3.0
	Freight Elev.			2	002	Edwds	3.2
	Elect	B		2	174	BRK	3.0
	Comm	B		2	174	BLK	3.0
	Teleph	B		2	174	BLK	3.0
	Elect	A		2	174	BLK	3.0
	Comm	A		2	174	BLK	3.0
	Teleph	A		2	174	BLK	3.0
	Elect	C		2	173	BLK	3.0
	Comm	C		2	173	BLK	3.2
	Teleph	C		2	173	BLK	3.0
	Elect	D		2	173	BLK	3.0
	Comm	D		2	173	BLK	3.2
	Teleph	D		2	173	BLK	3.2
25	Core	Mer	Duct Det	2	233	Hochiki	3.2
	Core	Mer	Duct Det	2	233	Hochiki	3.4
	Return Duct Det			North	232	Hochiki	3.2
25	Return Duct Det			South	232	Hochiki	3.2

13 Strobe Pnl check for trouble/reset AFC 100 panel - adjusted output voltage at panel. -

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED: 8-14-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☒ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): S. O'Keeffe

CUSTOMER SIGNATURE:

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Prev. Maintenance - Sensitivity Test - Service Contract - on Smoke Detectors Area/Elevator's on 25 Floor as listed above. - Also repair in Strobe panel 13 Fl "B" Comm. closet AFC 100 as per F.S.D. - Request [illegible]. - Trouble/Trouble Reseted. - Back to normal. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection services by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the fire protection services during their service of the equipment.

NAME / DATE / TIME

FIRE SERVICE INCORPORATED 103631

SUBSIDIARY OF FI[illegible]OM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
NY. NY.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
Shop	SC# 818				7/3/01

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		7/3/01	am / pm	[signature]

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☑ EMERGENCY CALL
- ☐ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 am	9:00 am	3:30 pm	4:30 pm					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7/03/01

WILL RETURN ON:

CUSTOMER SIGNATURE: R. Mercado

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED — Trouble call —

SERVICE PERFORMED Assisted technician Jimmy T.
For more information see report #
16th floor strobe panel & 46th floor elev. lobby det.
Trouble status repairs
System Operational

WORK REMAINING

FCI 155
REV 8/86

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

97626

SUBSIDIARY OF FI. .OM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C. –
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.W	@ 818				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		7-2-01	AM	J. Torres

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
800 AM	900	3:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7-2-01

WILL RETURN ON:

CUSTOMER SIGNATURE: D. Mercado

SERVICEMAN SIGNATURE: [signature]

PROBLEMS—AS DESCRIBED Repairs as per previous S/contract report. / STABSEP.

SERVICE PERFORMED S/Contract – check troubleshooted 39' floor stage panel defective circuits 'A' – 'B' – wiring check found (1) unit with reverse wiring wall type (wheelock) on 'B' circuit / and loose E.O.L. on 'A' ckt – by restroom's. – Circuits rewired back in operation.

System ock / reseted back in operation

WORK REMAINING

FCI 155
REV 6/86

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is necessary and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ____ Date ____

FIRE SERVICE INCORPORATED

103630

SUBSIDIARY OF F... COM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
NY NY

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
Shop		60#				F/Q/D
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		7/02/	am/pm			[signature]

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☑ EMERGENCY CALL
- ☐ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8⁰⁰ am	9⁰⁰ am	3³⁰ pm	4³⁰ pm					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7/02/01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED — Trouble call —

SERVICE PERFORMED Assisted technician Jimmy.
For more information see report #

System Operational

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the ... service of the equipment.

X

FIRE SEPVICE INCORPORAT=D

97625

SUBSIDIARY OF FIRE_OM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7 WTC
New York, N.Y.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
	SCM 8B				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		06-27-2001	AM.	[illegible]

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 06-27-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeff

SERVICEMAN SIGNATURE: [illegible]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Date

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy [illegible] on the performing of the Service Contract.

WORK REMAINING

FIRE SERVICE INCORPORATED

97623

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, NY.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-26-2001	AM.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐	CALL COMPLETE ☐	SERVICE DATE	CUSTOMER SIGNATURE
		06-26-2001	Sean O'Keeffe
		WILL RETURN ON	**SERVICEMAN SIGNATURE**
			Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy [illegible] in the performing of the Service Contract.

WORK REMAINING

FCI 155

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name ____ Date ____ X

FIRE SERVICE INCORPORATED

97624

SUBSIDIARY OF FIR... M INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, NY

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-25-2001	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F.C.I. NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 A.M.	9:00 A.M.	3:30 P.M.	4:30 P.M.					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 06-25-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean OKeeffe

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Raphael Yadgarov in the installation of the new LD-40 Card Printers on 44th floor Security Office and downloading the system at the F.C.S. and also assisting Jimmy Fiza moving the panels from 44th floor down to 14th floor

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ______ Date ______

FCI 155
REV 8/86

FIRE SERVICE INCORPORATED

97617

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-20/2001	A.M. -			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE 06-20-2001

WILL RETURN ON

CUSTOMER SIGNATURE Sean O'Keeffe

SERVICEMAN SIGNATURE Frank L.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Torres On The Performing of The Service Contract.

WORK REMAINING

FCI 155
REV 6/86

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

X

Name ______ Date ______

FIRE SERVICE INCORPORATED : 23496

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				W/STA	SPK	STRB	H/STA
34	TENANT SPACE			✓	✓	✓	ACTIV.
						BATTERIES	
33	TENANT SPACE			✓	✓	✓ (1) LIGHT OUT	ACTIV.
32	TENANT SPACE.			✓	✓	✓	ACTIV.
31	TENANT SPACE.			✓	✓	✓ (1) LIGHT OUT	ACTIV.
30	TENANT SPACE.			✓	✓	✓	ACTIV.
29	TENANT SPACE.			✓	✓	✓	ACTIV.
28	TENANT SPACE.			✓	✓	✓	ACTIV.
27	TENANT SPACE.			✓	✓	✓	ACTIV.
26	TENANT SPACE.			✓	✓	✓	ACTIV.
34	CONF. "B" STROBE PNL (101) - TBLE. REPAIRED, REPLACED (2) 12 VLT BATTERIES						

INVOICE TO: 7 W.T.C.
SILVERSTEIN PROP.
N.Y.C.
(SLOMAN BARNEY)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 6-20-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keefe.
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by deactivating the system and/or a component in the performance of their assigned work. The undersigned hereby [redacted] responsibility for the notification of the authorities at the time the interruption [redacted] take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT - CHECK/TESTED AS PER BLD ACCESS/TENANT AUDIO/COMMUNICATION/SPEAKERS PAGE - STROBES LIGHTS - W/STATIONS. - ON FLOOR'S (ABOVE LISTED). - SYSTEM ACK/RESET.

(*) NOTE: TO REPAIR (1) STROBE LIGHT ON 33rd FL. BY MAIL RM. - 31st FL (1) STROBE LIGHT TO REPAIR BY FILE ROOM. - TO FOLLOW UP. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

97619

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
TWTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #.	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		Scoo 818				F.S.D.
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-19-2001	A.M.			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 06-19-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: Frank L.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Lozza on the performing of the service contract.

WORK REMAINING

FCI 155

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name ______ Date ______ X

FIRE SERVICE INCORPORATED

23495

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				W/STA	SPKR	STROBE	W/STA ACTIV.
48	PLANT			✓	✓	✓ = REP.	✓
47	TENANT SPACE			✓	✓	✓ - (1) OUT	✓
46	TENANT SPACE.			X	✓	✓ - ½ CKT	✓
45	TENANT SPACE			X	✓	✓	✓
44	TENANT SPACE			✓	✓	✓	✓
43	TENANT SPACE			✓	✓	✓	✓
42	TENANT SPACE			✓	✓	✓	✓
41	TENANT SPACE			✓	✓	✓	✓
40	TENANT SPACE			✓	✓	✓	✓
39	TENANT SPACE			✓	✓ (1) OUT 'B' STAIR	X OUT	✓
38	TENANT SPACE			✓	✓	✓	✓
37	TENANT SPACE			✓	✓	✓	✓
36	TENANT SPACE			✓	✓	✓	✓
35	TENANT SPACE			✓	✓	✓	✓

INVOICE TO:
7 W.T.C.
SILVERSTEIN PROP.
N.Y.C.
(SOLOMON SMITH BARNEY TENANT)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 6-19-01
CONTRACT #: SC 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #

CALL AUTHORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☒ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O-Keeffe.

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of the assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT - AS PER BLD ACCESS / TENANT PROCEEDED TO CHECK / TESTING OF: WARDEN'S STATIONS - SPEAKERS PAGE AUDIO / COMMUNICATIONS AND STROBE LIGHT ACTIVATION ON FLOOR'S - AS (LISTED ABOVE) SYSTEM ACKNOWLEDGED - ACTIVATION / RESET'S. -
NOTE: TO REPAIR TO FOLLOW UP ON FLOOR'S 48' STROBE PNL UPDATE - 47 FL (1) SPK OUT / STROBE 46' FL. STROBES LIGHT CKT (A) OUT. - 39' FL SPK OUT 'B' STAIR AREA / STROBE ACTIV. - OUT. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 97615

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
		S000818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-13-2001	A.M.			Frank

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 06-13-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank [signature]

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Lane on the performing of the Service Contract

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Date

FIRE SERVICE INCORPORATED 23494

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			CABLE	XMDR	S/D	CLEAN TEST
3rd	WEST HER			3	006	PEC3T	✓
	WEST HER			3	006	PEC3T	✓
	SECURITY CLOSET			3	048	PEC3	✓
	DUCT DET KITCHEN			3	042	EDWDS	✓
	(SUPPLY CEILING PLENUM)						
3rd	W. HER D/D FAN			3	040	EDWDS	✓
	W. HER D/D FAN			3	040	EDWDS	✓
	W. HER D/D FAN			3	040	EDWDS	✓
	W. HER D/D FAN			3	041	EDWDS	(*)
(*)	(INSTALLED S/D) – UNIT Replaced old N/G						
3rd	CONF. AREA			1	077	DI-3	✓
	RECEPT. AREA			1	077	DI-3	✓
	ELEV LBBY			3	029	PEC3	✓
2	FAN RM D/D			1	014	EDWDS	✓
2	ELEV. LBBY			3	028	PEC3	✓
2	ELEV. LBBY			3	005	PEC3T	✓
1st	PLANT HER D/D			3	039	EDWDS	✓
1st	PLANT HER D/D			3	037	EDWDS	✓
1st	PLANT HER AREA			1	012	PEC3T	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. (Solomon Smith Barney) N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	7 S.D
	DATE SCHEDULED: 6-13-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LW 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Miguel Rivera
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by deactivating the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their servicing of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: As per contract. Test maintenance on smoke detection class E system in areas floors 3rd 2nd 1st FLS (listed above). – System ack / reset back to open.
(*) Note: W. HER. D/D (041) unit replaced / wired – (old defective N/G)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

Unit supplied by Bldg.

FIRE SERVICE INCORPORATED

23493

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S . CLOSET'S		CABLE	XTNDR	S/D	TST CLEAN
5	PASS ELEV.		1	004	BLK	✓
	FREIGHT		1	004	BLK	✓
	ELECT A		1	169	BLK	✓
	TELEPH A		1	169	BLK	✓
	ELECT B		1	169	BLK	✓
	COMM B		1	169	BLK	✓
	ELECT C		1	169	BLK	✓
	ELECT F		1	169	BLK	✓
	ROTO	CLONE AREA	3	013	PEC3T	✓
	ROTO	CLONE AREA	3	013	PEC3T	✓
4	ELECT B		1	167	BLK	✓
	TELEPH B		1	167	BLK	✓
	COMM B		1	167	BLK	✓
	TELEPH A		1	167	BLK	✓
	ELECT A		1	167	BLK	✓
	ELECT G		3	050	PEL3	✓
	MAIN	PASS ELEV.	1	003	BLK	✓
	FREIGHT ELEV.		1	003	BLK	✓
	CHEF'S OFF. D/D		3	043	EDWDS	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C. (Solomon Smith B.)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Dorian	F.S.D
	DATE SCHEDULED 6-12-01
CONTRACT # S/C 00 818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #

CALL AUTHORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	ALARM'S LOG'S BOOKS	45 EACH
4	12 VLTS BATTERIES	69.95 EACH
	(STROBE'S PANEL'S)	

CUSTOMER NAME (PRINT) [signature]
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

DATE
NAME
TIME

SERVICE PERFORMED & REMAINING S/CONTRACT. S/DETECTORS ON FLOOR'S 5 + 4TH. - (SOLOMON BROTHERS / SMITH BARNEY) AREAS - CLOSET'S AS LISTED. - UNITS TESTED / CLEANED. - SYSTEM ACK / RESETED. -

(*) ALSO DELIVERED (2) ALARM'S LOG'S BOOK'S AS REQUESTED F.S.D. / BLDG. - A (4) BATTERIES TO BE REPLACED AT STROBE PNL'S (BACK UP PWR). -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

97668

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
	S000818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		06-12/2001	A.M.	Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:00 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 06-12-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Firing Line on the Performing of the Service Contract Also Testing Batteries and Alarm Books for 7WTC

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ________ Date ________

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

23492

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREA'S		CABLE	XMTR	S/D	TST CLEANED
26	ELECT A		2	176	BLK	✓
	COMM A		2	176	BLK	✓
	TELEPH A		2	176	BLK	✓
	COMM B		2	176	BLK	✓
	ELECT B		2	176	BLK	✓
	TELEPH B		2	176	BLK	✓
	PASS ELEV.	(003)	2	003	BLK	✓
	COMM C		2	175	BLK	✓
	ELECT C		2	175	BLK	✓
	TELEPH C		2	175	BLK	✓
	ELECT D		2	175	BLK	✓
	COMM D		2	175	BLK	✓
	TELEPH D		2	175	BLK	✓
	FREIGHT ELEV	(003)	2	003	BLK	✓
	CORE HER D/D.		2	235	SIF24	✓
	CORE HER D/D.		2	235	SIF24	✓
	RETURN D/D NORTH		2	234	SIF24	✓
	RETURN D/D SOUTH		2	234	SIF24	✓

26 RET. D/D LADIES RM. NO ACCESS. — BLD TO PROVIDE FUTURE. — NEXT —

44 PREACTION PNL/TROUBLE - TERMINATION AT TTB (45 FL) LIFTED - WIRES due to MULTIPLE TROUBLE(S) - SUB CONTRACTOR TO CHECK SUB SYSTEM PREACTION PNL. - REPAIRED — - TO RESTORE WIRED SUPV. - WHEN COMPLETE -

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 6-6-01
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 (AM)	4:30 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): [signature]
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Service Contract - Prev Maintenance & Repairs on listed above. — Smoke detectors alarm's serviced on 26 Fl. Area closets elev lobby. Main F.C. station alarm's acknowledged - reseted properly. — System back in operation. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. Representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

97667

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		SC008I8				F.S.I.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-04-2001	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q. C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 06-06-2001

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jerry [illegible] for the performing of the Service Contract

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SE⌐VICE INCORPORA⌐ED

97666

SUBSIDIARY OF FI... COM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		SC00518				F.S.I.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		06-04-2001	A.M.			Frank P.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 A.M.	9:00 AM	3:30 PM	4:30 PM					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 06-04-2001

CUSTOMER SIGNATURE: James Cappiello

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank P.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Lopez on the [illegible] of the Service Contract.

WORK REMAINING

FCI 155
REV 8/88

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name X

Date

FIRE SERVICE INCORPORATED

84035

SUBSIDIARY OF F M INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC.
Emergency Service.

SUNDAY

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE	FJ #	PO #	SEE AT JOB SITE
Service.	Sc 818				FSD- Angel

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		22 April 2001		Newell

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

CONTRACT TROUBLE CALL

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☐ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
930	1045	1100	1200	4.00				

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 22 April 2001

WILL RETURN ON:

CUSTOMER SIGNATURE: x [signature] Mercado

SERVICEMAN SIGNATURE: [signature] Newell

PROBLEM—AS DESCRIBED

Emergency Service.

SERVICE PERFORMED 930 recvd beep. Contact service and customer. Customer reports FCS lite up 8500 Interface board trouble. Need service ASAP. 10:45 arrived at jobsite. Met with Security / FSD Checked F.C.S. 76 Trouble (6) Supv (0) ASBL. Checked trouble list. 8500 IF # 240 in trouble and sub nodes. Reset 8500 IF - Trouble reset, However F.C.S. display locked up in trouble restart system. Performance checked F.C.S. -OK (65) Trouble (6) Supv. Fire Alarm system back on line. Call completed.

WORK REMAINING

FCI 155

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

97664

SUBSIDIARY OF FI... COM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
	Sc00818				FSD

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		05-30-01	A.M.	Frank K.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F.C.I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE CONTRACT		

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 05-30-01

WILL RETURN ON:

CUSTOMER SIGNATURE: [illegible]

SERVICEMAN SIGNATURE: Frank K.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Inspecting Fire [illegible]
Per the Agreement Of the
Service Contract.

WORK REMAINING

FCI 155
REV 6/86

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

23485

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR			CABLE	XTNDR	TEST CLEAN	S/D
29	PASS/FREIGHT	(2)	2	006	✓	BLK
	ELECT A-B	(2)	2	182	✓	BLK
	TELEPH A-B	(2)	2	182	✓	BLK
	COMM A-B	(2)	2	182	✓	BLK
	ELECT D.W		2	181	✓	BLK
	ELECT G/SEC	(2)	3	007	✓	PEC3
	ELECT C-D	(2)	2	181	✓	BLK
	TELEPH C-D	(2)	2	181	✓	BLK
	COMM C		2	181	✓	BLK
	ELECT F					
	SHUTTLE ELEV.		3	030	✓	PEC3
	(*) CORE MEC AREA	(3)	2	240	✓	PEL3T
	(*) CORE MEC D/D.	(2)	3	000	✓ SIF	[illegible]
	W. MEC AREA	(2)	3	032	✓	EDWS
28	PASS/FREIGHT	(2)	2	005	✓	EDWS
	ELECT A-B	(2)	2	180	✓	BLK
	COMM A-B	(2)	2	180	✓	BLK
	TELEPH A-B	(2)	2	180	✓	BLK
	ELECT C-D	(2)	2	179	✓	BLK
	COMM C-D	(2)	2	179	✓	BLK
	TELEPH C	(1)	2	179	✓	BLK.
	ELECT D.W.	(1)	2	179	✓	PEL3
	ELECT F					
	ELECT G		2	180	✓	PEL3
	(*) SECURITY CLOSET NO S/D. — NO WIRING EXISTING					
	SHUTTLE ELEV.		2	005	✓	PEC3
	CORE MEC D/D.		2	239	✓	SIF 24
	CORE MEC D/D		2	239	✓	SIF 24
	W. MEC AREA	(3)	3	057	✓	PEL3T
	W. MEC D/DET.		3	047	✓	DT-3

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.
(Solomon Floor)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 5-22-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT. CHECK/TEST/CLEAN SMOKE DETECTORS ON FLOOR 29/28 FLOORS AREAS ALL AS LISTED. — NOTE 29 FL. CORE MEC DUCT DET. (1) UNIT & (1) AREA CEILING NO SAFE ACCESS TO MAINTENANCE/SERVICE DUE TO HIGH VOLTAGE RISER POWER EXPOSED BY UNITS. 28 FL. (FOUND) SECURITY CLOSET WITH NO S/D. PROTECTION AS PREVIOUS REPORTED). — SYSTEM ACK/RESET BACK TO OPERATING/NORMAL. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

84206

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
		SC00818				F.S.D
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		05-23-2001	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F.C.I. NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQ'D
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQ'D
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 05-23-2001

CUSTOMER SIGNATURE: Sean O'Kee

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting [illegible] Laws on the performing of the Service Contract

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

X

Date

FIRE SERVICE INCORPORATED

84207

SUBSIDIARY OF F... COM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		05-22-2001	A.M. -			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 PM.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 05-22-2001

CUSTOMER SIGNATURE: Sean O'Keefe

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Completing ... per the ... of the Service Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. [illegible] that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

X

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

97660

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		05-16-2001	AM.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 05-16-2001
CUSTOMER SIGNATURE: [signature]
WILL RETURN ON:
SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Lesser Tech.
In the performance of the
Service Contract of Maintenance
of the Smoke detectors and Duct
detectors in the premises

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name
Date

FCI 155

FIRE SERVICE INCORPORATED

23484

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA		CABLE	XTNDR	S/D	TST CLEAN
31	PASS/FREIGHT	(2)	2	008	BLK	D13✓
	ELECT A-B	(2)	2	187	BLK	✓
	TELEPH A-B	(2)	2	187	BLK	✓
	COMM A-B	(2)	2	187	BLK	✓
	ELECT C-D	(2)	2	186	BLK	✓
	CONT/COMM D		2	186	BLK	
	CONT/D.W.		2	186	BLK	
	ELECT D.W.		2	186		
	ELECT 6/SEC.	(2)	3	009	PEC 3	✓
	ELECT F		3	016	PEC 3	✓
	SHUTTLE ELEV		3	025	PEC 3	✓
	CORE HEA. AREA	(3)	2	244	PECST	✓
	CORE HEA D/D	(2)	2	245	SIF 24	✓
	W. HEA AREA	(2)	3	002	PEC 37	✓
	W. HEA D/D	(2)	3	034	EDWDS	✓
	N. SUPPLY CLOSET	(2)	2	186	BLK	✓
30	PASS/FREIGHT	(2)	2	007	BLK	✓
	ELECT A-B	(2)	2	184	BLK	✓
	COMM A-B	(2)	2	184	BLK	✓
	TELEPH A-B	(2)	2	184	BLK	✓
	ELECT C-D	(2)	2	183	BLK	✓
	TELEPH D/CONT		2	183	BLK	✓
	TELEPH C		2	183	BLK	✓
	COMM C		2	183	BLK	✓
	ELECT D.W.		2	183	BLK.	
	ELECT F		3	015	PEC 3	✓
	ELECT 6 SEC	(2)	3	008	PEC 3	✓
	SHUTTLE ELEV		3	024	PEC 3	✓
	CORE HEA AREA	(3)	2	242	PEC 37	✓
(A)	CORE HEA D/D	(2)	2	243	SIF 24	✓
	W. HEA AREA	(2)	3	001	PEC 37	✓
	W. HEA D/D	(2)	3	033	EDWDS	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C.
N.Y.C.
J Garrigan/F.S.D.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. Torres / F. Rosillo	F.S.D.
	DATE SCHEDULED: 5-16-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) Silverstein
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE AS PER CONTRACT. – SMOKE DETECTORS (ABOVE LISTED) ON FLOOR'S 31 & 30 WERE TESTED & CLEANED. – CLASS E FIRE EQUIP – SYSTEM – ALARM'S / RESET'S ACKNOWLEDGED – OUTPUT'S FUNCTIONS AS FIRE SIGN / FLOW PAGE FLOOR / ABOVE / SIGNAL ON / CENTRAL OFFICE – CHECK'S O.K TO BE CONTINUED –

30 FL (A) (1) DUCT DET. CORE HEA (2/243) N/ACCESS – High Voltage "Buss Bars" ON WAY / OBSTACLE

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

97659

SUBSIDIARY OF FI...COM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		SC00 818				F.S.I
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		05-15-2001				Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 05-15-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: James Carrigan

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Rivera Jack. On the performing of the Service Contract of Maintenance of the smoke detector and duct detector on the premises.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

X

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

23483

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA		CABLE	ADDR	S/D	CLEAN TEST
32	PASS ELEV		2	009	BRK	✓
	ELECT A.		2	190	BRK	✓
	COMM A		2	190	BRK	✓
	TELEPH A		2	190	BRK	✓
	ELECT B		2	190	BRK	✓
	COMM B		2	190	BRK	✓
	TELEPH B		2	190	BRK	✓
	FREIGHT ELEV		2	009	BRK	✓
	ELECT 'C'		2	189	BRK	✓
	TELEPH C RET		2	189	BRK	✓
	COMM C/SUPPLY		2	189	BRK	✓
	ELECT 'D'		2	189	BRK.	✓
	TELEPH D SUPPLY		2	189	BRK	✓
	ELECT D.W		2	189	BRK	✓
	ELECT F		3	017	PEC3T	✓
	ELECT G		3	010	PEC3T	✓
	SECURITY CLOSET		3	010	PEC3T	✓
	SHUTTLE ELEV.		3	026	PEC3	✓
	CORE HER AREA		2	248	PEC3T	✓
	CORE HER AREA		2	248	PEC3T	✓
	CORE HER AREA		2	248	PEC3T	✓
	CORE HER D/D		2	247	SIF24	✓
*	CORE HER D/D		2	247	SIF24	—
	WEST HER AREA		2	003	PEC3T	✓
	WEST HER AREA		2	003	PEC3T	✓
	WEST HER D/D		3	035	EDWPS	✓
	WEST HER D/D		3	035	EDWPS	✓

42 FREIGHT ELEV. S/D — BRK UNIT & BASE REPAIRED — BACK IN OPERATION

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C.

MR. CHERIGAN

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J Torres / F Llano	F 59
	DATE SCHEDULED 5-15-01
CONTRACT # 51C00818	TYPE OF SYSTEM LSN2000
FEE SERVICE #	PO #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) SILVERSTEIN

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service the representative that it may be necessary to interrupt the fire protection services by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING PREVENTIVE MAINTENANCE AS PER CONTRACT / CHECK / TEST - CLEANED SMOKE DETECTOR UNITS / CLASS E SYSTEM ON 32nd FL / ALL AREAS AS LISTED —
(*) NOTE D/DETECTOR CORE HER UNIT N/G / TO REPLACE OR REPAIRED —
ALSO AS PER CONTRACT / REPAIRED FREIGHT UNIT ON 42nd FL. — BASE DEFECTIVE / CONTACTS WIRING LOOSE / REPAIRED O.K. — BACK IN OPERATION. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

97658

SUBSIDIARY OF F...COM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		S000818				F.S.D
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		05-14-2001	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 AM.	9:00 AM	3:30 PM.	4:30 PM.					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 05-14-2001

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Leese on the performing of the Service Contract

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

X

FIRE SERVICE INCORPORATED

23467

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS — DEVICES

FLOOR	
47	STROBE PNL AFC 100 CHECK - Replaced Key Lock (300 TYPE)
46	" "
45	STROBE PNL AFC 100 CHECK Replace (1) Key Lock (300 TYPE)
48	" "
13	Repair on STROBE PNL AFC 101 PANEL. - Also check STROBE PNL #2 AFC 100 by 13 ROOM. -
24	Fl. TAMPER S/W - Repair/Adj. Alarm status. -
30	Fl. TAMPER S/W - Adj/Repair on Alarm status. -

TROUBLE CALL

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7WTC
N.Y.C.
Mr. J. Carrigan

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 5-14-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	3:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME — DATE — TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT. Repairs on above floor's as per F.S.D. - STATUS REPORT. - on above LISTED. -
(→) Also ASSISTED SOFTWARE Eng. FIRECOM on 6 Fl. ARCADE SYSTEM - FAN UNIT - STATUS -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

97657

SUBSIDIARY OF F... ...COM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
TWTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		05-09-2001	A.M.			Frank R.?

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 05-09-2001

CUSTOMER SIGNATURE: James Carragher?

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank R.?

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Rosse? on the
performing of the Service Contract
for Maintenance of the area
Smoke and Duct Detectors

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

23482

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	AREA'S			CABLE	XTNDR	S/D	TST CLEAN
34	PASS/FREIGHT			2	011	BLK	✓
	ELECT	A-B	(2)	2	194	BLK	✓
	COMM	A-B	(2)	2	194	BLK	✓
	TELEPH	A-B	(2)	2	194	BLK	✓
	ELECT	C-D	(2)	2	193	BLK	✓
	ELECT	D.W.		2	193	BLK	✓
	ELECT	F		4	048	PEC3	✓
	ELECT F/A.V. ROOM			4	048	PEC3	✓
	ELECT	G/SEC.	(2)	4	072	PEC3T	✓
	TELEPH	C-D	(2)	2	193	BLK	✓
	MEDICAL DPT	AREA		2	193	BLK	✓
	SHUTTLE ELEV.			4	000	PEC3	✓
	CORE MER AREA	(3)		2	252	PEC3T	✓
	CORE MER D/DET.	(2)		2	251	EDWDS	✓
	W. MER	AREA.		4	024	PEC3	✓
	W. MER	D/DET.		4	096	EDWDS	✓
33	ELECT	A-B	(2)	2	191	BLK	✓
	COMM	A-B	(2)	2	191	BLK	✓
	TELEPH	A-B	(2)	2	191	BLK	✓
	ELECT/COMM 'C'		(2)	2	192	BLK	✓
	ELECT	D.W		2	192	BLK	✓
	ELECT	F		3	018	PEC3	✓
	ELECT	G/SECURITY	(2)	3	011	PEC3	✓
	TELEPH	/SUPPLY 'C'		2	192	BLK	✓
	TELEPH	/CLST D		2	192	BLK	✓
	FREIGHT/PASS		(2)	2	010	BLK	✓
	SHUTTLE ELEV			3	027	PEC3	✓
	CORE MER	AREA (3)		2	250	PEC3T	✓
	CORE MER	D/D (2)		2	249	SIF24	✓
	W MER	AREA	(2)	3	004	PEC3T	✓
	W. MER	D/D	(2)	3	036	EDWDS	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. (SOLOMON BROTHERS) N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / J. ROSARIO	F.S.D.
	DATE SCHEDULED: 5-9-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: USB2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTONE

CUSTOMER SIGNATURE: [illegible]

SERVICEMAN SIGNATURE: [illegible]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT / PREV MAINTENANCE SMOKE DETECTION ON FLOORS 34/33rd AS LISTED ABOVE.— SYSTEM ACK/RESETED BACK TO OPERATION

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 97656

SUBSIDIARY OF F... COM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7WTC New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D
PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		05-08-2001	A.M.			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 05-08-2001

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Lozze on the inspection of the Service Contract of Maintenance of the Area Smoke Detectors and Duct Detectors.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

23481

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	Area's			Cable	XTNDR	S/D	TST/Clean
35	Elect	A		2	196	BRK	✓
	Comm	A		2	196	BRK	✓
	Telco	A		2	196	BRK	✓
	Elect	B		2	196	BRK	✓
	Comm	B		2	196	BRK	✓
	Telco	B		2	196	BRK	✓
	PASS/FREIGHT (2)			2	012	BRK	✓
	Elect	G		4	073	PEC 3	✓
	Security closet			4	073	PEC 3	✓
	Elect	C		4	049	PEC 3	✓
	Elect	D		4	049	PEC 3	✓
	Elect	F		4	049	PEC 3	✓
	Elect	F1		4	049	PEC 3	✓
	Shuttle Elev			4	001	PEC 3	✓
	W. HER	Area		4	025	PEC 3T	✓
	W. HER	D/D		4	097	[illegible]	✓
42	TTB	Unit	check's Terminal's				
39	TTB's	Unit	"		"		

INVOICE TO: W.T.C.
(Solomon Smith Barney)
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres F. Rosario	FS-7
	DATE SCHEDULED: 5-8-01
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): Silverstein

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Service Contract / PREV Maintenance on Smoke Detection Class E Fire Alarm Floor 35th (As Listed) All areas. —
Also [illegible] Tech on 39/42 Fl. for checks on Inputs Terminal's for Stop/Status Elev Cars Displays Floor's 40/41/42/43. — System Left Good to Operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 84489

SUBSIDIARY OF F... , INC

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7 WTC NEW YORK
New . York

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
SHOP	U.P.S 818				F.S.O

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		5/4/01	AM	C. FORERO

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
800 AM	900 AM	200 PM						

☐ MAT REQD ☐ PARTIAL ☐ OTHER ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 5-4-01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: C. FORERO

PROBLEM—AS DESCRIBED PREVENTIVE MAINTENANCE / U.P.S SERVICE CONTRACT

SERVICE PERFORMED Arrived At Building. Checked U.P.S System, and Battery Racks (30 Batteries) Took Readings

TOTAL - BATTERY VOLTAGE = 139.8 VOLTS - A/DC
BATTERY AMP = .3 AMPS
L-1 = 11.3
L-2 = 10.9
INPUT - VOLTAGE = 208. A/C
246. A/C

WORK REMAINING Cleaned AND Checked U.P.S And Battery Racks, Systems [crossed out] (ON)

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FIRE SF?'ICE INCORPOR/'TFD 97655

SUBSIDIARY OF F...EC. ..INC
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
	SC00518				F.S.D.

PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		5/2/2001	A.M.	Frank [illegible]

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 5/2/2001

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank [illegible]

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Tech. Jimmy [illegible]
In the Performing of the
Service / Contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name _______________ Date _______________

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

23479

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		ZONE	XTNM	S/D	TST CLEAN
37	PASS/FREIGHT (2)		2	014	BLK	✓
	SHUTTLE PASS ELEV ✓		4	003	PEC 3	✓
	ELECT A-B	(3)	2	200	BRK	✓
	COMM. A-B	(3)	2	200	BRK	✓
	TELEPH A-B	(3)	2	200	BRK	✓
	ELECT C-D	(2)	2	199	BRK	✓
	ELECT D.W		2	199	BRK	✓
	ELECT "F"	EAST	4	051	PEC 3	✓
	ELECT G/SEE	(2)	4	075	PEC 3	✓
	TELEPH C-D	(2)	2	199	BLK	✓
	COMM C		2	199	BRK	✓
	CORE HEL AREA (3)		2/002	258	PEC 3T	✓
	CORE HER D/D (2)		2/001	257	HOCHIKI	✓
	W. HER AREA	(2)	4	027	PEC 3T	✓
	W HER D/D	(2)	4	099	ENDLI	✓
36	ELECT A-B	(2)	2	198	BLK	✓
	COMM A-B	(2)	2	198	BLK	✓
	TELEPH A-B	(2)	2	198	BLK	✓
	ELECT "F" EAST		4	050	PEC 3	✓
	ELECT D.W		2	197	BLK	✓
	ELECT G/SEE	(2)	4	074	PEC 3	✓
	ELECT C-D	(2)	2	197	BLK	✓
	TELEPH/CONT C-D (2)		2	197	BLK	✓
	COMM/STORAGE R		2	197	BLK	✓
	PASS/FREIGHT ELEV. (2)		2	013	BRK	✓
	SHUTTLE ELEV. PASS		4	002	PEC 3	✓
WEST	~~CORE~~ HER D/D		4	098	ENDLI	✓
WEST	~~CORE~~ HEL D/D		4	098	ENDLI	✓
WEST	~~CORE~~ HER AREA (3)		4	026	PEC 3T	✓
	CORE HEL D/D		2	255	SIF 24	✓
	CORE HER D/D		2	255	SIF 24	✓
	CORE HER AREA (3)		2	000	PEC 3T	✓

INVOICE TO: 7 W.T.C. / SOLOMON BROTHERS [illegible] / N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres	F.S.D.
	DATE SCHEDULED: 5-2-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: CSN 2000
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☐ MAINTENANCE (marked) ☐ TEST (marked)
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	4:20 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: S/CONTRACT - PREV MAINTENANCE ON FLOORS 37/36
(SOLOMON SMITH BARNEY) ALL AREAS / CLEAN / [illegible] - SMOKE DETECTOR
UNITS ARE LISTED ABOVE - SYSTEM ALL RESET - ANNUNCIATION AT F.C.S. -
BACK IN OPERATION -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME
DATE
TIME

FIRE SERVICE INCORPORATED 97654

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED: 7WTC NYC

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
		SC00818				7.SJ
PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		5/1/2001	A.M.			Frank R

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection service during their service of the equipment.

Date

Name

X

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 5/1/2001

WILL RETURN ON

CUSTOMER SIGNATURE: James Carragher

SERVICEMAN SIGNATURE: Frank R.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Keck. Jimmy Lure
See the performing of the service contract.

WORK REMAINING

FCI 156
REV 6/86

FIRE SERVICE INCORPORATED

23478

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREAS		CABLE	XTNDR	S/D	TST CLEAN
40	ELECT	A	2	207	BLK	✓
	COMM	A	2	207	BLK	✓
	TELEPH	A	2	207	BLK	✓
	ELECT	B	2	207	BLK	✓
	COMM	B	2	207	BLK	✓
	TELEPH	B	2	207	BLK	✓
	PASS / FREIGHT ELEV (2)		21	017	BLK	✓
	ELECT	C	2	208	BLK	✓
	CORE/COMM C		2	208	Apllo	✓
	TELE/Storage C		2	208	Apllo	✓
	ELECT	D	2	208	BLK	✓
	TELE/Storage D		2	208	Apllo	✓
	COMM/Storage D		2	208	Apollo	✓
	CORE	MED D/D	2	015	Apllo	✓
	CORE	MER D/D	2	015	Apllo	✓
	CORE	AREA CEILING	2	208	Apllo	✓
	CORE	AREA CEILING	2	208	Apllo	✓
(*)	ELECT 'F' MISSING / NO S/D DETECTOR					—
	SECURITY CLOSET		4	078	PEC 3	✓
	ELECT 'G'		4	078	PEC3	✓
	FILE RM		2	208	Apllo	✓
	FILE RM		2	208	Apllo	✓
Lobby	F.C. STATION REPAIR DCM 40 / DISPLAY #16 PURGE / PRESS FLOORS					
18	TTB REPAIR ON 795 MOTHER BOARD & REPLACE (2) 792 P.C. BOARDS - DEFECTIVE FOR REPAIR ON PURGE / PRESSURIZATION ON 18TH FL. —					

INVOICE TO: 7 W.T.C (Solomon Smith Barney) N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres	F.S.D
	DATE SCHEDULED 5-1-01
CONTRACT # S/C00818	TYPE OF SYSTEM LSN2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	792 P.C. BOARDS.	
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their [redacted].
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING S/CONTRACT - PREVENTIVE MAINTENANCE SMOKE DETECTION ON 40 FL (Solomon) ALL ELECT CLOSETS / ELEVATION LOBBIES / STORAGE & MACHINE RM'S / CORE MED'S AS LISTED. —
(*) NOTE: "F" ELECT CLOSET S/D NOT EXISTING - MISSING. —
(*) ALSO PERFORMED REPAIR / REPLACING BOARDS ON 18 FL TTB / PURGE / PRESS. FAN / OPER.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

23480

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	AREA'S			CABLE	XTNOL	S/D	TST CLEAN
41	ELECT "A"			2	209	BLK	✓
	COMM "A"			2	209	BLK	✓
	TELEM "A"			2	209	BLK	✓
	COMM "B"			2	209	BLK	✓
	ELECT "B"			2	209	BLK	✓
	TELEM "B"			2	209	BLK	✓
	PASS ELEV.			2	018	BLK	✓
	FREIGHT ELEV.			2	018	BLK	✓
	COMM/COAT "C"			2	195	APLLO	✓
	ELECT "C"			2	195	APLLO	✓
	TELEM "C"			2	195	APLLO	✓
	CORE MER	D/D		2	016	APLLO	✓
	CORE MER	D/D		2	016	APLLO	✓
	CORE AREA	MER.		2	019	APLLO	✓
	CORE AREA	MER.		2	019	APLLO	✓
	ELECT "G"			4	079	PEC3T	✓
	SECURITY CLOSET			4	079	PEC3T	✓
	SHUTTLE ELEV.			4	007	PEC3	✓
46	STROBE PANEL AFC 100 / "A" CKT OPR - SHORTED						
	(2) BATTERIES 12 VOLT REPLACED.						
39	STROBE PNL AFC 100 / (2) BATTERIES 12 VOLT						
	REPLACED - PNL UPDATE MODIF -						
18	PURGE / PRESS. FAN / ACTIVATION						
	TROUBLESHOOTING / REPAIR -						

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
Solomon Smith Barney
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.I.
	DATE SCHEDULED: 4-30-01
CONTRACT #: 5/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
900 AM	900 AM	5:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	792 P.C. BOARDS	385
4		

CUSTOMER NAME (PRINT): SILVERSTEIN'S
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representatives that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Prev. Maintenance as per contract on 41st Floor smoke detectors areas / elev. lobbies as listed above. - and repairs on defective or malfunction on strobe panels 46th Fl & 39th Fl - Replaced defective batteries low output voltage - (4) units 12 volt. and troubleshooting / status problem with 18th Fl purge / pressurization fan unit - (2) 792 P.C. replaced - need to repair 795 board panel T/B / data monitor sw. - system ok / reset back to operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

97653

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO	SERVICED
	7WTC NYC

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
		SC00818				F.S.D
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		4/30/2001	A.M.			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 AM	9:00 AM.	4:30 P.M.						

- ☐ MAT REQD
- ☐ OTHER
- ☐ PARTIAL
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 4/30/2001

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank L.

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Tech. Jimmy [illegible] for the performing of the service contract.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Date

Name

FCI 155
REV 8/85

FIRE SERVICE INCORPORATED

23473

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / DEVICES

FLOOR	AREA			CABLE	XTNDR	S/D	TST CLEAN
37	E.H.R AREA (x2)			1	201	BLK	✓
	CAR'S 16-20						
31	E.H.R. AREA			1	188	BLK	✓
	CAR'S 13-14-15 (x2)						
31	E.H.R	DUCT DET		2	246	SIF24	✓
		E.C.R					
31	E.H.R	AREA		1	188	BLK	✓
	E.H.R	DUCT DET. ECR		2	246	SIF24	✓
	CAR'S 11+12						
30	E.H.R	AREA (x2)		1	185	BLK	✓
	CAR'S 13-14-15						
30	EHR	AREA		1	185	BLK	✓
	CARS 11+12						
16	E.H.R	AREA	EAST	1	195	BLK	✓
16	E.H.R	AREA	EAST	1	195	BLK	✓
16	E.H.R	D/D	EAST	1	254	EDW'S	✓
16	EHR	AREA	WEST	1	195	BLK	✓
16	EHR	DUCT	DET. WEST	1	254	EDW'S	✓
15	E.H.R	AREA	EAST	1	192	BLK	✓
15	E.H.R	AREA	EAST	1	192	BLK	✓
15	E.H.R	AREA	WEST	1	192	BLK	✓
3RD	SHUTTLE	ELEV	SHAFT	3	049	PER3	✓
2ND	EHR	H.E.	3+2	3	005	PER3T	✓
23	EHR	AREA (x2)		1	170	BLK	✓
	EHR	D/D		2	229	SIF24	✓

INVOICE TO: W.T.C / SILVERSTEIN PROP. / N.Y.C.

SERVICEMAN ASSIGNED: J. Torres / F. Poffrew [illegible]	SEE AT JOB SITE: F.S.I.
	DATE SCHEDULED: 4-28-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: CSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	7:00 AM	4:00 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature] (Al [illegible])

SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING: S/Contract - Phase [illegible] Smoke Detection: SHAFT'S - As Listed - Assisted By OTIS Mech Elev Hoist Rm's/SHAFT'S - Also Repair (1) D/D EHR - 31st Fl Rewired Also at Base Unit - Back to Operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

94445

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
		S000818				F.S.I.
PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		04-28-2001	AM.			Frank L.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	7:00 AM.	3:30 P.M.						

- ☐ MAT RECD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR RECD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 04-28-2001

CUSTOMER SIGNATURE: (signature) (Ahmed)

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank L. (signature)

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Heck during the performing of the Service Contract of Testing and Cleaning of the Smoke and Duct Detectors inside the EMR and Staff elevators. See Service Report #23473

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

X.

Name ______ Date ______

FIRE SERVICE INCORPORATED

97652

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C. –
Silverstein Prop. –
N-Y-C

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
ET.	S/C 00 818				7.1.?

PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		4-25-01	Am	J. Torres

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
2			Batteries 12 VLT (Strobe Pnl)	6995		

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800 Am	4:30 Pm						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 4-25-01

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED Service Contract / Repair Strobe Panel's – Various Floor's Also to check Purge Fan 18th Fl. N/G. – As per F.S.D. –

SERVICE PERFORMED Performed Repair on Strobes Panel's – Trouble's / Troubleshooting Replaced (6) Set's of 12 VLTS Batteries on Floors 7th - 8th - 39th Floors and Traced / Troubleshooting panel on 46th Fl. Strobe Pnl. – Circuit #2 Lifted due to High Resistance - / Trouble Condition. – Circuit NAC activating / Trace unit Defective Panel Back on Line. – Also check / Troubleshooting 18th Fl. Purge Unit not "Lacking" on Alarm Condition at F.C. Station Display / as well Pressurizing 17 & 19th Fl. – Further check's leads to also Malfunction on Purging 17 & 19th Floor's. – Check TTB's on 18th Fl. Inputs O.K. / PCS 792 replaced / Problem persisting / F.C. Station

WORK REMAINING Power / Download / ~~[illegible]~~ – Purging 18 still Defective. – Program to be check / 8500 I.F Unit at Console. –

(B) Also Arcade Unit (Fan's) on 6th Fl Not Displaying Current Event's Account Billing. – Showing Acc Billing – | Run Time Error 3021
Notified Harty on Eng / Dale's Dept | No Current Record

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service, Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Date

Name

FIRE SERVICE INCORPORATED

94436

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO	SERVICED
	7WTC New York, N.Y.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
	SC00818				7-S D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		4/25/01	A.M.	Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 A.M.	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 4/25/01

CUSTOMER SIGNATURE:

WILL RETURN ON:

SERVICEMAN SIGNATURE:

PROBLEM—AS DESCRIBED Service Contract

SERVICE PERFORMED Assisting Tech. Jimmy Torres on the replacing of Strobe Panels on 7th floor, 8th floor, 39th and 46th floors. Also on the replacing of Batteries on 7th, 8th and 39th floors. Also assisting on the checking of Purge and Pressurization of the 18th floor. See Service Report # 97652.

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

23476

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREAS		CABLE	XTNDR	S/D	TST CLEAN
49	PASS/FREIGHT	(2)	2	019	BRK	✓
	ELECT A-B	(2)	2	211	BRK	✓
	COMM A-B	(2)	2	211	BRK	✓
	TELEPH A-B	(2)	2	211	BRK	✓
	SUPPY 'C'		2	210	Apllo	✓
	TOWER 'C'		2	210	Apllo	✓
	ELECT C		2	210	Apllo	✓
	COAT D		2	210	Apllo	✓
42	CORE HEY AREA	(2)	2	212	Apllo	✓
42	CORE UPER D/D	(2)	2	017	Apllo	✓
	SHUTTLE ELEV. PASS		4	008	PEC3	✓
	ELECT D		2	210	Apllo	✓
	COAT/STORAGE 'D'-TTB		2	210	PEC3	✓
42	'G' ELECT/SEC.	(2)	4	080	PEC3	✓
43	PASS/FREIGHT	(2)	2	020	BRK	✓
	ELECT A-B	(2)	2	213	BRK	✓
	TELEPH A-B	(2)	2	213	BRK	✓
	COMM A-B	(2)	2	213	BRK	✓
	COMM C-D	(2)	2	212	BRK	✓
	TELEPH C-D	(2)	2	212	BRK	✓
	ELECT C-D	(2)	2	212	BRK	✓
	CORE HEL AREA	2	2	253	Apllo	✓
	CORE UPER D/D	2	2	018	Apllo	✓
	ELECT G		4	081	BRK	✓
43	SECURITY		4	081	PEC3T	✓
	SHUTTLE ELEV. PASS		4	009	PEC3	✓
43	'F' ELECT	NO S/D	IN	PREMISES; —		

INVOICE TO: 7 W.T.C. (SOLOMON BROTHERS) N.Y.C. —

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES	F.S.I.
	DATE SCHEDULED: 4-24-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
4	BATTERIES 12 VOLTS (STROBE PNL'S)	69.95

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of this assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME

DATE

TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT PREV MAINT. ON SMOKE DETECTION ON FLOOR'S 43 & 42ND AT LISTED ABOVE. — DEFICIENCY BATTERIES 42ND FL. FREIGHT ELEV. UNIT — POOR SENS. NEED TO BE REPLACED TO CONTINUE. — SYSTEM ~~BACK~~ IN OPERATION — 43RD FL
(4) 'F' ELECT CLOSET - S/D MISSING / NEED UNIT TO BE WIRED / INSTALLED.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

(7) BATTERIES TO BE REPLACED ON 7 & 8TH FL. — STROBE PNL'S. —

FIRE SER'ICE INCORPORAT'D

94437

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
ZWTC
New York, N.Y.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
		SC00818				F.S.D.
PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		4/24/01	A.M. -			Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00 AM	4:30 P.M.						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 4/24/01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: Frank Ropris

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Date

Name

X

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Tech. Jimmy Torres on the
Performing of the service Contract
of Cleaning and Testing of the Area
Smoke Detectors and Duct Detectors
On #3rd and #2nd floors
See Service report #25476

WORK REMAINING

FCI 155
REV 6/86

FIRE SER''ICE INCORPORAT''D 77450

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC
New York, N-Y.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
	Sc008 18				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		4/21/01	AM-	Frank R.

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
					PREVENTIVE MAINTENANCE CONTRACT	

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	7:AM	330PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 4/21/01

CUSTOMER SIGNATURE: [signature] (Ahmed)

WILL RETURN ON:

SERVICEMAN SIGNATURE: Frank [signature]

PROBLEM—AS DESCRIBED

Service Contract

SERVICE PERFORMED

Assisting Jimmy Torrez Tech. on the Cleaning and Testing of the Smoke and Duct Detectors in the Elevator Motor Rooms and Elevator Shafts from 48th Floor Down to 43rd Floor. See report #23475

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FCI 155
REV 8188

FIRE SERVICE INCORPORATED　23475

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		DEVICES	CABLE	XTNDR	S/D	CLEAN TEST
48	ROOF	E.M.R	CAR 31	2	226	BLK	✓
47	SHUTTLE	ELEV. SHAFT		4	037	PEC3T	✓
47	SHUTTLE	ELEV. SHAFT		4	037	PEC3T	✓
47	E.M.R	AREA	CAR 29-30	2	224	BLK	✓
47	ELEV. SHAFT	CAR 44/47		4	037	PEC3T	✓
	BANK	H-SHUTTLE					
47	E.M.R	CARS	21-28	2	220	BLK	✓
47	E.M.R	AREA	21-28	2	220	BLK	✓
47	E.M.R	AREA	21-28	2	220	BLK	✓
47	E.M.R	AREA	21-28	2	220	BLK	✓
47	E.M.R	AREA	21-28	2	220	BLK	✓
47	E.M.R	AREA	21-28	2	220	BLK	✓
46	KITCHEN	SHUTTLE	CAR 38	4	036	PEC3T	✓
	SHAFT	BANK K — (PIPE)					
46	FREIGHT SHUTTLE	HKE-1 AREA. E.M.R	CAR 38				
	BANK I	—		4	036	PEC3T	✓
47	E.M.R	AREA - 32-33		4	067	PEC3T	✓
46	E.M.R	H.KE1 AREA		4	065	PEC3T	✓
	CAR'S 2-3						
46	E.M.R	HKE-1 AREA		4	066	PEC3	✓
	BANK J CAR 37						
46	SHAFT	SHUTTLE	CAR 37	4	036	PEC3T	✓
	BANK J. CAR 37						
43	E.M.R	AREA	61-2	4	064	PEC3	✓
	CAR'S	34-35	BATH	ENT./LADIES -			

INVOICE TO: 7 W.T.C.
SILVERSTEIN PROP.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED SAT 4-21-01
CONTRACT # S/C 00818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE　☐ TEST
☐ JOB COMPLETE　☒ JOB INCOMPLETE
☐ SYSTEM ON LINE　☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	7:10 AM	3:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature] AHMED

SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instituted and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME　DATE　TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT - PREVENTIVE MAINTENANCE SMOKE DETECTION SYSTEM / UNITS BY ELEVATOR'S SHAFTS & ELEV. MOTOR RM'S ASSISTED BY OTIS MECH (BOB) - UNITS ALARMED / CLEANED TESTED MONITORED / RESET AT F.C. STATION OUTPUTS - NORMAL - SYSTEM BACK IN OPERATION. —
TO BE CONTINUE

(A) INACCESSIBLE　(B) MISSING　(C) DEFECTIVE　(D) OTHER

FIRE SERVICE INCORPORATED

23474

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S.		CABLE	XMDR	S/D	TEST CLEAN
38	W) HER. AREA.		4	028	PEC 3T	✓
	W. HER. D/D.		4	0100	Hochiki	✓
	ELECT A-B	(2)	2	202	BLK	✓
	TELEPH A-B	(1)	2	202	BLK	✓
	COMM A-B	(2)	2	202	BLK	✓
	ELECT C		2	203	BLK	✓
	ELECT D		2	203	BLK	✓
	ELECT D.W.		2	203	Edwards	✓
	ELECT F		4	052	PEC 3	✓
	ELECT G		4	076	PEC 3	✓
	SECURITY		4	076	PEC 3	✓
	PASS/FREIGHT ELEV. (2)		2	015	BLK	✓
	ELEV. SHUTTLE		4	004	PEC 3	✓
	CORE HER AREA (3)		2	004	PEC 3T	✓
	CORE HER D/D	(2)	2	005	Hochiki	✓
	W. HER AUDTM AREA		4	046	PEC 3T	✓
	W. HER D/D AUDTM		4	127	Edwards	✓
39	ELECT A-B	(2)	2	205	BLK	✓
	COMM A-B	(2)	2	205	BLK	✓
	TELEPH A-B	(2)	2	205	BLK	✓
	ELECT C		2	204	BLK	
	ELECT D.W		2	204	BLK	
	ELECT F		2	053	PEC 3	
	ELECT G		4	077	PEC 3	
	SECURITY CLOSET		4	077	PEC 3	
	ELECT D1		2	204	BLK	
	FREIGHT/PASS ELEV (2)		2	016	BLK	
	ELEV. SHUTTLE		4	005	PEC 3	
	RECP. CEILING D/D (2)		2	254	Apollo	
	RECEP. CEILING D/D/SEC (3)		2	254	Apollo	
	CORE HER AREA	(3)	2	006	PEC 3	
	CORE D/DET.	(2)	2	007	Hochiki	
	W. HER AREA		4	029	PEC 3T	
	W. HER. D/D.		4	101	Edwards	

INVOICE TO: 7. W.T.C. (Solomon/Smith Barney) N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / C. TABARES	F.S.D.
	DATE SCHEDULED: 4-18-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: CSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN'S SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Serv. Contract - Prev. Maint. Smoke Detection (Solomon) Floor's 39 & 38' as listed all area closet's. System ack/reset's - at F.C. Station. - Back to normal operation. -

(*) Also check as per F.S.D. Strobe (pnl) 7 & 8' Fl. Trouble condition. - Taken to low batteries 12 VLT / 7 AH. - to be replaced (2) set's. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

23470

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				Cable	XTNDR	S/O	TST Clean
44	Elect	A		2	215	BLK	✓
	Comm	A		2	215	BLK	✓
	Teleph	A		2	215	BLK	✓
	Pass	Elev.		2	021	BLK	✓
	Elect	B		2	215	BLK	✓
	Comm	B		2	215	BLK	✓
	Teleph	B		2	215	BLK	✓
44	Freight	Elev.		2	021	BLK	✓
	Elect	G		4	082	PEC3	✓
	Security	Closet		4	082	PEC3	✓
	Shuttle	Elev.		4	010	PEC3	✓
	Shuttle	Elev.		2	018	PEC3	✓
	West	Fan Rm	D/D	4	112	[illegible]	✓
	West	Fan Rm	Area	4	034	PEC3T	✓
44	Elect	F		4	058	PEC3	✓
2nd	Elect	D		1	163	BLK	✓
2nd	Front	Ent-High Ceiling		1	163	BLK	✓
2nd	"	"	"	1	163	BLK	✓
2nd	"	"	"	1	163	BLK	✓
2nd	"	"	"	1	163	BLK	✓
2nd	Front	Ent	Escalator's	1	163	BLK	✓
	•	•	•	•	[illegible]	[illegible]	•
2nd	Hallway	Display	Lobby	1	163	BLK	✓
	"		"	1	163	BLK	✓
2nd	Fan Rm	East	D/D	1	270	[illegible]	✓
1st	Freight	Elev.		1	000	PEC3	✓
	Pump Rm		(2)	1	160	BLK	✓
	Elect	A		1	160	BLK	✓
	Trash Rm	Storage		1	160	PE3T	✓
	Handicap	Elev	Lobby	1	000	BLK	✓
1st	Low Ceiling	Lobby	(2)	1	161	BLK	✓
1st	Elect	D		1	161	BLK	✓

INVOICE TO: 7 W.T.C. Prop. Silverstein Prop. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
[signature] F. Rosario	F.J.
	DATE SCHEDULED 4-11-01
CONTRACT # SK00818	TYPE OF SYSTEM LSN2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☒ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Silverstein
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING

Service Contract / Prev. Maintenance Smoke Detection Units on 44 Fl and 2nd / 1st Fl. Lobbies as listed above (Silverstein Area). — Use of "Genie Boom" to reach High Ceiling Lobby Entrance. — System Left Reset Back to Operation. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of the assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their servicing of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

23468

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR	AREA'S	CABLE	XTNGE	S/D	TST/CLEAN
47	STAIR 'A'-ELEV.	2	024	BLK	✓
	ELEV. SHUTTLE	4	016	PEC3T	✓
	SECURITY CLOSET	4	085	PEC3	✓
	ELECT 'G'	4	085	PEC3	✓
	ELECT A	2	222	BLK	✓
	ELECT B	2	222	BLK.	✓
	ELECT 'C'	2	223	BLK	✓
	ELECT F	4	061	PEC3	✓
	TELEPH B	2	222	BLK	✓
	'B' STAIRWAY/LANDING	2	221	EDWDS	✓
	TELEPH A	2	222	BLK	✓
	COMM D	2	223	BLK	✓
	CUSHMAN OFFICE AREA	4	113	EDWDS	✓
	SHAFT VERTICAL CONV.	4	068	EDWDS	✓
	W. MER	4	069	EDWDS	✓
	W. MER D/D 47-1	4	115	EDWDS	✓
	CORE MER D/D	2	023	[illegible]	✓
	CORE MER AREA (3)	2	022	PEC3	✓
46	FREIGHT ELEV. LBY	2	023	BLK	✓
	ELEV. SHUTTLE 'F'	4	014	PEC3	✓
	ELEV. SHUTTLE 'H'	4	015	PEC3	✓
	KITCHEN SHUTTLE ELEV	4	013	PEC3	✓
	ELECT 'G'/SEC. (2)	4	084	PEC3	✓
	ELECT B	2	218	BLK	✓
	COMM B	2	218	BLK	✓
	ELECT A	2	218	BLK	✓
	COMM A	2	218	BLK	✓
	TELEPH A	2	218	BLK	✓
	TELEPH D	2	219	BLK	✓
	ELECT D	2	219	BLK	✓
	COMM D	2	219	BLK	✓
	CORE MER D/D (2)	2	021	ADDCK	✓
	CORE MER AREA (3)	2	020	PEC3	✓
	ELECT F	4	060	PEC3	✓
	ELECT C	2	219	PEC3	✓

INVOICE TO: 7 W.T.C. / SILVERSTEIN PROP. / N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	7.5.7
	DATE SCHEDULED: 4-10-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	PO #

CALL AUTHORIZED BY	PHONE	EXT

- ☒ MAINTENANCE
- ☒ TEST
- ☐ JOB COMPLETE
- ☐ JOB INCOMPLETE
- ☐ SYSTEM ON LINE
- ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	9:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service [redacted] and its employees regarding interruption of fire protection service during their service of the equipment.

NAME

DATE

TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT

PREV. MAINTENANCE SMOKE DETECTION CHECKS - CLASS E SYSTEM - ON FLOOR'S 47 - 46 - AREAS / LOCATIONS AS LISTED ABOVE - EQUIP / ACK / RESET PROPERLY. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

23465

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	AREA'S			S/D	CABLE	ZONE	TEST CLEAN
6	SWITCHGEAR		VAULT	BRK	1	171	✓
	"		"	BRK	1	171	✓
	"		"	BRK	1	171	✓
	"		"	BRK	1	171	✓
	"		"	BRK	1	171	✓
	HIGH	VOLTAGE	VAULT	BRK	1	171	✓
6	High	Voltage	VAULT (X4)	BRK	1	171	✓
	"	"	" (4)	BRK	1	171	✓
	"	"	" (4)	BRK	1	171	✓
5	H.V. VAULT	(X6)		BRK	1	170	✓
5	H.V. VAULTS	(X6)		BRK	1	170	✓
5	SWITCH	GEAR	NORTH	BRK	1	170	✓
	SWITCH	GEAR	NORTH	BRK	1	170	✓
	SWITCH	GEAR	NORTH	BRK	1	170	✓
5	SWITCH	GEAR	SOUTH	BRK	1	170	✓
	SWITCH	GEAR	SOUTH	BRK	1	170	✓
18	CORE HET	STROBE PNL AT 101 HOTEL					✓
	(2) BATTERIES Replaced/Check.						
	Trouble Unit back in order						

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: TW. F.C.
SILVERSTEIN PROP.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES	F.S.D.
	DATE SCHEDULED: 4-4-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LW 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	BATTERIES 12 VOLT PACK (STROBE PNL)	69.95

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN'S SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING

Prev. Maintenance Smoke Detection Silverstein Area Only on 6th/5th Fl. As Listed (High Voltage Vault - Escorts Needed) Also Repairs done on 18th Fl Strobe Pnl. - (101) Batteries Replaced) O.K.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

23466

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	AREA'S.	CABLE	XTNDR	S/D	TEST
3rd	Hallway Top Escalatr	1	166	BLK	✓
	Hallway Top Escalatr	1	166	BLK	✓
	Tele A	1	166	BLK	✓
	Comm A	1	166	BLK	✓
	Elect A	1	166	BLK	✓
	Comm B	1	166	BLK	✓
	Comm/Tele B	1	166	BLK	✓
3	Freight Elev Lbby	1	0021	BLK	✓
	Pass Elev. Lbby (413-144)		002	BLK	✓
	Elev. Min Rise (22-28)	1	166	BLK	✓
	Elev. High Rise (36-45)	1	166	BLK	✓
	Elev Min Rise (22-28)	1	0021	BLK	✓
	(Repair/Reset's Tampers)				
45	Tamper S/W	2	147		✓
	Alarm/Reseted. Adjusted				
42	Tamper S/W	2	139		✓
	Alarm/Reseted Adjusted.				
40	Tamper S/W	2	137		✓
	Trouble/Repaired (Wiring Broken)		—		
37	Tamper S/W	2	134		✓
	Alarm/Reseted Adjusted.				
20	Tamper S/W	2	143		✓
	Alarm/Reseted/Adjusted		—		

INVOICE TO: W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F-S-D
	DATE SCHEDULED: 4-3-01
CONTRACT #: SIC00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: Service Contract Preventive Maintenance on Smoke Unit's Floor's 3rd (Silverstein Area) - only. - Also Adjusted Alarm/Alarms Reseted on Tamper S/W on Floor (Listed Above) B Riser only - DSK-FSD. - Unit Back on Service. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11842

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	AREAS/CLOSETS	CARD	XTNDR	S/D	TEST CLEAN
23	PASS ELEV.	2	000	BRK	✓
	COMM B	2	169	BRK	✓
	ELECT B	2	169	BRK	✓
	TELCOM B	2	169	BRK	✓
	ELECT A	2	169	BRK	✓
	COMM A	2	169	BRK	✓
	TELCOM A	2	169	BRK	✓
	CORE HEX D/D.	2	228	Hochiki	✓
	CORE HEX D/D	2	228	Hochiki	✓
	ELECT C	2	168	BRK	✓
	COMM C	2	168	BRK	✓
	TELCOM C	2	168	BRK	✓
	FREIGHT ELEV	2	000	BRK	✓
	COMM D	2	168	BRK	✓
	ELECT D	2	168	BRK	✓
	TELCOM D	2	168	BRK	✓
	RETURN D/D LADDER	2	227	Hochiki	✓
*	RETURN D/D NORTH	N/A – AS PREVIOUS			
*	RETURN D/D. SOUTH (SILVERSTEIN AREA)	N/A – AS PREVIOUS			
5	FAN RM – STEAM RM D/D	1	223	Hochiki	✓
5	FAN RM DUCT DET.	1	224	Hochiki	✓
5	FAN RM D/DET.	1	228	Hochiki	✓
5	FAN RM D/DET	1	267	Hochiki	✓

AS REQUEST / MARTY = SILVERSTEIN
D. CAMPBELL. SOLOMON
| 32 | CHECK / TEST AUDIO VISUAL / ALARM DEVICES |
| 33 | " " " " |
AS MR CAMPBELL REQUEST / P.A. TEST.
audibility (DECIBELS) INTENSITY. –

INVOICE TO: 2 W.T.C. R
SILVERSTEIN PROP.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.I.
	DATE SCHEDULED: 3-28-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	PO #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keefe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT — PREV. MAINTENANCE ON SMOKE DETECTION SYSTEM – CLASS 'E' DEVICES LOCATED BY CLOSET'S AREA CORE HEX'S – DUCT UNIT – ELEVATION LOBBYES AS LISTED. — ALSO ASISTED BUILDING / SOLOMON BROTHERS REQUEST P.A. TEST AUDIO/VISUAL ALARM'S ON 32/33 FLOORS – AS REQUESTED MR: ED CAMPBELL & MARTY SYSTEM ACK/RESETED PROPERLY. — (PRINT OUT)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

:27005

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	Area/Locat			Cable	XTNDR	S/D	TEST
10	Elect A			1	181	BLK	✓
10	Comm A			1	181	BLK	✓
10	Teleph A			1	181	BLK	✓
10	Comm B			1	181	BLK	✓
10	Elect B			1	181	BLK	✓
10	Teleph B			1	181	BLK	✓
10	Pass/Freight	(2)		1	009	BLK	✓
10	Elect C			1	180	BLK	✓
10	Comm C			1	180	BLK	✓
10	Teleph C			1	180	BLK	✓
10	Teleph D			1	180	BLK	✓
10	Elect D			1	180	BLK	✓
10	Comm D			1	180	BLK	✓
10	Core HER	(2)		1	241	Hochiki	✓
10	Return D/D	(3)		1	240	Hochiki	✓
9	Elev. Pass			1	008	BLK	✓
9	Comm A			1	179	BLK	✓
9	Elect A			1	179	BLK	✓
9	Teleph A			1	179	BLK	✓
9	Elect B			1	179	BLK	✓
9	Comm B			1	179	BLK	✓
9	Teleph B			1	179	BLK	✓
9	Freight Elev			1	008	BLK	✓
9	Elect C			1	178	BLK	✓
9	Comm C			1	178	BLK	✓
9	Teleph C			1	178	BLK	✓
9	Elect D			1	178	BLK	✓
9	Comm D			1	178	BLK	✓
9	Teleph D			1	178	BLK	✓
9	Return D/D South			1	238	Hochiki	✓
9	Return D/D North			1	238	Hochiki	✓
9	Return D/D East			1	238	Hochiki	✓
9	Corener D/D			1	239	Hochiki	✓
9	Corener D/D			1	239	Hochiki	✓

INVOICE TO: 2 W.T.C. / Silverstein Prop. / N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / E. Rosario	F.S.I
	DATE SCHEDULED: 3-27-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: S/Contract - Preventive Maintenance Smoke Detectors Built on Floor's 9 & 10 / Areas Above Listed. - System OK / Reset properly. - (Print out). -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 27004

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	Areas		Cable	Trans	S/D	Test
7TH	Comm A		1	175	BRK	✓
	Elect A		1	175	[illegible]	✓
	Teleph A		1	175	BRK	✓
	Pass Elev		1	006	BRK	✓
	Freight Elev		1	006	BRK	✓
	Comm B		1	175	BRK	✓
	Elect B		1	175	BRK	✓
	Teleph B		1	175	BRK	✓
	Comm C		1	174	BRK	✓
	Elect C		1	174	BRK	✓
	Teleph C		1	174	BRK	✓
	Comm D		1	174	BRK	✓
	Elect D		1	174	BRK	✓
	Teleph D		1	174	BRK	✓
	Core MER		1	235	Hochiki	✓
	Core MER		1	235	"	✓
	Return North D/D		1	234	"	✓
	Return South N/A		—	—	—	—
6TH	Pass Elev		1	005	BRK	✓
	Freight Elev		1	005	BRK	✓
	Comm A		1	172	BRK	✓
	Elect A		1	172	BRK	✓
	Teleph A		1	172	BRK	✓
	Comm B		1	172	BRK	✓
	Elect B		1	172	BRK	✓
	Fan Room Area		1	173	BRK	✓
	Fan Room Area		1	173	BRK	✓
	Fan Room Area		1	173	BRK	✓
	Fan Room D/D		1	231	Hochiki	✓
	Fan Room D/D		1	229	Hochiki	✓
	Fan Room D/D		1	232	Hochiki	✓
	Fan Room D/D		1	233	Hochiki	✓

INVOICE TO: 7 WTC
New York, N.Y.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
Frank R Marcos D	F.S.D.
	DATE SCHEDULED: 03-21-01
CONTRACT #: SC00818	TYPE OF SYSTEM: LSH 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE:
SERVICEMAN SIGNATURE: Frank Lucan, Marcos Claudio

SERVICE PERFORMED & REMAINING
Preventive Maintenance
See all Smoke and Duct Detectors Located on
7th & 6th floors. Performing Satisfactorily.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during that service of the equipment.

NAME

DATE

TIME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11840

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	Areas		Cable	S/D	Zone	Test Clean
8	Elev	Mach	/	BRK	007	
			/			
"	Freight Elev		/	BRK	007	✓
"	Elect	A	/	BRK	177	✓
"	COMM	A	/	BRK	177	✓
	Teleph	A	/	BRK	177	✓
"	COMM	B	/	BRK	177	✓
"	Elect	B	/	BRK	177	✓
"	Teleph	B	/	BRK	177	✓
"	COMM	C	/	BRK	176	✓
"	Elect	C	/	BRK	176	✓
"	Teleph	C	/	BRK	176	✓
"	Com	D	/	BRK	176	✓
"	Elect	D	/	BRK	176	✓
"	Teleph	D	/	BRK	176	✓
"	Return D/D North		/	Hochiki	236	✓
"	Return D/D South		N/A	—	—	—
"	Return D/D East		(File)	Hochiki	236	✓
"	Core MER D/D		/	Hochiki	237	✓
"	Core MER D/D		/	Hochiki	237	✓

Note: Removed of a BRK Detector on 21st Floor Electric Closet and Replaced with a New One. Hooked Separately. Report Made By Jay.

INVOICE TO: 7WTC
New York, N.Y.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
Frank K. / Jay	F.S.D.
	DATE SCHEDULED: 03-20-01
CONTRACT #: Sc00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Preventive Maintenance
As per contract cleaned and tested elevator lobby detectors, and detectors and duct smoke detectors on 8th Floor. All devices tested are working properly.
System is operational

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11839

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR	AREA	CODE	XNDR	S/D	TEST
11	COMM B	1	182		✓
	ELECT B	1	182		
	TELEPH B	1	182		
	FREIGHT ELEV.	1	010	BAK	✓
	ELECT A	1	182		
	COMM A	1	182		
	TELEPH A	1	182		
	PASS ELEV.	1	010		
	COMM C	1	183		
	ELECT C	1	183		
	TELEPH C	1	183		
	TELEPH D	1	183		
	ELECT D	1	183		
	COMM D	1	183		
11	CORE HER D/D	1	243	Hotkis	✓
	CORE HER D/D	1	243	Hotkis	✓
	RETURN D/D North	1	242	Hotkis	✓
	RETURN D/D South	1	242	Hotkis	✓

12' STROBE PNL AFC 101 (2) PANELS
North SIDE UNIT REPAIRED. — B COMM.
(12VDC BATTERIES Replaced). — CLOSET.

1 B STAIR PAYPHN (1-12E) Repairs/ADJ.
CHECK OK. —

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
SILVERSTEIN PROP.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / A. ZINGER	F.S.D.
	DATE SCHEDULED: 3-14-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
1	12VDC BATTERIES	

CUSTOMER NAME (PRINT) Sean O'Keeffe.
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT. PREV. MAINTENANCE ON SMOKE DEVICES DETECTORS INSIDE AREA CLOSETS AS (LISTED) ON 11th FLOOR. — ALSO REPAIRS ON 12th FL. STROBE PNL & 1st FL TALKER S/W. — SYSTEM ACK/RESET BACK TO OPERATION.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11838

REPORT OF FIELD SERVICE

FLOOR	AREA'S			MODULE	XTNDR	S/D.	TEST
13	ELEV. PASS			1	019	BLK	✓
	FREIGHT ELEV			1	012	BLK	✓
	COMM	A-B	(2)	1	186	BLK	✓
	ELECT	A-B	(2)	1	186	BLK	✓
	TELEPH	A-B	(2)	1	186	BLK	✓
	CORE	HEL D/D		1	247	HOCHIKI	✓
	CORE	HEL D/D		1	247	HOCHIKI	✓
	PLENUM	D/D	NORTH	1	246	HOCHIKI	✓
	PLENUM	RET D/D	SOUTH	1	246	HOCHIKI	✓
	COMM	C-D	(2)	1	187	BLK	✓
	ELECT	C-D	(2)	1	187	BLK	✓
	TELEPH	C-D	(2)	1	187	BLK	✓
12	PASS ELEV.			1	011	BLK	✓
	ELECT	A-B	(2)	1	184	BLK	✓
	TELEPH	A-B	(2)	1	184	BLK	✓
	COMM	A-B	(2)	1	184	BLK	✓
	FREIGHT ELEV			1	011	BLK	✓
	CORE	HEL D/D		1	245	HOCHIKI	✓
*	CORE	HEL D/D (LED)		1	245	HOCHIKI	✓
	RETURN	D/D	NORTH	1	244	HOCHIKI	✓
	RETURN	D/D	SOUTH	1	244	HOCHIKI	✓
	COMM	C		1	185	BLK	✓
	ELECT	C		1	185	BLK	✓
	TELEPH	C		1	185	BLK	✓
	TELEPH	D		1	185	BLK	✓
	COMM	D		1	185	BLK	✓
	ELECT	D		1	185	BLK	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C. / SILVERSTEIN PROP. / N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 3-13-01
CONTRACT #: 5/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:00 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Open (Detuned Manual) FT8500 Smoke Detection System Class "E" / As Listed Above Floors 13" & 12" All Areas. — Semi-annually

(*) NOTE: Core Hel D/D (L.E.D.) Replacement/Repairs Unit O.K. 1) Unit.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE X TIME

14546

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S.		Cable	ADDR	S/D	TST Clean
15	PASS/FREIGHT	(2)	1	014	BLK	✓
	COMM	B-A (2)	1	190	BLK	✓
	ELECT	B-A (2)	1	190	BLK	✓
	TELEPH	B-A (2)	1	190	BLK	✓
	CORE HEX D/D Supply		1	251	Hochiki	✓
	CORE HEX D/D Supply		1	251	Hochiki	✓
	COMM	C	1	191	BLK	✓
	ELECT	C	1	191	BLK	✓
	TELEPH	C	1	191	BLK	✓
	TELEPH	D	1	191	BLK	✓
15	COMM	D	1	191	BLK	✓
	ELECT.	D	1	191	BLK	✓
	RETURN DUCT North		1	250	Hochiki	✓
(A)	" DUCT South		NO ACCESS	-		—
14	COMM	A-B (2)	1	189	BLK	✓
	ELECT	A-B (2)	1	188	BLK	✓
	TELEPH	A-B (2)	1	188	BLK	✓
	PASS ELEV./FREIGHT (2)		1	013	BLK	✓
	CORE HEX D/D		1	249	Hochiki	✓
	CORE HEX D/D		1	249	Hochiki	✓
	TELEPH	C	1	189	BLK	✓
	ELECT	C	1	189	BLK	✓
	COMM	C	1	189	BLK	✓
	TELEPH	D	1	189	BLK	✓
	ELECT	D	1	189	BLK	✓
	COMM	D	1	189	BK	✓
14	RETURN D/D South		1	248	Hochiki	✓
	" D/D North		NO ACCESS	AS PREVIOUS		

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
Silverstein Prop.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.I.
	DATE SCHEDULED: 3-07-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Service Contract - Prev. Maintenance on Scope
① Detectors Units on Floors 15th / 14 Floor Areas Above Listed
② NOTE: Units on 15/14" Return Duct Units not accessible / As previous listed. - Bldg Notified System OK / Reseted. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SERVICE INCORPORATED

22383

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREAS		CABLE	XTNDE	S/D	TST/CLEAN
17	PASS ELEV.		1	096	BRK	✓
	ELECT A		1	197	BRK	✓
	COMM A		1	197	BRK	✓
	TELEPH A		1	197	BRK	✓
	COMM B		1	197	BRK	✓
	TELEPH B		1	197	BRK	✓
	ELECT B		1	197	BRK	✓
	CORE HER.		1	000	HOCHIKI	✓
	CORE HER.		1	000	HOCHIKI	✓
	FREIGHT ELEV.		1	016	BRK	✓
	ELECT C		1	196	BRK	✓
	COMM C		1	196	BRK	✓
	TELEPH C		1	196	BRK	✓
	COMM D		1	196	BRK	✓
	ELECT D		1	196	BRK	✓
	TELEPH D		1	196	BRK.	✓
	(*) PLENUM RETURN (NO ACCESS SOLID CEILING) – AS PREVIOUS REPORTED N/A. –					
16	PASS/FREIGHT (2)		1	015	BRK	✓
	COMM A-B (2)		1	193	BRK	✓
	ELECT A-B (2)		1	193	BRK	✓
	TELEPH A-B (2)		1	193	BRK	✓
	CORE HER D/D (1)		1	253	HOCHIKI	✓
	CORE HER D/D (1)		1	253	HOCHIKI	✓
	COMM C		1	194	BRK	✓
	ELECT C		1	194	BRK	✓
	TELEPH C		1	194	BRK	✓
	TELEPH D		1	194	BRK	✓
	COMM D		1	194	BRK	✓
	ELECT D		1	194	BRK.	✓
	PLENUM RET D/D NORTH.		1	252	HOCHIKI	✓
	(A) PLENUM RET. D/D SOUTH N/A NO ACCESS SOLID CEILING AS PREVIOUS REPORTED TO BLD. –					

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 3-6-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection [redacted] by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: PERFORMED SERVICE ON SMOKE DETECTION UNITS ON FLOOR'S 17 & 16 FL. ALL AREAS (ABOVE LISTED) – SYSTEM OK/RESETTED AS OPERATIONAL. –
* NOTE: 17 FL. RETURN UNIT NO ACCESS AS PREVIOUS –
(A) 16 FL NO ACCESS SOUTH RETURN UNIT AS PREVIOUS REPORTED. –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22382

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREA'S		CABLE	XTNDR	S/D	TST CLEAN
19	ELEV. LBBY		1	018	BRK	✓
	ELEC B		1	201	BRK	✓
	COMM B		1	201	BRK	✓
	TELEPH B		1	201	BRK	✓
	COMM A		1	201	BRK	✓
	ELEC A		1	201	BRK	✓
	TELEPH A		1	201	BRK	✓
	FREIGHT LBBY		1	018	BRK	✓
	COMM C		1	200	BRK	✓
	ELEC C		1	200	BRK	✓
	TELEPH C		1	200	BRK	✓
	ELEC D		1	200	BRK	✓
	COMM D		1	200	BRK	✓
	TELEPH D		1	200	BRK	✓
19	CORE HGR.	(2) 2D	1	004	Hochiki	✓
	RETURN D/D	(2)	1	003	Hochiki	✓
18	ELEC A		1	199	BRK	✓
	COMM A		1	199	BRK	✓
	TELEPH A		1	199	BRK	✓
	PASS ELEV.		1	017	BRK	✓
	ELEC B		1	199	BRK	✓
	COMM B		1	199	BRK	✓
	TELEPH B		1	199	BRK	✓
	FREIGHT ELEV.		1	017	BRK	✓
	COMM C		1	198	BRK	✓
	ELEC C		1	198	BRK	✓
	TELEPH C		1	198	BRK	✓
	COMM D		1	198	BRK	✓
	ELEC D		1	198	BRK	✓
	TELEPH D		1	198	BRK	✓
	RETURN DUCT NORTH		1	001	Hochiki	✓
18	RETURN DUCT SOUTH		1	001	Hochiki	✓
	CORE HGR DUCT D		1	002	Hochiki	✓
	CORE HGR D/D		1	002	Hochiki	✓

INVOICE TO: 7 W.T.C.
SILVERSTEIN PROP.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / E. Rosario	F.S.D.
	DATE SCHEDULED: 2-28-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: S/ CONTRACT - / PREV. MAINTENANCE ON SMOKE DETECTORS CLASS E SYSTEM IN AREAS / FLOORS 19/18 AS LISTED ABOVE SYSTEM OK / NECESSARY FUNCTIONS OUTPUTS OK

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22381

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	AREA'S		Cable	Address	Tst Clean	S/D
21	Pass Elev.		1	020	✓	BLK
	Freight Elev.		1	020	✓	BLK
	Comm A		1	204	✓	BLK
	Teleph A		1	204	✓	BLK
	Elect A		1	204	✓	BLK
	Elect B		1	204	✓	BLK
	Comm B		1	204	✓	BLK
	Teleph B		1	204	✓	BLK
	Elect C		1	205	✓	BLK
	Comm C		1	205	✓	BLK
	Teleph C		1	205	✓	BLK
	Core HER	Supply Duct	1	008	✓	Hochiki
	Core HER	Supply Duct	1	008	✓	Hochiki
	Teleph D		1	206	✓	BLK
	Elect D		1	206	✓	BLK
	Comm D		1	206	✓	BLK.
21	Return Duct North		1	007	✓	Hochiki
	Return Duct South		1	007	✓	Hochiki
20th	Comm A		1	203	✓	BLK
	Elect A		1	203	✓	BLK
	Teleph A		1	203	✓	BLK
	Elect B		1	203	✓	BLK
	Comm B		1	203	✓	BLK
	Teleph B		1	203	✓	BLK
	Teleph C		1	202	✓	BLK
	Comm C		1	202	✓	BLK
	Elect C		1	202	✓	BLK.
	Pass Elev.		1	019	✓	BLK
	Freight Elev.		1	019	✓	BLK
	Elect D		1	202	✓	BLK
	Comm D		1	202	✓	BLK
	Teleph D		1	202	✓	BLK
	Core HER Duct (2)		1	006	✓	Hochiki
	Return Duct North		1	005		
20	Return Duct South		1	005	✓	

INVOICE TO: 7th W.T.C.
Silverstein Properties
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 2-27-01
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instituted and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING:
Return Duct N.E. 3 045 ✓ Hochiki
S/Contract / Preventive Maintenance on Smoke Detector Units On Floor's 21st / 20th Areas / Closet's as listed above - System ACK/Reset Functions / Print Out. - O.K. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22380

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	AREA'S	CLOSET'S		CABLE	XTNDR	TST	S/D
22	ELEV	S/D.		1	021	✓	213 (DFS)
	ELEV	'C'		1	206	✓	BRK.
	COMM	C		1	206	✓	BRK
	TELEPH	C		1	206	✓	BRK
	TELEPH	'D'		1	206	✓	BRK
	COMM	'D'		1	206	✓	BRK.
	ELEV	'D'		1	206	✓	BLK
22	ELEV	'A'		1	207	✓	BLK
	COMM	'A'		1	207	✓	BLK
	TELEPH	'A'		1	207	✓	BLK
	COMM	'B'		1	207	✓	BLK
	ELEV	'B'		1	207	✓	BLK
	TELEPH	'B'		1	207	✓	BLK
	CORE	HER D/DET		1	010	✓	Hochiki
	CORE	HER D/D.		1	010	✓	Hochiki
	RETURN D/D SOUTH			1	009	✓	Hochiki
	RETURN D/D. NORTH			1	009		Hochiki
22	FREIGHT ELEV.			1	021	✓	BRK.

11 SPEAKER PAGE - (3) CKTS OUT (REPAIRED) WIRING for EXISTING CKTS - TESTED MAINT/FIBER O.K. -

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C. (SILVERSTEIN) N.Y.C.

ATT: J. Carrozzo [illegible]

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 2-21-01
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT - REPAIR - AS ABOVE LISTED - 22nd FL. S/DETECTORS TESTED & CLEANED [illegible] PREVENTIVE MAINTENANCE ALSO CHECKED REPAIRS ON AUDIO SPEAKER'S PAGE ON 11 FL (3) CKTS N/G - 12 FL (3) WIRING CORRECTED WITH TEST OK - (AS PER PREVIOUS REPORT) -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22379

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

(W/STA) (SPEAKERS)

LOCATIONS			DEVICES				
FLOOR			CABLE	XTNDR	TST	SPKR'S	UNITS
6	H.E.R.		1	338	✓	O.K	1
	H.E.R-H.V.		1	338	✓		1
	ENG. RAN II		1	335	✓	↓	1
	Hallway		1	317	✓	↓	1
5	Hallway/Freight		1	336	✓	OK	1
	Switch Gear H.V.		1	336	✓		1
	H.E.R. NORTH			337	✓	↓	1
	H.E.R. South			337	✓		1
	H.E.R. N.W.			316	✓	↓	1
4	AREA 'B' exit			315	✓	OK.	1
3	RAN I. F.S.D. OFFICE			314	✓	OK.	1
2	H.E.R. WEST			334	✓	OK	1
2	TEIF/RANE RM			334	✓	↓	1
2	'A' EXIT			313	✓	↓	1
1	PUMP RM			341	✓	OK.	1
(*) 1	ENTRANCE CENTER			N/G	OUT	SERVICE	1
	Ground/Faulty Wiring			(G)	[illegible]	REPAIR	
	F.S.D. Notified —						

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 2-20-01
CONTRACT #: SKOO 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	930 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN.
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT —
Check/Test for operations on Communication/Fire Fire System As: Warden's phone stations & Speaker's page on/ Area/Floor's above listed floor's Completely. —.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22378

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			S/D (DEVICES)		Cable	
25	Elect	B		BRK		2	
	Comm	B		"		"	
	Tele	B		"		"	
	Pass	Elev		"		"	
	Freight	Elev		Edwards		2	
	Comm	A		BRK		"	
	Elect	A		"		"	
	Tele	A		"		"	
	Elec	C		"		"	
	Comm	C		"		2	
	Tele	C		"		"	
	Tele	D		"		"	
	Elect	D		"		"	
	Comm	D		"		"	
	Return	D/D	North	Hochiki		"	
	Return	D/D	South	Hochiki		2	
	Core	MER	D/D	Hochiki		"	
	Core	MER	D/D	Hochiki		"	
24	Elev	Lobby	Pass	BRK		2	
	Elev	Lobby	Freight	BRK		"	
	Comm	A		"		"	
	Elect	A		"		"	
	Tele	A		"		"	
	Comm	B		"		"	
	Elect	B		"		2	
	Tele	B		BRK		"	
	Comm	C		"		"	
	Elect	C		"		"	
	Tele	C		"		"	
	Comm	D		"		"	
	Elect	D		"		"	
	Tele	D		"		"	
	Return	D/D	North + South	Hochiki		"	
	Core	MER	D/D North South	Hochiki		"	

INVOICE TO: 7WTC
N.Y., N.Y.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
Frank R / Tom White	F.S.D
	DATE SCHEDULED: 02-14-01
CONTRACT #: S000818	TYPE OF SYSTEM: LSM 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT
☑ MAINTENANCE	☑ TEST
☐ JOB COMPLETE	☐ JOB INCOMPLETE
☐ SYSTEM ON LINE	☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection services by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection services during their service of the equipment.

NAME | DATE | TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keefe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: Frank Rosin / Thomas White

SERVICE PERFORMED & REMAINING
Contract Preventive Maintenance
Tested and Cleaned all Smoke and Heat Detectors
On the 25th and 24th Floors, Found that
every Unit Working Properly.
System Back to Normal Operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

27009

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR			Warden Phone			Speakers	
25th			✓			✓	
24th			✓			✓	
22nd			✓			✓	
21st			✓			✓	
20th			✓			✓	
19th			✓			✓	
18th			✓			✓	
17th			✓			✓	
16th			✓			✓	
15th			✓			✓	
14th			✓			✓	
13th			✓			✓	
12th			✓			✓	
MB. 11th			✓			✓	* Horns (N.O.) by stairs A+B.
8th			✓			✓	
7th			✓			✓	

INVOICE TO: #7 World Trade Center. N.Y.C, N.Y.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
(i) Clifton Basden (ii) Frank Rosario (iii) Tom White	F.S.D.
	DATE SCHEDULED: 13th Feb, 2001
CONTRACT #: SC00818	TYPE OF SYSTEM: ASN 2000.
FEE SERVICE #: -	PO #
CALL AUTHORIZED BY: Shop.	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
11:30 AM	12:00 PM	4:30 PM	AM / PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE:
SERVICEMAN SIGNATURE: Clifton Basden

SERVICE PERFORMED & REMAINING: Performed service - contract of Bldg Class-"E" Warden Phones and Floor-Page Speakers from 25th floor down through 7th floor. Found (1) problem — Horns by Stair 'A' and Stair 'B' are not operating. All other devices tested are operating properly. Restored system back to normal operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22375

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

EXIT!

LOCATIONS			DEVICES (MANUAL STATIONS)				
FLOOR	A	B	C		H/STA		UNITS
48	147	147			✓		2
47	080	081	082		✓		3
47	FITNESS CENTER			084	✓		1
46	079	078			✓		2
45	076	077			✓		2
44	074	075			✓		2
43	072	073			✓		2
42	071	070			✓		2
41	068	069			✓		2
40	067	066			✓		2
39	065	064	193		✓		3
39	AUDITH EXIT 194				✓		2
38	062	063	192		✓		3
37	060	061	145		✓		3
36	058	059	144		✓		3
35	056	057	195		✓		3
34	054	055			✓		2
33	051	050			✓		2
31	048	049			✓		2
30	046	047			✓		2
29	044	045			✓		2
28	042	043			✓		2
27	040	041			✓		2
27	040	EAST Corridor			✓		1
26	038	039			✓		2
26	038	EAST Corridor			✓		1
5	N/A				—		
4	033	034			✓		2
4	EAST HALL 202	ESCALATOR			✓		3
3	029	030	S.E 032-SW031		✓		4
3	N.W. ENTRANCE/EAST ... / CONF. EAST				✓	201	3

INVOICE TO:
7 W.T.C.
(SOLOMON SMITH BARNEY)
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES F. ROSARIO	F-S-7
	DATE SCHEDULED 2-07-01
CONTRACT # S/00 818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Sean O'Keefe.
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is ordered and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING Floor	A	B	TST	UNITS	
2	027	028	✓	2	Prev. Maint. Service Contract. TEST ACTIVATION OF MANUAL PULL STATIONS
1	S.E. DOOR 024		✓	1	on Floors (Listed) 48th FL 1st FL. -
1	S.W. DR 025		✓	1	ANNUNCIATION / ALARM, ACK / RESETS FCSTA. -
1	LOADING POST 026		✓	1	(PRINT OUT AVAIL.)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22374

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

LOCATIONS				DEVICES			
FLOOR	STAIR	EXIT		CABLE	M/STA	TST	
25		A		2	036	✓	
25		B		2	037	✓	
24		A		2	034	✓	
24		B		2	035	✓	
23		A		2	032	✓	
23		B		2	033	✓✓	
22		A		2	070	✓	
22		B		2	071	✓	
21		A		2	068	✓	
21		B		2	069	✓	
20		A		2	066	✓	
20		B		2	067	✓	
19		A		2	064	✓	
19		B		2	065	✓	
18		A		2	062	✓	
18		B		2	063	✓	
17		A		2	060	✓	
17		B		2	061	✓	
16		A		2	058	✓	
16		B		2	059	✓	
15		A		2	056	✓	
15		B		2	057	✓	
14		A		2	054	✓	
14		B		2	055	✓	
13		A		2	052	✓	
13		B		2	053	✓	
12		A		1	050	✓	
12		B		1	051	✓	
11		A		1	048	✓	
11		B		1	049	✓	
10		A		1	046	✓	
10		B		1	047	✓	
9		A		1	044	✓	
9		B		1	045	✓	
8		A		1	042	x ANN. ok.	
8		B		1	043	✓	
7		A		1	040	✓	
7		B		1	041	✓	
6		A		1	038	✓	
6		B		1	039	✓	

INVOICE TO: 7 W.T.C.
Silverstein Prop.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. Torres / A. Ziegler	F.S.D.	
	DATE SCHEDULED: 2-06-01	
CONTRACT #: 3/C00 818	TYPE OF SYSTEM: LSN2000	
FEE SERVICE #	P.O #	
CALL AUTHORIZED BY	PHONE	EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 (AM)	4:30 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe.

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING

Prev. Maint & Service Contract.
Test / Activation manual pull stations
on floor (above listed). – 25/6 Fl.
by exits to stairs A+B. – Annunciation
alarm / ack / reset at F.C. Sta. –
(Print out avail). –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22373

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR				TMPR		W/F	TEST CHECK
35	STAIR	'B'	RISER	2-132		2-100	✓
34	STAIR	'B'	RISER	2-131		2-099	✓
33	STAIR	'B'	RISER	2-130		2-098	✓
32	STAIR	'B'	RISER	2-129		2-097	✓
31	STAIR	'B'	RISER	2-128		2-096	✓
30	STAIR	'B'	RISER	2-127		2-095	✓
29	STAIR	'B'	RISER	2-126		2-094	✓
28	STAIR	'B'	RISER	2-125		2-093	✓
27	STAIR	'B'	RISER	2-124		2-092	✓
26	STAIR	'B'	RISER	2-123		2-091	✓
G	PUMP	RM.		2-113			
G	"	"		2-115			
G	"	"		2-116			
G	"	"		2-118			
G	"	"		2-117			
G	"	"		2-119			
G	"	"		2-120			
G	"	"		2-121			
G	"	"		2-122			
G	"	"		2-124			
G.	COMPRESSOR DRAIN			2-157			

INVOICE TO: 7 W.T.C.
N.Y.C.
J. CARRIGAN

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES	F.S.D.
F. ROSALIO	DATE SCHEDULED: 1-31-01
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE:
SERVICEMAN SIGNATURE: [signature] Fred Rosario

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME　　DATE　　TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT - PREV. MAINTENANCE CHECK/TEST'D WATERFLOW'S S/W & TAMPER'S ON STANDPIPE RISER 'B' STAIRCASE. - ON FLOOR'S ABOVE LISTED (PRINT OUT AVAILABLE). - SYSTEM FIRE COMMAND UNIT ACKNOWLEDGED ALARMS / RESET'S. - SEE ABOVE. - COMPLETE. -

(A) INACCESSIBLE　　(B) MISSING　　(C) DEFECTIVE　　(D) OTHER

FIRE SERVICE INCORPORATED 22372

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR		TAMPERS	W/F	TST CHECK	
47	STAIR 'B' RISER	2-155	2-112	✓	
46	WATER TANK RM	2-148			
	" "	2-149			
	" "	2-150			
	" "	2-151			
	" "	2-152			
	" "	2-153			
46	STAIR 'B' RISER	2-154	2-111	✓	
45	STAIR 'B' RISER	2-147	2-110	✓	
44	" "	2-142	2-109	✓	
44	" "	2-146			
43	" "	2-140	2-108	✓	
42	" "	2-139	2-107	✓	
41	STAIR 'B' RISER	2-138	2-106	✓	
40	" "	2-137	2-105	✓	
39	" "	2-136	2-104	✓	
38	" "	2-135	2-103	✓	
37	" "	2-134	2-102	✓	
36	STAIR 'B' RISER	2-133	2-101	✓	

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C
N.Y.C
M. J. Carrigan

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 1-30-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection services by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT. YEAR 2001 /W/FLOWS /TAMPERS SWITCHES CHECK /TEST ALARMS /ALERTS TO FIRE COMMAND UNIT. ACKNOWLEDGE - /RESET - (PRINT OUT AVAILABLE). - SEE BOOK LIST FLOORS 47 TO 36TH -
TO BE CONTINUED

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22212

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	B	RISER	CABLE	TAMPER	CABLE	W/F
25	B	"	2	122	2	090
24	B	"	2	121	2	089
23	B	"	2	120	2	088
22	B	"	1	150	1	103
21	B	"	1	149	1	102
20	B	"	1	143	1	101
20	B	"	1	144	—	—
20	B	"	1	145	—	—
20	B	"	1	146	—	—
19	B	RISER	1	142	1	100
18	B	"	1	141	1	099
17	B	"	1	140	1	098
16	B	"	1	139	1	097
15	B	"	1	138	1	096
14	B	"	1	137	1	095
13	B	"	1	136	1	094
12	B	"	1	135	1	093
11	B	"	1	134	1	092
10	B	RISER	1	133	1	091
9	B	*	1	132(C)	1	090
8	B		1	131	1	089
7	B		1	130	1	087

INVOICE TO: 7 W.T.C.
N.Y.C.
MR. J. CURRIGAN

SERVICEMAN ASSIGNED: J. Torres / F. Rosario	SEE AT JOB SITE: 7.5.7.
	DATE SCHEDULED: 1-24-01
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P O #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 (AM)	4:30 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Service Contract - Year 2001 (Tested activation) Alarm's / Reset's on Tamper's / Waterflow's S/W on (Listed above) Floor's 25 to 7: Note: 9th Fl Tamper S/W to check [illegible] to follow up - Continuity Test - Print out available. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

22211

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR			TTB'I		STRB. PNL'I	MAINT
6	'B' STAIRCASE		2			✓
	'B' COMM.			AFC 100	1	✓
5	'B' COMM			AFC 100	1	OUT SERV.
5	'B' Stain		1			✓
5	W. MER. (FAN RM)		2			✓
4	'B' COMM			AFC 100	1	✓
3	'B' Stain		1			✓
3	'B' COMM			AFC 100	1	✓
2	FREIGHT AREA Wall			AFC 100	1	✓
1	PUMP RM			AFC 100	1	✓
1	PUMP RM		1			✓
48	PLANT MER			AFC 100	1	✓
47	'A' STAIR Closet			AFC 100	1	✓
46	ELEV. S/D by SHUTTLE ELEVATOR (Solomon Fl.) Replaced/Installed. - old unit Broken Back in operation. -					
46	'B' COMM			AFC 100	1	✓

INVOICE TO: 7W. T.C.
N.Y.C.
M. J. CARRIGAN

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 1-23-01
CONTRACT #: S/C 00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O.#
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Contract Prev. Maintenance on Riser TTB'I Units & Strobe Lights Fire Alarms PNL'S. - Jobbattery's - Supervision / Door release voltages outputs. - Checked O.K. -
Also Repairs on 46 Fl. (Solomon Floor) Smoke Elev. Shuttle Detector Broken Replaced / Installed New Unit - (Bldg provided). - Also Rec 3 -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22210

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				TTB'S		PANEL STROS	MAINT
15	CORE HER			3	AFC 100	1	✓
14	CORE HER				AFC 102	1	✓
13	'B' COMM / 'C' ELECT.				AFC 100	2	✓
12	'B' COMM / CORE HER			3	AFC 101	2	✓
11	'B' COMM				AFC 101 (BATTERIES CHK.)	2	✓
10	N/A						
9	N/A.						
8	'B' COMM				AFC 101	1	✓
7	'B' COMM / CORE HER			1	AFC 100	1	✓
Lbby	(DCM - 40) F.C. STATION) CHECK #10 NETWORK / OPER. PLUGS ADJ.						

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES F. ROSARIO	DATE SCHEDULED 1-17-01
CONTRACT # S/C 00 818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P O #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection services during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: CONTINUE PREV. MAINTENANCE ON RISER'S TTB'S / STROBE PNL'S / SUBSYSTEM'S - DOOR RELEASES / POWER VOLTAGES READINGS CHECKS O.K. ALSO REPAIRING STROBE PNL ON 16 FL. - CKT / DISABLED DUE TO FAULTY. UNIT IN FIELD - TO BE ACTIV. / TRACKING. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22208

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / DEVICES

FLOOR				TTB'S	PANEL STROBE		MAINTN
24	CORE	HER		(3)	1	AFC100	✓
23	CORE	HER					
22	'B' COMM.				(2)	AFC100	✓
21	CORE	HER		(2)	1	AFC100	✓
20	CORE	HER			1	AFC100	✓
19	CORE	HER			1	AFC100	✓
18	CORE	HER		(2)	2	AFC100	✓
17	CORE	HER			1	AFC100	✓
16	CORE	HER			1	AFC100	✓
			(1) CKT DEFECT / UNIT REPAIRED				

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres F. Rosario	F.S.D.
	DATE SCHEDULED: 1-16-01
CONTRACT #: S/C00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O #: -
CALL AUHTORIZED BY	PHONE / EXT

☐ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Continue S/contract - Prev Maintenance on TTB'S Riser (Floor's above) / Listed Strobe PNL'S / Subsystem's Door Lobby power voltages outputs O.K. - Normal Level). - System ok back to operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

26939

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

PREVENTIVE MAINTENANCE CONTRACT

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			DEVICES: TTB'S		STROBE PNL	
38	FREIGHT AREA			(1) D3C3		(1) AFC100	
37	FREIGHT AREA.			(1) D3C3		(1) AFC100	
36	FREIGHT AREA					(1) AFC100	
	OPPOSITE/RECEPT (SOUTH)			(1) D1C1			
35	FREIGHT AREA.					(1) AFC100	
34	FREIGHT/AREA			(1) D3C4		(2) AFC100 PAD102	
	CONF RM EXIT					(1) PAD102	
33	FREIGHT/AREA			(1) D1C1 CORE HER.		(1) AFC100	
32	FREIGHT AREA			(1) D3C3		(1) AFC100	
31	FREIGHT AREA			(1) D3C3		(1) AFC100	
30	CORE HER			(1) D1C1		(1) FREIGHT AFC100 AREA.	
29	FREIGHT AREA					(1) AFC100	
28	FREIGHT AREA			(1) D3C4		(1) AFC100	
27	CORE HER.			(1) D3C3		(1) Tyco Spectra 3	
26	CORE HER			—		(1) Tyco Spectra 3	
25	CORE HER			—		(1) AFC100	

INVOICE TO:	7 W.T.C. N.Y.C.
SERVICEMAN ASSIGNED	J. Torres, F. Rossetti
SEE AT JOB SITE	F.S.D
DATE SCHEDULED	1-10-01
CONTRACT #	S/C 918
TYPE OF SYSTEM	LSN 2000
FEE SERVICE #	
P.O. #	
CALL AUTHORIZED BY	
PHONE	
EXT	

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:00 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Service Contract Maintenance on TTB's Riser's as listed on Floor's 38th thru 25th. — and strobe pnl's — Door Releases [illegible] Riser's check/voltage o.k. —
Also Ability Ally Check Floor Page/Radio 37th Fl o.k. — (Trouble Page 37 Fl) clear (Elect. Forgot Connecting Wire's Away). —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of [illegible] work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

97640

FIRE SERVICE INCORPORATED

SUBSIDIARY OF FIRECO INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
SKol-	5/C00898				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		1-9-01	AM	G. Torres / A. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800 AM	420 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 1-9-01

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name ____ Date ____

PROBLEM—AS DESCRIBED: Service Contract / Status Repairs / Purge / Pressuration — Floor's 25/26/24th Fl. — as / F.S.D. Requested — and 23 Fl. Pressuration. —

SERVICE PERFORMED: As per Contract check follow up on Purge / Pressuration Activation FAN'S Units Malfunctions as: 25 Fl. Purge. Pressuration 26' and 24' Floor's. — + Pressuration 25th Fl. Units. Repairing / Exchanges (1) 792 P.C. Board (output function) Down Loaded System — Units Back In Operation Check O.K. — 24 Fl. 778 Unit — Also check with Electrician Foreman / For Floor Page 3944 + Strobe Pull. — Check Defective Circuits / Short + Ground — All Corrected. — CKT's Normal. — Trouble Conditions Clear. — Back in Operation. —

WORK REMAINING: C/ Service Contract.

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

22207

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR						CHK	
47		(1)	TTB	DATA	3/4	✓	
47		(1)	TTB	DATA	1/2.	✓	
47		(1)	STROBE PNL			✓	
46		(1)	STROBE	PNL		✓	
45		(1)	TTB	DATA	3/4	✓	
45		(1)	TTB	DATA	1/2	✓	
45		(3)	STROBES	PNL'S		✓	
44		(1)	STROBE	PNL		✓	
43		(1)	STROBE	PNL		✓	
43		(1)	TTB	DATA	3/4	✓	
42		(1)	STROBE	PNL		✓	
42		(1)	TTB	DATA	3/4	✓	
42		(1)	TTB	DATA	1/2	✓	
41		(1)	STROBE	PNL		✓	
40		(1)	STROBE	PNL		✓	
40		(1)	TTB	DATA	3/4	✓	
39		(1)	STROBE	PNL		✓	
39		(1)	TTB	DATA	1/2	✓	

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 1-3-01
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature] [signature: F. Rosario]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

TIME | DATE | NAME

SERVICE PERFORMED & REMAINING: S/CONTRACT - CHECK / P.MAINTENANCE ON TTB'S RISER ON FLOOR'S 47-46-45-44-43-42-41-40-39 FL. -

ALSO CHECK FOR FLOOR PAGE SPK TROUBLE ON 39 FL. (FOREST ELECTRIC AND UNITS) (1) CKT GROUNDING / SHORTED - ALSO (1) STROBE CKT SHORTED. - ELECTRICIAN TO TRACE WIRING. - SPKR'S / STROBES ONLY (1) CKT EACH IN OPERATION. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERViCE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22206

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR		Purge		Press	Press		
7		✓		8	—		
8		✓		8	7		
9		✓		10	8		
10		✓		9	11		
11		✓		12	10		
12		✓		13	11		
13		✓		14	12		
14		✓		15	13		
15		✓		14	16		
16		✓		17	15		
17		✓		16	18		
18		✓		17	19		
19		✓		20	18		
20		✓		21	19		
21		✓		22	20		
22		✓		21	23		
23		✓		22	—		
24		✓		23	—		
25		—	N/G	—	—		
26		✓		27	—		
27		✓		28	26		
28		✓		27	29		
29		✓		28	30		
30		✓		29	31		
31		✓		30	32		
32		✓		31	33		
33		✓		32	34		
34		✓		33	35		
35		✓		36	34		
36		✓		37	35		
37		✓		38	36		
38		✓		37	39		
39		✓		38	40		
40		✓		41	39		
41		✓		40	42		
42		✓		43	41		
43		✓		44	42		
44		✓		43	45		
45		✓		44	46		
46		✓		45	—		
47		—		—	—		

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. Torres / F. Rosario	F-S.D	
	DATE SCHEDULED: 1-2-01	
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: LSN 2000	
FEE SERVICE #	P.O. #	
CALL AUTHORIZED BY	PHONE	EXT

☒ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service [redacted] and its employees regarding interruption of fire protection service during their service of the equipment.

NAME

DATE

TIME

SERVICE PERFORMED & REMAINING

As per Bldg Request - Check for operation on Purge / Press. Status indications at Console. Found missing pressurization on 23rd-24-25-26 as listed above. Also 47/46 as listed. — Manual Press. on floors 47/46 - 5th-3rd. Manual Purge on floors 4th-3rd-2nd-FP. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

See Print Out. —

FIRE SER'''CE INCORPORAT'' 93978

SUBSIDIARY OF FIR...INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WORLD TRADE CENTER
NEW YORK. NY

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.T		SCH UPS				J F.S.D
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		1-4-2001	AM			C. FORERO

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE	CUSTOMER SIGNATURE
1-4-2001	X
WILL RETURN ON	**SERVICEMAN SIGNATURE**
	C. FORERO

PROBLEM—AS DESCRIBED PREVENTIVE MAINTENANCE / SERVICE CONTRACT (UPS)

SERVICE PERFORMED Checked U.P.S System Took Readings (OK)
TOTAL Battery Voltage 140.5 V-DC, output HZ 62.2
L1=12.5 L=10.9 (OK) Checked and Cleaned Battery Rack #1 & #2
And Main Cabinet, Filters Mini-Fans (OK)
System operational.

OK Tony 1/4/01

WORK REMAINING

(Battery Rack = 30 pcs)

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ______ X Date ______

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

22204

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREAS	S/D	CHK	XTNAL	SENS TEST	CLEAN
45	FREIGHT ELEV	BLK	2	022	3.0	✓
	PASS ELEV	BLK	2	022	3.2	✓
	ELECT A	BLK	2	217	3.0	✓
	COMM A	BLK	2	217	3.0	✓
	ELECT B	BLK	2	217	2.8	✓
	TELE B	BLK	2	217	3.0	✓
	COMM B	BLK	2	217	3.0	✓
	'G' ELECTRIC	PEL3	4	083	2.8	✓
	SECURITY	PEL3T	4	083	2.8	✓
45	SHUTTLE ELEV	PEL3	4	011	3.0	✓
	KITCHN SHUTTLE ELEV	PEL3	4	012	3.0	✓
'D'	AREA STAIR	PEL3T	4	063	3.0	✓
	SHUTTLE FREIGHT KITCHN	PEL3T	4	019	3.0	✓
	AUDIO/VISUAL	PEL3T	4	091	3.0	✓
	AREA RISER SHAFT		4	089	3.0	✓
	EAST ELECT-F	PEL3T	4	059	3.0	✓
	DUCT DET. KITCHN.	EDWDS	4	094	3.2	✓
	D/DET. KITCHN	EDWDS	4	123	3.2	✓
	D/D. KITCHN TF45	EDWDS	4	092	3.2	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. N.Y.C. (Solomon Bros)

SERVICEMAN ASSIGNED: J. Torres, F. Rosario

SEE AT JOB SITE: F.S.D.

DATE SCHEDULED: 12/27-00

CONTRACT #: 5/C00 818

TYPE OF SYSTEM: LSN 2000

FEE SERVICE #

PO #

CALL AUTHORIZED BY

PHONE

EXT

☒ MAINTENANCE ☒ TEST

☐ JOB COMPLETE ☐ JOB INCOMPLETE

☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	9:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Silverstein

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: Prev. Maintenance & Sensitivity Test on Smoke Detection Units / Class 'E' Fire System. LSN 2000 Model — on 45th Fl. (Solomon Brothers) — System Full Working — Back to normal

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

22205

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR			Chamb	Cable	XTNDL	S/D	SENS TEST
Grnd	Ceiling			1	163	BLK	3.0
	"			1	163	BLK	3.2
	"			1	163	BLK	3.2
	"			1	163	BLK	3.0
G	Ceiling			1	163	BLK	3.2
	—				—		
G	Elev.	Machine Rm.	1		000	BLK	3.0
16'	Stby Pnl	Check / Normal Wiring / System Normal. —					

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 12-26-00
CONTRACT #: S/COD 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #: —	PO #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
12:00 AM	12:45 PM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Silverstein

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature] - [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME — DATE X — TIME

SERVICE PERFORMED & REMAINING: Prev. Maintenance / Silverstein Area — Ground Floor - High Ceiling Main Entrance (Using "Genie Boom") Smoke Detectors Class "E" Fire Alarm System. — System Ok / Normal. —
— Assisted by Bldg Silverstein Eng. "Kevin"
Also Checked 39th Fl Stdby Pnl Ckts — Field Wiring Shorted / Panel Remains Disabled. — (Floor Under Const / Renovation) Also Floor Page Spk Ckts. — Trouble Status;

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22203

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR			CABLE	XMDR	S/D	SENS TEST	CLEAN
3RD	SECURITY		3	048	PEC3	3.0	✓
	D/D AHU 34		3	042	EDWDS	3.2	✓
	KITCHEN SUPPLY						
	W. HER AREA		3	006	PEC3T	3.0	✓
	W. HER AREA		3	006	PEC3T	3.0	✓
3RD	W.HER D/D		3	040	EDWDS	3.2	✓
	W.HER D/D		3	041	EDWDS	3.4	✓
	W HER D/D		3	040	EDWDS	3.2	✓
	W.HER D/D		3	040	EDWDS	3.2	✓
3RD	CONF. AREA		1	077	DI-3	3.0	✓
	RECEPTION AREA		1	077	DI-3	3.0	✓
	ELEV. Lbby		3	029	PEC3	3.0	✓
2ND	ELEV Lbby		3	028	PEC3	3.0	✓
2ND	ELEV RH		3	005	PEC3T	3.2	✓
1ST	PLANT HER D/D		3	039	EDWDS	3.2	✓
	PLANT HER D/D		3	037	EDWDS	3.2	✓
	PLANT AREA		1	012	PEC3T	2.8	✓
30	COMMUNICATIONS B (AREA S/D)	BAK UNIT	1	184	RETESTED / CHECK O.K.		

INVOICE TO: 7 W.T.C. (SOLOMON BLDG)
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / J. ROSARIO	F.S.D
	DATE SCHEDULED 12-20-00
CONTRACT # S/C 00 818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.
NAME DATE TIME

SERVICE PERFORMED & REMAINING: PREVENTIVE MAINTENANCE / SENSITIVITY TEST ON SMOKE UNITS CLASS E SYSTEM - SEMI ANNUAL TEST COMPLETE. - AS PER CONTRACT ON AREA / FLOOR'S ABOVE LISTED. -
ALSO UNIT ON 30TH FL "B COMMUNICATION CLOSET" - RETESTED / CHECK FOR NORMAL OPERATION / ALL - O.K. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22184

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR			Cable	XTNDR	S/D	SENS TEST	Change
5TH	MAIN ELEV.		1	004	BRK	3.0	✓
	FREIGHT ELEV		1	004	BRK	3.2	✓
	ROTO CLONE		3	013	PEC3T	3.0	✓
	ROTO CLONE		3	013	PEC3T	3.0	✓
	ELECT 'A'		1	169	BRK	3.0	✓
	ELECT 'B'		1	169	BRK	3.2	✓
	ELECT 'C'		1	169	BRK	3.0	✓
	ELECT 'F'		1	169	BRK	3.2	✓
	TELEPH 'A'		1	169	BRK	3.0	✓
	COMM 'B'		1	169	BRK	3.0	✓
4TH	MAIN ELEV.		1	003	BLK	3.0	✓
	FREIGHT ELEV		1	003	BLK	3.2	✓
	CHEFS OFFICE		3	043	EMDH	3.0	✓
	ELEC 'B'		1	167	BLK	3.0	✓
	TELEPH 'A'		1	167	BLK	3.0	✓
	ELECT 'A'		1	167	BLK	3.0	✓
	ELECT 'G'		3	050	PEC3	2.8	✓
	TELEPH 'B'		1	167	BRK	3.0	✓
	COMM 'B'		1	167	BLK	3.0	✓

37TH Floor Page Trouble Status — Check
due to 'B' Loop Grounded. —
(Forest Elect. notified). —
to locate unit(s) grounded. —

INVOICE TO: 7 WTC
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Toney / F. Rosario	F.S.D
	DATE SCHEDULED: 12-19-00
CONTRACT #: SK00818	TYPE OF SYSTEM: LSN2000
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	930 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Preventive Maintenance / Servicing Smoke Detection on Solomon Smith Floors 5th/4th. — Areas as listed above) — Also 37TH SPACE Page Trouble Condition found) 'B' Loop Grounded — Elect. 'Forest' notified (with Weir Ridge) — to locate unit & correct. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

22183

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR				XTNSIL	SENS TEST	S/D.	cleaned
27	ELECT	A-B	(2)	2-178	3.0	BLK	✓
	CONN	A-B	(2)	2-178	3.0	BLK	✓
	TELEPH	A-B	(2)	2-178	3.2/3.0	BLK	✓
	CONN	C-D	(2)	2-177	3.0	BLK	✓
	ELECT	C-D	(2)	2-177	3.2/3.0	BLK	✓
	TELEPH	C-D	(2)	2-177	3.0/3.2	BLK	✓
	PASS ELEV.		(1)	2-004	3.0	BLK	✓
	FREIGHT ELEV		(1)	2-004	3.0	BLK	✓
	CORE HER D/D			2-237	3.4	SIF24	✓
	CORE HER D/D			2-237	3.2	SIF24	✓
27	LADIES BATH D/D R.			2-236	3.2	SIF-24	✓
	RET. D/D N/SIDE		(2)	2-236	3.2	SIF24	✓
26	ELECT	A-B	(2)	2-176	3.0	BLK	✓
	CONN	A-B	(2)	2-176	3.2	BLK	✓
	TELEPH	A-B	(2)	2-176	3.0	BLK	✓
	CONN.	C-D	(2)	2-175	3.0	BLK	✓
	ELECT	C-D	(2)	2-175	3.0	BLK	✓
	TELEPH	C-D	(2)	2-175	3.2/3.0	BLK	✓
	PASS ELEV.		(1)	2-003	3.0	BLK	✓
	FREIGHT ELEV		(1)	2-003	3.2	BLK	✓
	CORE HER D/D		(1)	2-235	3.4	SIF24	✓
	CORE HER D/D		(1)	2-235	3.4	SIF24	✓
	RET. D/D LADIES		(1)	2-234	3.2	SIF24	✓
	NORTH D/D RET		(1)	2-234	3.2	SIF24	✓
	SOUTH D/D RET		(1)	2-234	3.4	SIF24	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres	F.S.D.
F. Rosario	DATE SCHEDULED 12-13-00
CONTRACT # S/C 00 818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #

CALL AUHTORIZED BY | PHONE | EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) Silverstein
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signatures]

SERVICE PERFORMED & REMAINING Preventive Maintenance / Check Smoke Detectors Units Sensitivity + Maintenance by areas (above listed) on floors 27/26 floors System ck/reset. - Functions operations normal. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time [redacted] is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22182

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				Made	Sens Test	Clean	S/D
29	Elect	A-B	(2)	2-182	3.0	✓	BRK
	Teleph	A-B	(2)	2-182	3.2	✓	BRK
	Comm.	A-B	(2)	2-182	3.0	✓	BRK
	Elect	C		2-181	3.0	✓	BRK
	Elect	DW/D	(2)	2-181	3.2/3.0	✓	BRK
	Elect	6/Sec	(2)	3-007	3.0	✓	Pec 3
	Elect	'F'		3-014	3.2	✓	Pec 3
	Teleph	C-D	(2)	2-181	3.2/3.0	✓	BRK
	Comm	C		2-181	3.0	✓	BRK
	Pass/Freight Elev (2)			2-006	3.0	✓	BRK
	Shuttle Elev			2-080	2.8	✓	Pec 3
*	Core	Mer Area (3)		2-240	3.0	✓	Pec 3T
*	Core	Mer D/D	(2)	2-241	3.2	✓	SIF 24
29	W. Mer Area		(2)	3-000	3.0	✓	Pec 3T
	W. Mer Duct Det		(2)	3-032	3.2	✓	Edwds.
28	Elect	A-B	(2)	2-180	3.0	✓	BRK
	Comm	A-B	(2)	2-180	3.2	✓	BRK
	Teleph	A-B	(2)	2-180	3.0	✓	BRK
	Elect	C-D	(2)	2-179	3.0	✓	BRK
	Comm	C-D	(2)	2-179	3.2/3.0	✓	BRK
	Teleph/Rest C		(1)	2-179	3.0	✓	BRK
	Elect	D.W	(1)	2-179	3.0	✓	Pec 3T
	Elect	'F'	(1)	2-179	2.8	✓	Pec 3T
	Elect	6/[illegible]	(1)	2-180	3.0	✓	Pec 3
	Pass Elev		(1)	2-005	2.8	✓	Edwds
	Freight Elev		(1)	2-005	3.0	✓	Edwds
	Shuttle Elev		(1)	2-005	3.0	✓	Pec 3
	Core	Mer [illegible] Duct		2-239	3.2	✓	SIF 24
	Core	Mer Duct Det		2-239	3.2	✓	SIF 24
	W. Mer Area		(3)	3-057	3.0	✓	Pec 3T
28	W. Mer D/Det			3-047	3.2	✓	DT 3

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 12-12-00
CONTRACT #: S/K 00 818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature] [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Continue Prev. Maintenance clean/tested - sensitivity on smoke units floors 29 & 28 as listed. - System back/restored
(*) NOTE: 29 Fl Core Mer D/D (1) front unit u/w for service - danger high power line - [illegible] (1) area unit ceiling - Bldg to provide safe access for service / Core Mer. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22215

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR			COBN	XTNDR	S/D	SENS TEST	CHANGED
31	ELECT	A-B	2	187	BRK	3.0	✓
	TELEPH	A-B	2	187	BRK	3.2/3.0	✓
	COMM	A-B	2	187	BRK	3.0	✓
	ELECT	C-D	2	186	BRK	3.2	✓
	ELECT	D.W	2	186	BRK	3.0	✓
	ELECT	F	3	016	PEC 3	3.0	✓
	ELECT	G	3	009	PEC 3	2.8	✓
	SECURITY		3	009	PEC 3	3.0	✓
	COAT/COMM 'B'		2	186	BRK	3.0	✓
	COAT D.W.		2	186	BRK	3.0	✓
	PASS ELEV. MAIN		2	008	BRK	3.0	✓
	FREIGHT ELEV		2	008	BRK	3.0	✓
	SHUTTLE ELEV		3	025	PEC 3	3.0	✓
	CORE HER AREA (3)		2	244	PEC3T	3.0	✓
	CORE HER D/D (2)		2	245	SIF24	3.2	✓
	W. HER AREA (2)		3	002	PEC3T	3.0	✓
	W. HER D/D (2)		3	034	EDWDS	3.2	✓
	W. Supply CloSET (2)		2	186	BRK	3.0	✓
30	ELECT	A-B (2)	2	184	BRK	3.0	✓
*	COMM	A-B (2)	2	184	BRK	3.0	✓
	TELEPH	A-B (2)	2	184	BRK	3.0	✓
	ELECT	C-D (2)	2	183	BRK	3.2	✓
	ELECT	D.W	2	183	BRK	3.0	✓
	ELECT	F	3	015	PEC 3	3.2	✓
	ELECT	G/SEC. (2)	3	008	PEC 3	3.0/3.2	✓
	TEL/COMM	C (2)	2	183	BRK	3.0	✓
	COAT/TELEPH 'D'		2	183	BRK	3.0	✓
	PASS/FREIGHT ELEV (2)		2	007	BRK/DIB	3.0	✓
	SHUTTLE PASS ELEV.		3	024	PEC3	2.8	✓
	CORE HER AREA (3)		2	242	PEC3T	3.2	✓
	CORE HER D/D (2)		2	243	SIF24	3.2	✓
	W. HER D/D (2)		3	033	EDWDS	3.0	✓
	W. HER D/D		3	033	EDWDS	3.2	✓
	W. HER AREA		3	001	PEC3T	3.2	✓
	W. HER AREA		3	001	PEC3T	3.0	✓

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F. S. D.
	DATE SCHEDULED: 12-6-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: PREV MAINTENANCE SMOKE DETECTION UNITS LOCATED ON FLOORS 31 + 30 AS LISTED. - SYSTEM ACK/RESETED. - SENSITIVITY TEST CHECK. - AS ABOVE. -
NOTE: 30 FL. COMM 'B' CLOSET - BASE/TERMINAL S/D DEFECTIVE TO CHECK REPAIR. - TO CONTINUE —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22214

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR	AREA'S		CABK	XTUDR	S/D	SENS TEST	CLEANED
33	ELECT	A-B (2)	2	191	BRK	3.2	✓
	COMM	A-B (2)	2	191	BRK	3.0	✓
	TELEPH	A-B (2)	2	191	BRK	3.2/3.0	✓
	ELECT	C (2)	2	192	BRK	3.0	✓
	ELECT	D.W	2	192	BRK	3.2	✓
	ELECT	F	3	018	PEC 3	2.8	✓
	ELECT	G/SEC. (2)	3	011	PEC 3	3.0	✓
	TEL/SUPPLY	C	2	192	BRK	3.0	✓
	COAT	D/TEL	2	192	BRK	3.2	✓
	FREIGH	PASS (2)	2	010	BRK	3.0	✓
	SHUTTLE	ELEV.	3	027	PEC3	2.8	✓
	CORE MEC	AREA (3)	2	250	PEC3T	3.0	✓
	CORE MEC	D/D (2)	2	249	SIF24	3.2/3.0	✓
	W. MEC	AREA (2)	3	004	PEC3T	2.8	✓
	W. MEC	D/D (2)	3	036	EDWDS	3.2	✓
32	ELECT	A-B (2)	2	190	BRK	3.0	✓
	COMM	A-B (2)	2	190	BRK	3.2/3.0	✓
	TELEPH	A-B (2)	2	190	BRK	3.0	✓
	ELECT	C-D (2)	2	189	BRK	3.0	✓
	ELECT	D.W	2	189	BRK	3.2	✓
	ELECT	F	3	017	PEC3T	3.0	✓
	ELECT	G/SEC.	3	010	PEC 3T	3.2	✓
	TEL D/SUPPLY		2	189	BRK	3.0	✓
	COMM	C/SUPPLY	2	189	BRK	3.2	✓
	MAIN	FREIGHT ELEV	2	009	BRK	3.0	✓
	SHUTTLE	ELEV	3	026	PEC 3	3.2	✓
	CORE MEC	AREA (3)	2	248	PEC3T	3.0	✓
	CORE MEC	D/D (2)	2	247	SIF24	3.0	✓
	W. MEC	AREA (2)	2	003	PEC3T	3.2	✓
	W. MEC	DUCT D/D	3	035	EDWDS	3.4	✓
	W. MEC	D/D	3	035	EDWDS	3.2	✓
	TELEPH	C/COAT	2	189	BRK	3.0	✓

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED: J. TORRES / J. ROSARIO
SEE AT JOB SITE: F.S.D
DATE SCHEDULED: 12-5-00
CONTRACT #: S/C00 818
TYPE OF SYSTEM: CSW 2000
FEE SERVICE #
PO #
CALL AUTHORIZED BY
PHONE
EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE / SENSITIVITY TEST of SMOKE DETECTORS
CLASS E FIRE SYSTEM ON FLOORS 33 & 32ND AREAS ABOVE LISTED
SYSTEM CHK/RESET.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22371

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		CABLE	XTNDR	SENS TEST	CLEANED
35	ELECT A-B	(2)	2	196	3.0	✓
	COMM A-B	(2)	2	196	3.2/3.0	✓
	TELEPH A-B	(2)	2	196	3.2/3.0	✓
	ELECT C		4	049	3.2	✓
	ELECT D		4	049	3.0	✓
	ELECT F		4	049	3.2	✓
	ELECT F1		4	049	3.0	✓
	ELECT G/SEC.	(2)	4	073	3.0	✓
	FREIGHT ELEV		2	012	3.0	✓
	PASS ELEV MAIN		2	012	3.0	✓
	ELEV SHUTTLE		4	001	3.0	✓
	W. HEZ AREA		4	025	3.0	✓
	W. HEZ D/D		4	097	3.2	✓
34	ELECT A-B	(2)	2	194	3.0	✓
	COMM A-B	(2)	2	194	3.0	✓
(#)	TELEPH (A) B	(2)	2	194	3.0	✓
	ELECT C-D	(2)	2	193	3.2/3.0	✓
	ELECT DW		2	193	3.0	✓
	ELECT F		4	048	3.2	✓
	ELECT F1/AV ROOM		4	048	3.0	✓
	ELECT G/SEC.	(2)	4	072	3.0	✓
	TELEPH C-D	(2)	2	193	3.0	✓
	MEDICAL OPEN AREA		2	193	3.0	✓
	PASS ELEV. MAIN		2	011	3.0	✓
	FREIGHT ELEV.		2	011	3.2	✓
	SHUTTLE ELEV.		4	000	3.0	✓
	CORE HEZ AREA	(3)	2	252	3.2	✓
	CORE HEZ DUCT	(2)	2	251	3.2	✓
	W. HEZ AREA		4	024	3.2	✓
	W. HEZ D/D		4	096	3.2	✓
#	TELEPH (A) 34th FL.		N/A	(BLOCKED ENTRANCE)		
+	EXH. UNIT KITCHEN		N/A	PENDING +		

INVOICE TO: 7 W.T.C.
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 11-29-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☒ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME ____ DATE ____ TIME ____

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE ON SMOKE DETECTION ON FLOORS 35/34th AREAS LISTED ABOVE - SENSITIVITY TEST / UNIT ALARMED - RESET PROPERLY - SYSTEM BACK TO NORMAL -

NOTE: (1) UNIT D/D EXHAUST TO BE DONE. / 34th FL -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 22370

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S.		CABLE	XTNDR	SENS TEST	S/D
37	ELECT A-B	(2)	2	200	3.0	BRK
	COMM A-B	(2)	2	200	3.2/3.0	BRK
	TELEPH A-B	(2)	2	200	3.0/3.2	BRK
	ELECT C-D	(2)	2	199	3.0	BRK
	ELECT DW		2	199	3.2	BRK
	ELECT F		4	051	3.0	PEC3
	ELECT G/sec.	(2)	4	075	3.0	PEC3
	TELEPH C-D	(2)	2	199	3.0	BRK
	COMM C		2	199	3.2	BRK
	PASS ELEV.		2	014	3.0	BRK
	FREIGHT ELEV		2	014	3.2	BRK
	ELEV. SHUTTLE		4	003	3.0	PEC3
	CORE MEA AREA	(3)	2	258	3.2	PEC3T
	CORE MEY D/D	(2)	2	257	3.2	SIF24
	W. MEA AREA	(2)	4	027	3.0	PEC3T
	W. MEA D/D	(2)	4	099	3.2	EDWDS
36	ELECT A-B	(2)	2	198	~~BRK~~ 3.0	BRK
	COMM A-B	(2)	2	198	3.0	BRK
	TELEPH A-B	(2)	2	198	3.0	BRK
	ELECT C-D	(2)	2	197	3.0	BRK
	ELECT F		4	050	3.0	PEC3
	ELECT D.W		2	197	3.0	BRK
	ELECT G/SEC	(2)	4	074	3.0	PEC3
	TELEPH C.D (CONT)	(2)	2	197	3.2	BRK
	COMM Arrange C		2	197	3.0	BRK
	PASS ELEV		2	013	3.0	BRK
	FREIGHT ELEV.		2	013	3.2	BRK
	SHUTTLE ELEV.		4	002	3.2	PEC3
	CORE MEY AREA	(3)	2	256	3.0	PEC3T
	CORE MEY D/D	(2)	2	255	3.2	SIF24
	W. MEY AREA	(2)	4	026	3.2	PEC3T
	W. MEY ~~DUCT~~ DET		4	098	3.4	EDWDS
	W. MEY D/DET		4	098	3.2	EDWDS

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES	F.S.D
F. ROSARIO	DATE SCHEDULED 11.28-00
CONTRACT # S/C 00818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #

CALL AUTHORIZED BY | PHONE | EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE

SERVICE PERFORMED & REMAINING S/CONTRACT -
Prev. Maintenance Smoke Detection on Floors 37/36
as listed above & per Supple Solomon Brothers Floors -
Sensitivity Test & System Ock Inspected properly

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) O

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME
DATE
TIME

FIRE SERVICE INCORPORATED

22369

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS: Area's			DEVICES: CABK	XTNDR	S/D	SENS. TEST
39	ELECT	A-B	(2)	242	205	BRK	3.0
	COMM	A-B	(2)	242	205	BRK	3.0
	TELEPH	A-B	(2)	242	205	BRK	3.2/3.0
	ELECT	C		242	204	BRK.	
	ELECT	D.W.		242	204	BRK	
	ELECT	D1		242	204	BRK	
	ELECT	F		246	053	PEC3	
	ELECT	G/SEC	(2)	246	077	PEC3	
	FREIGHT ELEV			222	016	BRK	
	PASS ELEV. MAIN			242	016	BRK	
	ELEV. SHUTTLE			246	005	PEC3	
	RECPTN CEILING DUCT			242	254	Apllo	
	RECPTN CEILING DUCT			242	254	Apllo	
	RECEPTN " DUCT			242	254	Apllo	
	RECEPTN " DUCT			242	254	Apllo	
	RECEPTN " DUCT			242	254	Apllo	
	CORE HER AREA			243	006	Apllo PEC3	
	CORE HER AREA			243	006	Apllo PEC3	
	CORE HER AREA			243	006	PEC3	
	CORE DUCT DET.			243	007	Hochiki	
	CORE DUCT DET			243	007	Hochiki	
	WEST HER AREA			246	029	PEC3T	
	W. HER. DUCT DET.			246	101	EDW3S	
38	W HER CEILING AREA			246	026	PEC3T	
38	W. HER DUCT DET.			246	127	EDW3S	

AUDITORIUM (39)

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: T.W.T.C. N.Y.C. (SOLOMON/SMITH BARNEY)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES, F. ROSARIO	F.S.D.
	DATE SCHEDULED: 11-21-00
CONTRACT #	TYPE OF SYSTEM: LSN 500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keefe

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection served by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME   DATE   TIME

SERVICE PERFORMED & REMAINING

Prev. Maintenance Smoke Detection Units on 39 Fl As Listed Above and 38 Floor Auditorium Side W. HER Facility. - Sensitivity Tested. Sprays Detector Box to operating

(A) INACCESSIBLE   (B) MISSING   (C) DEFECTIVE   (D) OTHER

FIRE SERVICE INCORPORATED

22368

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR	AREA'S	CABLE	XTNDE	S/D	SENS
39/38	W. HER AREA. AUDIT	246	046	PEC3T	3.0
39/38	W. HER D/D (AUDIT)	246	127	EDWDS	3.2
	ELECT A-B (2)	242	202	BRK	3.0
	TELEPH A-B (2)	242	202	BRK	3.0
	COMM A-B (2)	242	202	BRK	3.0
	ELECT C-D (1)	242	203	BRK	3.0
	ELECT D. (1)	242	203	BRK	3.2
	ELECT D.W.	242	203	EDWDS	2.8
	ELECT F	246	052	PEC3	2.9
	ELECT G	246	076	PEC3	2.8
	SECURITY CLOSET	246	076	PEC3	2.8
	PASS ELEV. MAIN	242	015	BRK	3.0
	FREIGHT ELEV.	242	015	BRK	3.2
	ELEV. PASS SHAFE	246	004	PEC3	3.0
	CORE HER AREA	243	004	PEC3T	3.0
	" " "	243	004	PEC3T	3.0
	" " "	243	004	PEC3T	3.0
	CORE HER DUCT	243	005	HOCHIKI	3.2
	CORE HER DUCT	243	005	HOCHIKI	3.2
	W. HER AREA	246	028	PEC3T	3.0
38	W. HER DUCT	246	0100	HOCHIKI	3.2
			—	EDWDS	—

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 11-22-00
CONTRACT #	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM		

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keefe.
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME ____ DATE ____ TIME ____

SERVICE PERFORMED & REMAINING: Continue Service Contract
Prev. Maintenance on Smoke Detection Unit on 38th Fl. Above ...
System Act/Reset – Back to operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHE

FIRE SERVICE INCORPORATED 22366

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	AREA'S			CABLE	XTNDR	S/D	SENS
41	PASS ELEV			2	018	BRK	3.2
	FREIGHT ELEV			2	018	BRK	3.0
	PASS SHUTTLE			4	007	PEC3	3.0
	ELECT	A-B	(2)	2	209	BRK	3.0/3.0
	COMM	A-B	(2)	2	209	BRK CDWS	3.0/2.8
	TELEPH	A-B	(2)	2	209	BRK	3.0/3.0
	TELEPH	C-D	(2)	2	195	APLLO	2.8
	COMM	C-D	(2)	2	195	APLLO	2.8
	ELECT	C-D	(2)	2	195	APLLO	2.8
	'G'/SECURITY		(2)	4	079	PEC3	3.0/3.0
	H.E.R.	AREA	(2)	2	019	APLLO	2.8
	H.ER.	D/DET.	(2)	2	016	APLLO	3.0
40	PASS/~~FREIGHT~~			2	017	BRK	3.0
*	FREIGHT - (BURIED)			2	017	BRK	3.0
	SHUTTLE ELEV.			4	006	PEC3	2.8
	AREA ELECT	A-B	(2)	2	207	BRK	3.0
	COMM	A-B	(2)	2	207	BRK	3.0
	TELEPH	A-B	(2)	2	207	BRK	3.0
	TELEPH	C-D	(2)	2	206	APLLO	2.6
	COMM	C-D	(2)	2	206	APLLO	2.8
	ELECT	C-D	(2)	2	206	APLLO	2.6
	H.ER.	AREA	(2)	2	208	APLLO	2.8
	H.ER	D/D	(2)	2	015	APLLO	2.8
	FILE	RM AREA (Solomon)		4	252	APLLO	2.8
	FILE	RM AREA Solomon		4	251	APLLO	2.8
	'G' ELECT.			4	078	PEC3	2.8
	SECURITY			4	078	PEC3	2.8

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C.
N.Y.C.
(Solomon)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES F. ROSARIO	F.S.D.
	DATE SCHEDULED: 11-15-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: LSN 2000
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

TIME

DATE

NAME

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE SERVICE CONTRACT - ON SMOKE DETECTION CLASS 'E' SYSTEM ON FLOOR'S 41 + 40 (SOLOMON SMITH BARNEY) ON AREA (ABOVE LISTED). -
(*) SMOKE DETECTOR 40TH FREIGHT AREA 'BURIED' TOP CEILING ABOVE TILES

(A) INACCESSIBLE " (B) MISSING (C) DEFECTIVE (D) OTHER

— MUST BE EXPOSED. — (FREIGHT ELEV/SOLOMON) —

FIRE SERVICE INCORPORATED

22367

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				Cask	XTWDR	S/D	Sens.
42	Pass Elev.			2	019	BRK	3.0
*	FREIGHT ELEV (BURIED)			2	019	BRK.	3.2
	SHUTTLE PASS.			4	008	PEC3	3.0
	TELEPH A			2	211	BRK	3.0
	ELECT A			2	211	BRK	3.0
	COMM A			2	211	BRK	3.2
	COMM B			2	211	BRK	3.0
	ELECT B			2	211	BRK	3.0
	TELEPH B			2	211	BRK	3.2
	TELEPH C			2	210	Apllo	3.0
	ELECT C			2	210	Apllo	3.0
	COMM C			2	210	Apllo	2.8
	COMM D			2	210	Apllo	2.8
	ELECT D			2	210	Apllo	3.0
	TELEPH D			2	210	Apllo	2.8
	MER AREA			2	212	Apllo	2.8
	MER AREA			2	212	Apllo	2.8
	MER D/D			2	017	Apllo	2.8
	MER D/D			2	017	Apllo	2.8
	'B' ELECT.			4	080	PEC3	2.8
	SECURITY CLOSET			4	080	PEC3	3.0

'F' ELECT. → MISSING S/D / NO WIRING

(#) ASISTED FIRECOM KENNY WALL / RICK TAHINO ON CHECK'S FOR FAN'S SHUTDOWN / ACTIVATIONS ON 18 FL UNIT / ARCADE SYSTEM

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED 11-14-00
CONTRACT # S/C 00 818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. # LSN 2000
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	5:00 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING S/CONTRACT -
Quarterly PREV. MAINTENANCE on SMOKE DETECTION ZONE E SYSTEM. -
FIRECOM LSN 2000 MODEL. - SENSITIVITY TEST / SEMIANNUALLY. -
On Floor's Listed Above / Area. -
(#) NOTE: FREIGHT ELEV. S/D. (BURIED) Above Ceiling Tiles. - Must be Removed / Exposed Ceiling - (Forest Elect / Solomon). -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22365

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		DEVICES	Qty		S/D	Sens Test
46	Elect	B		2		BRK	
	Comm	B		2		BRK	
	Freight	Elev		2		BRK	
	Elect	D		4		PEC 3	
	Sec.	Closet		4		DI 3	
	Elect	A		1		BRK	
	Comm	A		1		BRK	
	Teleph	A		2		BRK	
	Teleph	D		2		BRK	
	Elect	D		2		BRK	
	Comm	D		2		BRK	
	Elev.	W Shuttle		4		PEC 3	
	Elev.	E Shuttle		4		PEC 3	
	Core HER	D/D (2)		2		Honey	
	Core HER	Area (2)		2		PEC 3 T	
	Elect	F		4		PEC 3	
	Elect	C		2		PEC 3	
	Kitchen Elev Shuttle			4		PEC 3	
43	Freight/Pass (2)			2		BRK	
	Elect	A+B (2)		2		BRK	
	Teleph	A+B (2)		2		BRK	
	Comm	A+B (2)		2		BRK	
	Elect	C		4		BRK	
	Security			4		PEC 3 T	
	Shuttle Elev			4		PEC 3 T	
	East HER	D/D		4		Apollo	
	East HER	Area		4		Apollo	

Note F Elect none S/D

Note Code 213 on 43rd in trouble

INVOICE TO: 7 WTC
NYC

SERVICEMAN ASSIGNED	SEE AT JOB SITE
F. Rosario / Zweck	F.S.D.
	DATE SCHEDULED: 11-8-2000
CONTRACT #: SC00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: Frank Rosario Zweck

SERVICE PERFORMED & REMAINING: Service Contract
Preventive Maintenance Check for Sensitivity Test on Smoke Detectors Units on 46th and 43rd Floors Solomon Smith Bros

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

SUBSIDIARY OF FIRECOM INC

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

55015

REPORT OF FIELD SERVICE

INVOICE TO:

SERVICED: 7 WORLD TRADE
NY NY

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
SHOP	SC 818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		11-1-00	AM	C Blyl

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE CONTRACT		

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
800 AM	900 AM	400 PM	430 PM					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 11-1-00

CUSTOMER SIGNATURE: [signature]

WILL RETURN ON:

SERVICEMAN SIGNATURE: Calvin Blyl

PROBLEM—AS DESCRIBED: SERVICE CONTRACT

SERVICE PERFORMED: ASSIST TECH with TESTing ON AREA SMOK DETECTOR, and DUCT SMOKE DETECTOR Floor WORK ON MAS 45, 44 and 46 Floor.

WORK REMAINING:

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

X ____ Date

FIRE SERVICE INCORPORATED

22361

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				CABK	XTNDL	S/D	SENS TEST
47	ELECT	A	CLOSET	2	222	BRK.	3.0
	ELECT	B	"	2	222	BRK	3.0
	ELECT	C	"	2	223	BRK	3.2
	ELECT	F	"	4	061	PEC3	3.0
	ELECT	G	"	4	085	PEC3	2.8
	TELEPH	B	"	2	222	BRK	3.0
	B STAIRWAY			2	221	EDWDS	3.2
	TELEPH	A	CLOSET	2	222	BRK	3.0
	COMM	D	"	2	223	BRK	3.0
	CUSHMAN OFFICE	AREA		4	113	EDWDS	3.0
	SHAFT/VERTICAL	CONVYR		4	068	EDWDS	3.0
	SECURITY CLOSET			4	221	EDWDS	3.0
	ELEVATOR SHUTRE			4	016	PEC3T	2.8
	WEST HER			4	069	EDWDS	3.0
	W. HER D/D. 47-1			4	115	EDWDS	3.0
	CORE HER	D/D		2/023	279	PEC3T	3.0
	CORE HER	AREA		2/022	278	PEC3	3.2
	CORE HEY	AREA		2 022/278		PEL3	3.2
	CORE HEY	AREA		2-022/278		PEL3	3.0
47	A STAIR/ELEV S/D			2	024	BRK	3.0
48	D/D.	EF	2	4	117	EDWDS	3.2
48	D/D	AC	1	4	118	EDWDS	3.0
48	D/D	AC	2	4	118	D138	3.2

UNITS REPLACED/due to FALSE ACTIVATION. – RETESTED BACK TO OPERATION. –

45 RETEST SPK - STROBE AS per FOREST ELECT. REQUEST. –

24 DOOR RELEASE CHECK AS PER BLD / ENTRANCE GLASE DOORS. –

INVOICE TO: 2 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Tocker / F. Rosario	F.S.D.
	DATE SCHEDULED: 11-01-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. # LSN2000
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☒ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT FA ABOVE LISTED FLOOR'S 47th
All Quar S/DETECTORS SENSITIVITY TEST / MAINTENANCE ALSO
TEST / Repair CHECK SPK / STROBE 45 Fl as Forest Request.
And 24 Fl. door release as per BLG Mgr. Requested. –
S/C to Continue –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Services Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Services Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME
DATE
TIME

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22363

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	PLANT			CABLE	XTNDR	S/D	SENS TEST
48	AREA CEILING			4	086	PEC3T	3.0
	"			4	086	PEC3T	3.0
	"			4	086	PEC3T	3.0
	"			4	086	PEC3T	3.0
	"			4	086	PEC3T	3.2
	"			4	086	PEC3T	3.0
48	D/DETECTOR 48-1 AHU			4	070	EDWIS	3.4
48	"	48-1 TE2		4	116	EDWIS	3.2
48	"	EF-1		4	118	EDWIS	3.4
48	"	EF-2		NO ACCESS	AT THIS	TIME	
48	"	AR 1			"	N/A	
48	"	AC 2			"	N/A	
44	ELECT	G		4	082	PEC3	3.0
	ELECT	A		2	215	BRK	3.2
	ELECT	B		2	215	BRK	3.0
	TELEPH	A		2	215	BRK	3.2
	TELEPH	B		2	215	BRK	3.0
	COMM	B		2	215	BRK	3.2
	COMM	A		2	215	BRK	3.0
	FREIGHT ELEV			4	021	BRK	3.0
44	PASS ELEV. MAIN			4	021	BRK	3.0
	ELEV. PASS SHUTTLE			4	010	PEC3	3.2
	ELEV PASS SHUTTLE			4	018	PEC3	3.2
	SECURITY CLOSET			4	082	PEC3	3.0
	W. HER AREA			4	034	PEC3T	3.2
	W. HER D/D			4	112	EDWIS	3.4

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C.
N.Y.C.
(Salomon Bros.)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.57
	DATE SCHEDULED: 10-31-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT)
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME
DATE
TIME

SERVICE PERFORMED & REMAINING: Preventive Maintenance / Sensitivity Test / Clean Smoke Units on 48th Fl. H.E.R / Plant - As Listed - (3) Duct Detectors Pending Service / Need Eng. Asist/Access. - Also Service 44th Areas / As Listed. - System Chk/Tested LSN 2000 Model. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SER'ICE INCORPORATED

97635

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
	SC 00818				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		10-30-00	AM	J. Torres / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8W	900	3:30	430					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

SERVICE DATE: 10-30-00

CUSTOMER SIGNATURE: [signature]

I&T COMPLETE ☐ CALL COMPLETE ☐

WILL RETURN ON

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED Service Contract / Maintenance — Repairs

SERVICE PERFORMED As per Contract check / Repairs on 16 Fl. Strobe panel AFC 100 Cole Ave. Traced ckt. - Unit Repaired back to normal. —
Also as per F.S.D. check / Repaired 35 Fl. AFC 100 Strobe Panel / Modification update P.C. Mother Board. — Rewired Back to operation. —
Also check 37 Fl. page trouble / strobe pnl trouble. — Condition due to Construction on floor / SPKR's / Strobes Ceiling being Removed / Relocated by Force Elect. / Solomon Brothers. —
System Ok / Back to operations —

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Date

Name

FIRE SERVICE INCORPORATED 97613

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7 W.T.C. N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.T.	S/C 60818				F.S.D

PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		10-25-00	AM.	J. Torres, A. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO.	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	900	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 10-25-00

CUSTOMER SIGNATURE: Sean O'Keeffe

WILL RETURN ON:

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED SERVICE CONTRACT — REPAIRS STATUS —

SERVICE PERFORMED AS PER CONTRACT CHECK TRACED 37th Fl. PAGE SPK TROUBLE. (Floor Under Renovation). — LOCATED OPEN Unit Dummy WIRES FIXED BY FOREST ELECTRIC. — 37 Floor Page Normalized. ALSO PROCEEDED TO ASIST FIRECOM TECH IGOR TO INSTALL DOOR Release Relay Supv. top TTB Unit Card #1, 47 Fl. RISER. — Unit Mounting Wiring Installed. — CHECK SUPV/RELEASE CP40 INDICATOR O.K. — ALSO PROCEEDED AFTER TO CHECK PRINTER UNIT — RA40 UNIT ON 44th Fl SECURITY OFFICE — WIRING RA40 to PRINTER — SOFTWARE P.C. DRIVER Unit S/W's POSITIONS — JUMPER 1 — AS PER ESPERS — ENG./FIRECOM. — UNIT DOWN/PRINT N/G. — NEED TO CHECK R.A40 UNIT- DB-25 CORRECTED PINS

WORK REMAINING (#R'S 25/17 O.K.) — ALSO CHECK FOR AUDIO RACK TROUBLE STATUS — TRACED to 796 P.C. CARD OPEN JUMPER AT OCP/ALL-11 TO AR4-9 Repaired O.K. — Trouble Audio Rack Cleared. —

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc representatives that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Date

Name

FCI 155
REV 8186

FIRE SERVICE INCORPORATED

22360

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

10/24/00

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	AREA'S			CABLE	ADDR	S/D	SENS TEST
3	TOP ESCALATOR			1	166	BRK	3.0
	TOP ESCALATOR			1	166	BRK	3.2
3rd	ELECT. 'D' (LOCKER'S)			1	165	BLK	3.0
	TEL/ELEC 'A'			1	166	BRK	3.0
	ELECT A			1	166	BLK	3.0
	COMM A			1	166	BRK	3.2
	COMM/TEL B			1	166	BRK	3.2
	COMM B			1	166	BRK	3.2
3	ELEV. LOBBY FREIGHT			1	002	BRK	3.0
	ELEV. LOBBY PASS (4-13/14-21)			1	002	BRK	3.2
	ELEV. HI RISE 22/28			1	166	BLK	3.0
	ELEV. HI RISE (36-45)			1	166	BRK	3.0
	ELEV. HI RISE (22-28)			1	002	BRK	3.2
3	SPT - SECURITY FSD			1	109	Apllo	3.0
Floor	TEST LIVE			Floor			
44	P.A. SPK TONES			29	P.A. SPK TONES		
43	"	"	OK	28		"	OK
42	"	"	OK	27		"	OK
41	"	"	OK	26		"	OK
40	"	"	OK	25		"	OK
39	"	"	OK				
38	"	"	OK				
37	"	"	OK				
36	"	"	OK				
35	"	"	OK				
34	"	"	OK				
33	"	"	OK				
32	"	"	OK				
31	"	"	OK				
30		"	OK				

INVOICE TO: 7W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres	F.S.D 10-24-00
F. Rosario	DATE SCHEDULED: 10-24-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500/2000 KSW
FEE SERVICE #	PO #

CALL AUTHORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE

SERVICE PERFORMED & REMAINING: Service Contract

Preventive Maintenance Smoke Sensitivity Test on Silverstein Spaces as Listed Above. - System Ack / Reset - Output Functions O.K. -
* NOTE: Also Traced and Repaired Tones / Audio Manual Evacuation on Floor's 25 thru 44 as listed. - (Defective No Tones on these floor's) Power Rack Audio. - Levels Adj. [illegible]

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER O.K.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

TIME
DATE
NAME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22362

REPORT OF FIELD SERVICE

LOCATIONS FLOOR	DEVICES						
7	AREA	S/D	PHOTO/HEAT		1-046	OPEN –	
	ANEX	DEVICE WIRING TO BE LOCATED					
7	DUCT	S/D	ANEX	1.047	OPEN –		
		DEVICE	WIRING	TO BE	LOCATED –		
7	FAN	SHUTDOWN	ANEX	1-050		OPEN	
		WIRING	/RELAY	TO BE	LOCATED –		
7	DAMPER	CONTROL/	ANEX		TO LOCATED –		
	WIRING / RELAY – 1.055			OPEN	EXT –		

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C (SILVERSTEIN)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres	F.S.D
F. Rosario	DATE SCHEDULED 10-23-00
CONTRACT # S/C 00 818	TYPE OF SYSTEM LSN 2000
FEE SERVICE #	P.O. #

CALL AUTHORIZED BY	PHONE	EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM/PM	2:30 PM	AM/PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME X

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING CHECK / AS per CONTRACT. Repairs per STATUS REPORT On 7th Fl. (CORE WEST) Area S/D (2) Units Located INSIDE Closet's - Units Dis-abled NO Power wiring open loop (From Previous). – Wiring need Tracing up Ceiling – Need to Locate Photo Heat Det/ANEX Cable - Under 046 Trouble & D/Det. ANEX (046) job appears to be Incomplete. FAN SHUTDOWN ANEX (1-050) And DAMPER CONTROL ANEX (1-055) 7th Floor – Also Started to Trace Audio / Tones Missing on Floors 35 up to Roof / Mike/Page OK.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

Microphone - page O.K. Entire Bld. – Tones Manual Evac - Defect/Missing Riser. – 1

FIRE SERVICE INCORPORATED

22386

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	AREAS			S/D	CABLE	XINDR	SENS
6	SWITCHGEAR			BRK	1	171	3.0
	"			BRK	1	171	3.0
	"			BRK	1	171	3.2
	"			BRK	1	171	3.2
	"			BRK	1	171	3.0
6	H.V. VAULT	(4)		BRK	1	171	3.0
	H.V. VAULT	(4)		BRK	1	171	3.0
	H.V. VAULT	(4)		BRK	1	171	3.0
	H.V. VAULT	(1)		BRK	1	171	3.2
5	STEAM EQ	FAN'S		Hochiki	1	223	3.4
	"		"	Hochiki	1	224	2.2
	"		"	Hochiki	1	228	3.4
	"		"	Hochiki	1	011	3.4
5	SWITCHGEAR		NORTH	BRK	1	170	3.0
	SWITCHGEAR		NORTH	BRK	1	170	3.0
	SWITCHGEAR		NORTH	BRK	1	170	3.2
	"		NORTH	BRK	1	170	3.2
	"		SOUTH	BRK	1	170	3.2
	"		SOUTH	BRK	1	170	3.0
	"		SOUTH	BRK	1	170	3.2
	"		SOUTH	BRK	1	170	3.0
	H.V. VAULTS	(6)		BRK	1	170	3.0/3.2
	H.V. VAULTS	(6)		BRK	1	170	3.0/3.2

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
SILVERSTEIN PROP.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES	F.S.D
F. ROSARIO	DATE SCHEDULED 10-16-00
CONTRACT # S/C00818	TYPE OF SYSTEM LX N2000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☐ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	330 PM	420 PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) Sean O'Keeffe.

CUSTOMER SIGNATURE

SERVICEMAN SIGNATURE [signatures]

SERVICE PERFORMED & REMAINING: CONTINUE S/CONTRACT SEMI-ANNUAL TEST SENSITIVITY AS LISTED ABOVE FLOOR'S 6 - 5 FLOOR'S - H.VOLTAGE VOLTAGE VAULTS & SWITCHGEAR AREA'S. SYSTEM ACK/RESETED AS OUTPUT FUNCTIONS O.K.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

22385

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS FLOOR	AREAS		DEVICES CABLE	XTNDR	S/D	SENS
9	ELECT	A	1	179	BRK	3.2
	COMM	A	1	179	BRK	3.0
	ELECT	A	1	179	BRK	3.0
	COMM	B	1	179	BRK	3.2
	ELECT	B	1	179	BRK	3.0
	TELEPH	B	1	179	BRK	3.2
	PASS ELEV		1	008	BRK	3.0
	ELECT	C	1	178	BRK	3.2
	COMM	C	1	178	BRK	3.2
	TELEPH	C	1	178	BRK	3.0
	FREIGHT ELEV		1	008	BRK	3.2
	RETURN D/D NORTH		1	238	HOCHIKI	3.4
	RETURN D/D EAST		1	238	HOCHIKI	3.2
	RET. D/D SOUTH		1	238	HOCHIKI	3.4
	—					
9	ELECT	D	1	178	BRK	3.0
	COMM	D	1	178	BRK	3.2
	TELEPH	D	1	178	BRK	3.0
	CORE MER D/D		1	239	HOCHIKI	3.2
	CORE MER D/D		1	239	HOCHIKI	3.2
2	TAMPER S/W		1	123	RESET	ALM
	(SPINDLE NOT SITTING PROPERLY)					—
37	TAMPER	S/W	(CLOSE VALVE / CONSTRUCTION)			
20	TAMPER		1	146	ALM	
	DUE TO NEED GROOVE/CUT ON SHAFT					
	AND ADJUSTMENT MECHANICALLY					

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Tower / F. Rosario	F.S.D
	DATE SCHEDULED: 10-11-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: EXN 2000
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keefe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Contract S/Contract — Repairs
Prev. Maintenance as per contract. Check / test sensitivity on devices above listed 9th fl. — Also check / repair on Tamper S/W floors 2nd / 20th – 37th as required. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22359

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'!		CABLE	XTNDR	S/D	SENS. TEST
8	COMM A		1	177	BLK	3.2
	ELEC A		1	177	BLK	3.0
	TELEPH A		1	177	BLK	3.0
	ELEC B		1	177	BLK	3.2
	COMM B		1	177	BLK	3.0
	TELEPH B		1	177	BLK	3.2
	COMM C		1	180	BLK	3.2
	ELECT C		1	180	BLK	3.0
	TELEPH C		1	180	BLK	3.2
	TELEPH D		1	180	BLK	3.0
	ELECT D		1	180	BLK	3.0
	COMM D		1	180	BLK	3.0
	PASS ELEV.		1	007	BLK	3.2
	FREIGHT ELEV		1	007	BLK	3.2
	CORE HER D/D		1	237	Hochiki	3.4
	CORE HGR D/D		1	237	Hochiki	3.4
	RETURN D/D NORTH		1	236	Hochiki	3.2
	RETURN D/D EAST		1	236	Hochiki	3.4
*	RETURN D/D SOUTH, Site		NO ACCESS.			—
12	STROBE PNL - Trouble / Repair (Loose Terminal P.C.)					
Lobby	F.C. STATION CXN 2000 Check'd. CP40 Unit —					

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED 10-4-00
CONTRACT # S/C00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) Sean O'Keeffe
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: As per contract check tested smoke detection on 8th Fl. area as listed. - Also repaired 12th Fl. strobe PNL's and check'd all equipment also on F.C. Sta. / CP40 Unit. / Reset system restored back to operation / ACK.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718)899-2311

52145

REPORT OF FIELD SERVICE

INVOICE TO	SERVICED
	7WTC. New York NY

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
SHOP	U.P.S 818				T.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		9/26/2000	AM	C. FORERO & C TABARES

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 AM	9.15 AM							

- ☐ MAT REQD
- ☐ OTHER
- ☐ PARTIAL
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE 9/26/2000

WILL RETURN ON

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE C. FORERO AND C TABARES

PROBLEM—AS DESCRIBED U.P.S MAINTENANCE / SERVICE CONTRACT (80 BATTERIES)

SERVICE PERFORMED TOOK READING CHECKED FANS, FILTERS AND CLEANED CABINET
EACH ALL BATTERIES TEST O.K U.P.S IT'S OPERATIONAL (OK)
TOTAL AMPS = 3
TOTAL BATTERY VOLTAGE 146.9 DC
FREQUENCY = (60) 62.5 HZ
LOAD 1 = 11.7
LOAD 2 11.5
INPUT V/AC 208/AC
OUTPUT 245

PREVENTIVE MAINTENANCE CONTRACT

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Date

Name

FCI 155

FIRE SERVICE INCORPORATED

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

76793

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7 W.T.C. N.Y.C

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
K.W	S/C 00 818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		9-27-00	A.M.	J. Torres [uncertain] / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ O.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800 Am	5:30 Pm						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 9-27-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED to perform S/contract - Test P. Authority : as Requested

SERVICE PERFORMED As F.S.D. Request Assisted G.C. = J.C. Heegan / elect. Contractor Solomon Brothers on Port Auth. Fire Inspection on Floors 31 - 32 + 36. Also Check 45 Fl standby lights. - NOTE: Ladies Bathroom Strobe Light Not operational - Also as per Contract Service Trouble Shooting 35 Fl. Sub-System Smoke panel Alarm. Wiring Termination Corrected back to Normal & Trouble status. due to Units Disabled / Floor under Renovation. - Also performed 'DRY' TEST on Area 1/0. [illegible] [illegible] Fan Room's on 43 and Area closet's 40 to 42nd Fl. - (See Print out) As Requested

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

22358

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREA'S		CHAN'L	XTNDR	S/D	SENS TEST GRAN
7TH	ELECT A		1	175	BLK	3.0
	COMM A		1	175	BLK	5.0
	TELEPH A		1	175	BLK	3.2
	PASS ELEV.		1	006	BLK	3.0
	FREIGHT ELEV.		1	006	BLK.	3.2
	COMM B		1	175	BLK	3.0
	ELECT B		1	175	BLK	3.0
	TELEPH B		1	175	BLK	3.2
	TELEPH C		1	174	BLK	3.0
	ELECT C		1	174	BLK	3.2
	COMM C		1	174	BLK	3.2
	TELEPH D		1	174	BLK	3.0
	ELECT D		1	174	BLK	3.0
	COMM D		1	174	BLK	3.0
7TH	CORE NER D/D		1	235	Hochiki	3.4
	CORE NER D/D		1	235	Hochiki	3.4
	RETURN D/D NORTH		1	234	Hochiki	3.2
	RETURN D/D SOUTH		1	234	Hochiki	3.4
3RD	AREA S/D (2)		1	166	BLK	
	UNITS CHECK / SENSITIVITY AS REQUIRED.					
	(3.2 RANGE NORMAL)					

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
SILVERSTEIN PROP.
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES E. ROSARIO	F.S.D.
	DATE SCHEDULED: 9-26-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #: -	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: AS PER CONTRACT SERVICED SMOKE DETECTORS ON 7TH FLOOR AREAS AS LISTED ABOVE / SENSITIVITY CHECK O.K. - SEE READINGS

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22356

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	Area	Loc		Cable	XINDR	S/D	Sens Test
11	Comm	A-B	(2)	1	182	BRK	3.2/3.0
	Elect	A-B	(2)	1	182	BRK	3.0/3.0
	Teleph	A-B	(2)	1	182	BRK	3.2/3.0
	Pass	Elev		1	010	BRK	3.0
	Freight Elev			1	010	BRK	3.0
	Comm	C		1	183	BRK	3.0
	Teleph	C		1	183	BRK	3.0
	Elect	C		1	183	BRK.	3.0
	Teleph	D		1	183	BRK	3.0
	Elect	D		1	183	BRK	3.2
	Comm	D		1	183	BRK	3.0
	Core Mech	D/D		1	243	Hochiki	3.4
LED *	Core Mech	D/D		1	243	Hochiki	3.2
	Return D/D	North		1	242	Hochiki	3.4
	Return D/D	South		1	242	Hochiki	3.2

35th Subsystem Operation Pnl Alarmed
Zone - TTB Terminal Check
Repair - O.K. - (4-163)
[illegible] F.S.D. - (XINDR - -

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 9-20-00
CONTRACT #: S/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: S/Contract - Routine S/C Prev. Maintenance on Smoke Detection Check on Area Locations (Above Listed.) - Floor 11th & Repairs on 35th Fl Subsystem Alarm. - Back to Operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22357

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS/CLOSET		CABLE	XTNDR	S/D	SENS TEST
14	COMM. A-B	(2)	1	188	BRK	3.0/3.2
	TELEPH A-B	(2)	1	188	BRK	3.0/3.0
	ELECT A-B	(2)	1	188	BRK	3.2/3.0
	PASS ELEV.	(1)	1	013	BRK	3.0
	FREIGHT ELEV	(1)	1	013	BRK	3.2
	ELECT C-D	(2)	1	189	BRK	3.2/3.0
	COMM C-D	(2)	1	189	BRK	3.0/3.2
	TELEPH C-D	(2)	1	189	BRK	3.2/3.0
	CORE HER D/D		1	249	HOCHIKI	3.4
	CORE HER D/D		1	249	HOCHIKI	3.4
	PLENUM RETURN SOUTH		1	248	HOCH	3.2
*	PLENUM RETURN NORTH		NO ACCESS - LOC. UNKNOWN			
12	ELECT A-B	(2)	1	184	BRK	3.0/3.2
	COMM A-B	(2)	1	184	BRK	3.2/3.0
	TELEPH A-B	(2)	1	184	BRK	3.0/3.0
	PASS ELEV	(1)	1	011	BRK	3.0
	FREIGHT ELEV	(1)	1	011	BRK	3.2
	CORE HER D/D	(2)	1	245	HOCHIKI	3.4/3.2
	RETURN PLENUM NORTH		1	244	HOCHIKI	3.2
	RETURN PLENUM SOUTH		1	244	HOCHIKI	3.2
	ELECT C-D	(2)	1	185	BRK	3.2/3.0
	COMM C-D	(2)	1	185	BRK	3.2/3.2
	TELEPH C-D	(2)	1	185	BRK	3.2/3.2

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	T.S.D
	DATE SCHEDULED: 9-19-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #:	P.O. #:
CALL AUTHORIZED BY:	PHONE: / EXT:

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keefe
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING

S/CONTRACT PREV. MAINTENANCE SMOKE DETECTION - SENSITIVITY TEST ON AREAS LOCATIONS (ABOVE LISTED) FLOOR'S 14 & 12TH FLOOR'S. — SYSTEM ACK/RESET - OUTPUT O.K. - BACK TO OPERATION. —

(*) NOTE: 14TH PLENUM RETURN D/D NORTH (NO ACCESS/LOCAT. UNK AS PREVIOUS LISTED). —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22355

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		PASK	YTUM	TST SENS	S/D
16	CORE HER	(1)	1	253	3.2	Hochiki
	CORE HER	(1)	1	253	3.4	Hochiki
	ELECT A-B	(2)	1	193	3.0	BLK
	COMM A-B	(2)	1	193	3.2	BLK
	TELEPH A-B	(2)	1	193	3.0	BLK
	PASS ELEV.	(1)	1	015	3.2	BLK
	FREIGHT ELEV.	(1)	1	015	3.2	BLK
	ELECT C-D	(2)	1	194	3.0	BLK
	COMM C-D	(2)	1	194	3.0	BLK
	TELEPH C-D	(2)	1	194	3.0	BLK
	PLENUM RET. D/D NORTH		1	252	3.4	Hochiki
	" RET-D/D SOUTH		NO ACCESS - U/L. -			
15*	CORE HER D/D	(1)	1.	251	3.4	Hochiki
*	CORE HER D/D	(1)	1	251	3.2	Hochiki
	COMM A-B	(2)	1	190	3.0	BLK
	ELECT A-B	(2)	1	190	3.2	BLK
	TELEPH A-B	(2)	1	190	3.2	BLK.
	TELEPH C-D	(2)	1	191	3.2	BLK
	ELECT C-D	(2)	1	191	3.2	BLK
	COMM C-D	(2)	1	191	3.2	BLK.
	PASS ELEV.		1	014	3.0	BLK
	FREIGHT ELEV		1	04	3.0	BLK.
	PLENUM RET. NORTH D/D		1	250	3.4	Hochiki
(*)	" RET. SOUTH	N/A	NO ACCESS -			

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. Prop. Silverstein Prop. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.I.
	DATE SCHEDULED: 8-30-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM / PM	8:00 AM	4:30 PM	AM / PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
(2)	I.C. Prem's - Bypass. -	

CUSTOMER NAME (PRINT): SILVERSTEIN.

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: S/Contract -
Prev. Maintenance on Smoke Detection System - Floors 16th & 15th as listed above - Units tested / sensitivity / cleaned - System A.K./Alerted outputs functions / Bypass check - O.K. -
Note: Core Her D/D (2) LED's N/G to repair / replace. (2) 15th Fl. -
Return South side @ 16th - 15th Fl. No access / As previous reported. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

(2) I.C.'s Prem's replaced on BPZ / Floors 20/14th Bypass defective / Corrected O.K. -

FIRE SERVICE INCORPORATED

76792

SUBSIDIARY OF FIRE[illegible]M INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
Silverstein Prop.
N.Y.C.

M. Carrigan

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
R.T.	S/C 00 818				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		8-29-00	AM	J. Torres J. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE ITEM

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00	4:30						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 8-29-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signatures]

PROBLEM—AS DESCRIBED S/Contract - Semiannual. - Repair -

SERVICE PERFORMED Performing Repairs on 44th Strobe Panel AFC100 - Main P.C. Board - Update changes - Intermittent signal trouble. - Replaced Part/Installing - Also as per Contract Maintenance on 13 Fl. all areas [illegible] Smoke Detectors Sensitivity Test: as:

Teleph Closet A+B	3.0 Sens	Test	XTNDR	BLK
Comm. " A-B	3.2 "	✓	1-186	BLK
Electric " A-B	3.0 "	✓	1-186	BLK
13th Fl — Comm " C-D	3.2	✓	1-187	BLK
Elect " C-D	3.0	✓	1-187	BLK
Teleph " C-D	3.2	✓	1-187	BLK.
~~Pass Elev~~	~~3.0~~	✓	~~1-012~~	~~BLK~~
Freight Elev	3.0	✓	1-012	BLK.
Core Mech (2) D/D	3.4	✓	1-247	Hochiki
Plenum Return D/D North	3.4	✓	1-246	Hochiki
Plenum Return D/D South	3.4	✓	1-246	Hochiki

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name ______ Date ______

FCI 155
REV 6/86

22354

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S		S/D	CABLE	XTNDR	SENS SET
17	PASS ELEV.		BLK	1	016	3.2
	FREIGHT ELEV		BLK	1	016	3.0
	ELECT. A		BLK	1	197	3.0
	COMM A		BLK	1	197	3.2
	TELEPH A		BLK	1	197	3.0
	ELECT B		BLK	1	197	3.0
	COMM B		BLK	1	197	3.2
	TELEPH B		BLK	1	197	3.2
	COMM C		BLK	1	196	3.0
	ELECT C		BLK	1	196	3.0
	TELEPH C		BLK	1	196	3.2
	ELECT D		BLK	1	196	3.0
	COMM D		BLK	1	196	3.0
	TELEPH D		BLK	1	196	3.2
	CORE MER		HOCHIKI	1	256	3.4
	CORE MER		HOCHIKI	1	256	3.4

17 PLENUM RET. D/D — N/A (4 2) —
(PLASTER CEILING – SOLID) —

PREVENTIVE MAINTENANCE CONTRACT

44th STROBE PNL: CHECK/REPLACED LOW BATTERIES OUTPUT — (2) NEW UNITS 12 VLTS – REPLACED O.K.

19th STROBE PNL: CHECK/TROUBLESHOOT (2) BATTERIES REPLACED LOW VOLTAGE OUTPUT (12 VLTS) O.K.

INVOICE TO: 7 W.T.C. SILVERSTEIN PROP. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.I
	DATE SCHEDULED: 8-23-00
CONTRACT #: S/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
4	12 VLT BATTERIES	69.95
—	(STROBES PNL'S) —	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: CONTINUING S/CONTRACT:
PREVENTIVE MAINTENANCE SMOKE DETECTION UNITS ON 17th FL. AREAS (ABOVE LISTED) CLASS E FIRE ALARM SYSTEM. — UNITS ON WORKING ORDER — PLENUM D/D N/A — AS PREVIOUS. — SYSTEM ACK/RESET. ALSO REPAIRED/REPLACED BATTERIES FOR STROBES PNL'S

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

On Floors 44th + 19th as listed —

FIRE SERVICE INCORPORATED   22353

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / DEVICES

FLOOR	AREAS		S/D	CABLE	XTNDR	TST READ
19th	ELEV PASS		BRK	1	018	✓3.2
	TELEPH A-B	(2)	BRK	1	201	3.0
	COMM A-B	(2)	BRK	1	201	3.0
	ELECT A-B	(2)	BRK	1	201	3.2
	CORE HER D/D		Hochiki	1	260	3.2
	CORE HER D/D		Hochiki	1	260	3.4
	ELEV FREIGHT		BRK	1	018	3.0
	PLENUM RET D/D South		Hochiki	1	259	3.4
	" RET D/D North		Hochiki	1	259	3.4
	ELECT C-D	(2)	BRK	1	200	3.2
	COMM C-D	(2)	BRK	1	200	3.0
19th	TELEPH C-D	(2)	BRK	1	200	3.0
18	ELECT A-B	(2)	BRK	1	199	3.2
	COMM A-B	(2)	BRK	1	199	3.0
	TELEPH A-B	(2)	BRK	1	199	3.2
	PASS ELEV.		BRK	1	017	3.0
	FREIGHT ELEV		BRK	1	017	3.2
	CORE HER D/D		Hochiki	1	258	3.4
	CORE HER D/D		Hochiki	1	258	3.4
	TELEPH C-D	(2)	BRK	1	198	3.2
	ELECT C-D	(2)	BRK	1	198	3.0
	COMM C-D	(2)	BRK.	1	198	3.0
	PLENUM RET D/D N.		Hochiki	1	257	3.4
18th	PLENUM RET D/D South		Hochiki	1	257	3.4

INVOICE TO: 7 W.T.C
SILVERSTEIN PROPERTIES
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Jones / F. Rosario	F.S.D
	DATE SCHEDULED: 8-22-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☐ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM) PM	430 AM (PM)	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME ______ DATE ______ TIME ______

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: SERVICE CONTRACT
Preventive maintenance on smoke detection units on floors (above list)
Class "E" fire equipment system - units in working order. - System [illegible]
Back to operation.
to be [illegible] by [illegible]. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22352

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		S/D	CABLE	XNDR	TST CHAN
20	PASS ELEV.		BLK	1	019	3.0
	FREIGHT ELEV.		BLK	1	019	3.0
	COMM A			1	203	3.2
	ELECT A			1	203	3.0
	TELEPH A			1	203	3.2
	COMM B			1	203	3.0
	ELECT B			1	203	3.2
	TELEPH B			1	203	3.0
	TELEPH C			1	202	3.0
	ELECT C			1	202	3.2
	COMM C			1	202	3.0
	ELECT D			1	202	3.0
	TELEPH D			1	202	3.2
	COMM D			1	202	3.0
	CORE HEX D/D		HOCHIKI	1	262	3.4
	CORE HEX D/D		HOCHIKI	1	262	3.2
	RETURN D/D NORTH		HOCHIKI	1	261	3.2
	RETURN D/D SOUTH		HOCHIKI	1	261	3.4
20	RETURN D/D EAST		HOCHIKI	3	045	

13 STROBE PNL AFC100 Replaced (2) Batteries 12 VLTS - Back up Power - OK -

44 STROBE PNL AFC100 TROUBLE STATUS (4-370) NEEDING (2) BATTERIES 12 VLT UNIT to be replaced -

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres F. Rosario	F.S.D.
	DATE SCHEDULED 8-16-00
CONTRACT # S/C 818	TYPE OF SYSTEM 8500
FEE SERVICE #	P O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	12 VLTS BATTERIES	69.95

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT) Sean OKeeffe.
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING: Conduct Scheduled Preventive Maintenance on Smoke Detection Alarm & Equipment on 20TH (as listed). - Also Repairs on 13th Floor / 44TH Pending - (2) Batteries Back up Unit Needed - 12 VLTS. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

22351

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				S/D	CABLE	XTNDR	TST SENS.
22	FREIGHT ELEV.			BRK	2	021	3.0
	PASS	ELEV.	21-3	BRK	1	021	3.0
	COMM	'A'		BRK	1	207	3.0
	ELECT	'A'		BRK	1	207	3.2
	TELEPH	'A'		BRK	1	207	3.2
	COMM	'B'		BRK	1	207	3.0
	ELECT	'B'		BRK	1	207	3.2
	TELEPH	'B'		BRK	1	207	3.0
	ELECT	'C'		BK	1	206	3.0
	TELEPH	'C'		BRK	1	206	3.0
	COMM	'C'		BRK.	1	206	3.2
	TELEPH	'D'		BRK	1	206	3.2
	ELECT	'D'		BRK	1	206	3.0
	COMM	D		BRK	1	206	3.0
	CORE	HER D/D		Hochiki	1	266	4.0
	CORE	HER D/D		Hochiki	1	266	3.8
(+)	RETURN SOUTH (LED)			Hochiki	1	265	3.8
	RET. NORTH			Hochiki	1	265	3.8
21	ELECT.	A-B	(2)	BRK	1	204	3.0/2.0
	TELEPH	A-B	(2)	BRK	1	204	3.2/3.0
	COMM	A-B	(2)	BRK	1	204	3.0/3.0
	ELECT	C-D	(2)	BRK	1	205	3.0/3.2
	COMM	C-D	(2)	BRK	1	205	3.0/3.0
	TELEPH	C-D	(2)	BRK	1	205	3.2/3.0
	CORE	HER D/D		Hochiki	1	264	3.4
	CORE	HER D/D		Hochiki	1	264	3.4
(+)	RETURN D/D	North LED		Hochiki	1	263	3.4
	RETURN D/D	South		Hochiki	1	263	3.4
	PASS ELEV.			BRK.	1	020	3.2
	FREIGHT ELEV			BRK	1	020	3.0

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.
FSD. J. Corrigan

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F Rosario	F.S.D.
	DATE SCHEDULED 8-15-00
CONTRACT # S/C00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Contract S/CONTRACT - PREVENTIVE MAINTENANCE
On Smoke Detectors All Areas Floors 22/21st Fl. -
(+) = 22nd + 21st Fl. LED's to replace (light indicator N/G). -
to Continue. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection served by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instituted and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME
DATE
TIME

FIRE SERVICE INCORPORATED

22350

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA		S/D	CABLE	XTNDR	TEST SENS
24	ELEV. Lobby Bas		BRK	2	001	3.0
	COMM	A	BLK	2	172	3.0
	ELECT	A	BLK	2	172	3.2
	TELEPH	A	BLK	2	172	3.0
	COMM	B	BLK	2	172	3.2
	ELECT	B	BLK	2	172	3.0
	TELEPH	B	BLK	2	172	3.0
	RETURN D/D NORTH		Hochiki	2	230	3.4
	RETURN D/D SOUTH		Hochiki	2	230	3.2
(*)	FREIGHT ELEV.		BRK	2	001	4.0 (*)
	COMM	C	BLK	2	171	3.0
	ELECT	C	BLK	2	171	3.2
(*)	TELEPH	C	BLK	2	171	3.4 (*)
	TELEPH	D	BRK	2	171	3.0
	ELECT	D	BLK	2	171	3.2
	COMM	D	BLK	2	171	3.0
	CORE	MEC. D/D	Hochiki	2	231	3.2
	CORE	MEC. D/D	Hochiki	2	231	3.4
47	E.M.R. AREA S/D (x2) UNITS RETESTED DUE TO SMOKE CONDITION AS BLD MANAG. REQUEST. – SENSITIVITY CHECK / NORMAL LEVEL (3.0 SENS. FIRING @ 3%). – UNITS DIDNT ACTIVATE POSSIBLE CAUSE TO AIR FANS BLOWING ON FLOOR PUSHING AIR / SMOKE AWAY FROM UNITS. SUGGESTED TO INSTALL ONE (1) EXTRA UNIT CENTER OF ROOM – DUE TO SIZE OF ROOM. –					
15	STROBE PANEL / Replaced Installed (2) NEW 12VOLTS BATTERIES. – PANEL / RESET BACK TO NORMAL. –					

INVOICE TO: 7 W.T.C. SILVERSTEIN PROP. N.Y.C. F.S.D.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / Carlos Tavares	8-9-00
	DATE SCHEDULED: 8-9-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME ____ DATE ____ TIME ____

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	12VOLTS BATTERIES	

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): Sean O'Keeffe.
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: Carrying Prev. Maintenance 24th Fl. All Area S/D. As Listed Above. SENSITIVITY TEST / CHECK. – NOTE: UNITS (*) TO BE RETESTED / SENS. TO BE TO HIGH AS PER LOCATION. – Also Check's done on 47th Fl as Bldg Request – & Repairs on 15th Fl. AFC. Strobe Panel's Batteries Replaced due to low output voltages. –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22349

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				S/D	CABLE	ADDR	TST SIGNL
25	ELECT	B		BLK	2	174	3.2
	COMM	B		BLK	2	174	3.0
	TELEPH	B		BLK	2	174	3.0
	PASS ELEV.			BLK	2	002	3.2
	FREIGHT ELEV			FDWDS	2	002	3.0
	COMM	A		BLK	2	174	3.2
	ELECT	A		BLK	2	174	3.0
	TELEPH	A		BLK	2	174	3.0
	ELEC	C		BRR	2	173	3.2
	COMM	C		BLK	2	173	3.0
	TELEPH	C		BLK	2	173	3.0
	TELEPH	D		BLK	2	173	3.0
	ELECT	D		BRK	2	173	3.2
	COMM	D		BLK	2	173	3.0
	RETURN D/D		NORTH	HOCHIKI	2	232	3.4
	RETURN D/D		SOUTH.	HOCHIKI	2	232	3.4
25	CORE	HER	D/D	HOCHIKI	2	233	3.4
	CORE	HER	D/D.	HOCHIKI	2	233	3.2
16	STROBE PNL	TROUBLE / CHECK'S DONE					AC.
			REPLACED / SIGNAL OUTPUT. — OK.				
15	STROBE PNL ; BATTERIES NEEDED (2) 12V						
	(BACK UP UNITS)						

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES C. TAVAREZ	F.S.D
	DATE SCHEDULED 8-8-00
CONTRACT # 3/C00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) Sean O'Keeffe
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE [signature] [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their [redacted]. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING
Century yearly (2) test sensitivity cleaning of smoke detectors units on 25th Fl. all addr as listed. — Also repairs on 16th + 15th Fl. strobe pnl's. — (2) batteries to be replaced on 15th Fl. (strobe pnl)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

90405

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED 7 W.T.C. N.Y.C

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
[illegible]	S/C 00 818				F.S.I.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		8-2-00	A.M.	J. Torres / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
5			387 bulbs (Bypass pnl's) -	N/C		

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8:00	4:30						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 8-2-00

CUSTOMER SIGNATURE: Sean O Keeffe

WILL RETURN ON:

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED Service Contract / Status Repairs - Troubleshooting - Trouble.

SERVICE PERFORMED As per Contract - Troubleshoot & Repairs done as:
45th Fl Tamper S/W 2-147 Transponder - Reset O.K.
45th Fl Tamper S/W 1-139 Transponder - Reset O.K..
34th Fl W/Flow S/W. 2-099. Transponder - Reset O.K -
20th Fl Tamper S/W 1-143 Transponder - Reset O.K -
All Units Located in 'B' Riser Stair Standpipe -
Also Replaced (5) Lamps/Bulbs at F.C. Station Bypass Panel's/Door's -
NOTE: Live Test/Solomon Floors 42+43rd A.C. Shutdowns - Postponed For New Date.

WORK REMAINING After Hours as per Mr. J. Marzano / Mr Campbell - Solomon Smith Barney + Cushman Wakefield - - Firedept will be Notified -

FCI 155
REV 6/86

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Date: X

Name:

FIRE SERVICE INCORPORATED

90404

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
SILVERSTEIN PROPERTIES –
N.Y.C.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
R.T.		S/C 00 818				F.S.7
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		8-1-00	AM			J. Torres. F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
15			7387 Lamps Display F.C.S.	N/C		

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8 00	4 30						

- ☐ MAT REQD
- ☐ OTHER
- ☐ PARTIAL
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 8-1-00
WILL RETURN ON:
CUSTOMER SIGNATURE: Sean O'Keeffe
SERVICEMAN SIGNATURE: [signatures]

PROBLEM—AS DESCRIBED SERVICE CONTRACT. –

SERVICE PERFORMED As per contract checked / repairs on 36th Fl. page. – Traced wiring found open wires (broken) by speaker/strobe (North west wall). – Also checked for intermittent 7232 P.O. at F.C. station 9th Fl. page / repaired I.C. 4512 replaced – back to operation. – Fire command station display lamps (burned out) replaced 7387 type – (11) units replaced) amber trouble status – (4) 7387 clear alarm status – replaced back to operation. – NOTE: As per conversation with Mr. Jerry Manzano CustomerWare[illegible] – Software [illegible] – B Schedule TEST / Live Shutdowns for 42 & 43 Fl. as requested by D. Trevino Fireman. – by tomorrow 8-2-00 / 9:00 AM. –

WORK REMAINING Continue S/C. –

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of protection service during their service of the equipment.

Date

Name

FIRE SERVICE INCORPORATED

90403

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO	SERVICED
	7 W.T.C. Silverstein Properties N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
L.T.	S/C 00 818				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		7-31-00	AM	J. Torres F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
2			(12 VLT) Batteries Strobe Pnl AFC100	6995		

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8 AM	9 AM	3:30 PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7-31-00

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keefe

SERVICEMAN SIGNATURE: [signatures]

PROBLEM—AS DESCRIBED S/Contract - Repairs -

SERVICE PERFORMED As per Contract / repairs done on 45th Fl. Strobe panel (3) panel AFC-100 intermittent - signal trouble - panel removed - changes done / updated - installed wiring back to operation, also batteries (2) (with 12 vlts. replaced). - Also as per status check repair on 22nd Fl. AFC 101 panel (2) - trouble condition South side - panel - - output voltage check anxiety - low - back to operation. - North side unit found loose connection on unit ceiling type - (East side) area - repairing back to operation. -
System ack / reset back to operation

WORK REMAINING Continue S/C.

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

22347

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		Cable	Number	DEVICES		
45	D/DETECTOR		4 -	125	= WIRES PULL OUT NOT LONGER - TTB		
45	D/DETECTOR		4 -	126	= WIRES PULL OUT - TTB NOT LONGER		
44	S/SYSTEM		4 -	228	WIRES PULL OUT - TTB NOT LONGER -		
45	FAN SHUTDOWN/ STATUS TF 45-2		4 -	345	WIRES PULL OUT NOT LONGER - TTB		
45	FAN SHUTDOWN STATUS		4 -	350	WIRES PULL OUT TTB NOT LONGER		
45	STAGE PULL/TRACK (PAD-2)		4 -	359	E.O.L. DEVICE WIRING. VALVE CORRECTED - (UNIT REWIRED) PAD-2		
43	TAMPER SW		4 -	439	WIRES PULL OUT - TTB NOT LONGER		

INVOICE TO: JWTC
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES H. ROSARIO	F.S.I
Zingera	DATE SCHEDULED 7-26-00
CONTRACT # S/C 00 818	TYPE OF SYSTEM 8000
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	930 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT) P. Kellar - (For J Corp)
CUSTOMER SIGNATURE (For J Corp)
SERVICEMAN SIGNATURE

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: As per Contract - Check / Troubleshooting / Correcting about circuits / TTB's check for wiring / pull out units not longer on field detector. - Also correcting wiring on PAD-2 strobe panel added on 45 Fl. Wrong end of line resistor (1.8) found on Relay Interface Terminal - placed 3.9K Ω EOL. & unit rewiring. - Check back to normal. - Also as per Mr. R. Wall Firecom Foreman reevaluated Fire Command Station Blue Prints / with existing labeling / wiring boards / function

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

- Copy returned to shop / Firecom -

FIRE SE~VICE INCORPORA ED 80966

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C. -

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.T.		S/C 00818				F.S.D
PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED			SERVICEMAN ASSIGNED
		7-25-00	A.M.			J. Torres F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7-25-00

CUSTOMER SIGNATURE: P. Kell - (Fr. J. Leung)

WILL RETURN ON:

SERVICEMAN SIGNATURE: [signatures]

PROBLEM—AS DESCRIBED S/Contract - Repairs Strobe Lights /Panel's - CKTS - 32 Fl. Ground Fault Condition. - 47 Fl. S/Detector Area. -

SERVICE PERFORMED Contract Repairs 32nd Fl. Strobe Lights CKT #1 - Trace Locating Negative Wire /Grounded on Existing Ceiling Speaker/Strobe White Unit. - - Which Were Removed to Install New Ceiling Tiles. - Corrected /Repaired CKT Back to Normal / Tested O.K. - Also Check 47 Fl. 'B' Communication Closet S/Detector Not Operating. - N/G. - Unable to Reach Unit due to Ceiling Pipes 'On Way' - Access Must Be Provided By Bld. - to Cut Hole on Wall near S/D. Top Portion in order to Remove Unit Check Base Wiring. -

WORK REMAINING Contract S/C.

FCI 155

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED

76790

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
DV.	S/C 00 818				

PHONE	EXT.	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		7-19-00	OH	J. Tornay / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F.C.I. NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	8AM	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7-19-00

WILL RETURN ON:

CUSTOMER SIGNATURE: P. Kelli (for J. Ceruzzi)

SERVICEMAN SIGNATURE: [signatures]

PROBLEM—AS DESCRIBED Service Contract -

SERVICE PERFORMED As per contract performed check / troubleshooting repairs on strobe panel unit on 32nd Fl. Check for CKT #1 ground fault. - E.O.L. placed at terminal. - (Further troubleshooting needed on CKT #1 in order to locate unit / unit grounded.) - Flow rehabilitation / Elev. - Also assisting tech Robert Dakosky checking activation / outputs 'DRY' - on floor's 40 thru 43 as requested Steve / R.W. - Firecom - See print out - Subsitted by tech. - Smoke det activating varied CKT'S / areas on floors -

WORK REMAINING Pending Contract -

FCI 155
REV 6/86

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FIRE SE[illegible]VICE INCORPOR[illegible]ED 76789

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C.

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	PO #	SEE AT JOB SITE
T.T.		SC00 818				F.S.D.
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		7-18-00				J. Torres A. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
800	900	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 7-18-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [illegible] (for J. Camp[illegible])

SERVICEMAN SIGNATURE: [signatures]

PROBLEM—AS DESCRIBED SERVICE CONTRACT. / STROBES LIGHTS [illegible] Trouble -

SERVICE PERFORMED As per Contract performed check's Repair on 15th Fl. Strobe panel Trouble activation. - AFC 110 Unit programed / P.C. and Batteries Replaced Voltage increase to 28.99 VDC. - BACKUP. - Normalized also Strobe light CKT #1 on 12th Fl panel - found their wiring loose. - Corrected. - Units back to operation. - AFC 101 #1 System Unit Back in operation. -

WORK REMAINING

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Name

Date

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22345

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR	FREIGHT AREA	TST CLEAN	TTB'S		STROBE
6	'B' COMM.	✓	TTB (1)		AFC 101 (1)
	CORE HER	✓	TTB (1) 23 C3		
	'B' STAIR		TTB (1) 21 C1		
5	W. HER (SCHM)	✓	TTB (1) DB C3		
	W. HER (SCHM)	✓	TTB (1) C3		
	'B' STAIR	✓	TTB (1) DIC1		
4	'B' COMM	✓	—		AFC 100 (1)
3	'B' STAIR	✓	TTB (1) DIC1		
	'B' COMM.	✓			AFC 100 (1)
2	FREIGHT AREA	✓			AFC 100 (1)
1	Lobby / BROWD	—			
	PUMP RM	✓	TTB (1) DIC1		
	PUMP RM	✓			AFC 100 (1)

3 F.C. STA. ByPass Pnl. Relamp. – Replaced (4) Lights –

INVOICE TO: W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres F. Rosario	F.S.D
	DATE SCHEDULED: 7-12-00
CONTRACT #: 5/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
3	Lamps 387 / ByPass Pnl.	N/C

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): P. Kinsel (for J. Comyn)
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection services by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection services during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: S/Contract.
Prev Maintenance on TTB'S Riser & Strobe Panel'S As Listed Voltages / Signal / Modules checked. Wiring Secured Batteries check. Ack / Resetting Back to operation –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22346

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS: AREAS	DEVICES: TTB'S	STROBS/PULL	TST CLEAN
11	'B' COMM		AFC 101 (2) (2) BATTERIES Replaced	✓
10	N/A	UNAVAILABLE	—	
9	N/A	UNAVAILABLE	—	
8	'B' COMM		AFC 101 (1)	✓
7	'B' COMM		AFC 101 (1)	✓
7	CORE HER	TTB (1) D1C1		✓
6	'B' COMM		AFC 100 (1)	
6	'B' STAIR	TTB (1) D1C1		✓
6	ENG. HEA RM	TTB (1) D3C3		✓
5	'B' COMM		AFC 100 (1) Disable out	
5	'B' STAIR	TTB (1) D1C1		✓
5	W. HER.	TTB (2) D3C3		✓
4	'B' COMM		AFC 100 (1)	✓
3	'B' COMM		AFC 100 (1)	✓
3	'B' STAIR	TTB (1) D1C1		✓
2	FREIGHT AREA		AFC 100 (1)	✓
1	PUMP RM	TTB (1) D1C1		✓
1	PUMP RM.		AFC 100 (1)	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 7-11-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	12 VOLT 7 AH BATTERIES	$69.75

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): PAT KINSELLA (For J. Cornyn)
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT –
PREVENTIVE MAINTENANCE ON TTB'S UNITS / STROBE PULL RISERS VOLTAGE / SIGNALS CHECKS – BATTERIES BACK UP'S REPLACED (2) (11th FL LISTED) – SYSTEM RESTORED BACK TO OPERATION

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22344

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				TEST CLEAN
FLOOR			TTB'S		STRB PNL	
20	CORE HER			(1)	AFC 100	✓
19	CORE HER			(1)	AFC 100	✓
18	CORE HEL	(2)	TTB DIC1	(2)	AFC 100	✓
		(1)	TTB D3C3			
17	CORE HER			(1)	AFC 100	✓
16	CORE HER			(1)	AFC 100	✓
15	CORE HEL	(2)	TTB DIC1	(2)	AFC 100	✓
		(1)	TTB D3C3			
14	CORE HEL			(1)	PAGZ	✓
13	'B' COMM			(1)	AFC 100	✓
	'C' ELECT			(1)	AFC 101	✓
12	CORE HER	(2)	TTB DIC1			
		(1)	TTB D3C3			
12	'B' COMM.			(2)	AFC 101	✓
⊛ 22	STROBE PNL "SOUTH"	(2) BATT. REPLACED -				12 VOLT 7 AMP

INVOICE TO: W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TOLLE / C. TABAREZ	F.S.I.
	DATE SCHEDULED: 7-5-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	BATTERIES 12 VOLT/7 AMP. (STROBE PNL).	@ 69.95
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN [illegible]
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature] [signature]

SERVICE PERFORMED & REMAINING: PREV. MAINTENANCE - AS PER CONTRACT CHECK TEST VOLTAGES / SIGNAL'S ON TTB'S RISERS & STROBE PANEL'S ON FLOORS ABOVE LISTED. - SYSTEM ACK/RESET - IN OPERATION
⊛ 22ND FL. (2) BATTERIES REPLACED. - OK. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22343

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		DEVICES	TTB'S		STROBE/PULL	TST CLEAN
26	CORE HER					(1) PYRO'S	✓
25	CORE HER					(1) AFC100	✓
24	CORE HER.		(2) TTB'S DIC (1) TTB DSC			(1) AFC100	✓
23	N/A AT THIS TIME (MAYOR'S OFFICE) -						
22	'B' COMM					(2) AFC101 * BATT. NEEDED (1) SEF.	✓
21	CORE HER		(1) TTB DIC (1) TTB DSCB			(1) AFC100	✓

INVOICE TO: TW.T.C N.Y.C

SERVICEMAN ASSIGNED: J. Torres / B. Tabares
SEE AT JOB SITE: F.S.D.
DATE SCHEDULED: 7-3-00
CONTRACT #: S/C 00 818
TYPE OF SYSTEM: 8500
FEE SERVICE #:
P.O. #:
CALL AUHTORIZED BY:
PHONE: EXT:

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	3:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: S/CONTRACT - PREV. MAINTENANCE CHECK ON TTB'S RISERS PANEL'S UNITS. - / STROBES LIGHTS PANEL'S ON FLOOR'S ABOVE LISTED. - VOLTAGE / SIGNAL'S READINGS TAKEN - / WIRING CHECKED - BATTERIES CHECKED.

AS: 22nd FL. STROBE PNL 'SOUTH' AFC101 NEEDS (2) BATTERIES 12 VLTS. 7.0 AMPS. - TO REPLACE. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instituted and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

22341

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS		DEVICES				
	'B' COMM. (CLOSET)			TTB'S		STROBES	TST CLEAN
31	'B' COMM		(1) TTB 22 A/B D3C3			AFC 100 (1)	✓
				(2) Battery Replaced (Disabled)			
30	'B' COMM				(1) AFC 100		✓
				(2) Batteries Replaced OK			
30	CORE	HEL	(1) TTB D1C1				
			#13 A/B - Key Chain Missing				
29	'B'	COMM.				AFC 100 (1) OK.	✓
28	'B' COMM.		(1) TTB D3C3 #21 A/B			AFC 100 (1)	✓
27	CORE	HEL	(1) TTB #12 A/B			Rico 3 ... OK.	✓
32	Floor Page / Back to Normal (Replaced) (Floor Renovated) ! -						

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / C. Tabary	F.S.D
	DATE SCHEDULED 6-28-00
CONTRACT # S/C 00 818	TYPE OF SYSTEM 8VT
FEE SERVICE #	PO #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	1:00 PM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
4	Batteries 12 Volts.	69.95
–	Strobes Panel (AFC 100)	

CUSTOMER NAME (PRINT) Silverstein
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities of the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING S/CONTRACT.

Check/Repair on TTB'S / Strobes Panel's or Prev. Maintenance as Items Listed Above also Batteries Replaced as Specified (Low Voltage) (2) Units On 30th Fl. Strobe Panel + 31st Fl. –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

NOTE: 31st Fl. Panel Disabled due to Shorted CKT 'A'/B on Strobes Loop's –

FIRE SERVICE INCORPORATED 22342

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			DEVICES			
				TTB'S		Strobe PUL	
35	'B'	COMM				STROBE PUL. ✓ (2) BATTERY Replace	
33	B	COMM				(2) BATT. Replace STBE PUL	
33	CORE	HET	(1) TTB D1C2 * KEY Cylinder Defect.			✓	
32	'B'	COMM	(1) TTB D3C3 # 23A/B			(1) Strobe PUL AFC 100 ✓	
31	'B'	COMM.				(1) STROBE PUL ✓ (2) BATT. Repl. AFC 100	
37	'B'	COMM				(1) AFC 100 STROBE ✓ (2) BATT. REPLACE) OK	
36	'B'	COMM				(1) STBE PUL ✓ (2) BATTERY Replace	

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. TORREY / C. TABALEP	FSI
	DATE SCHEDULED 6-27-00
CONTRACT # SKC00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
4	BATT. 12 VLTS.	69.95
	STROBE PUL (AFC 100)	

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING S/C.
PREV. MAINTENANCE CHECKS/REPAIRS ON TTBS & STROBE PULS ON FLOORS ABOVE LISTED. — BATTERIES REPLACED ALSO. — (LOW VOLTAGE) —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.
NAME DATE TIME

FIRE SERVICE INCORPORATED

22340

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR				TTB's		STROBES	TST MAINT
38	FREIGHT AREA			TTB 26A/B (1)		AFC 100 (1)	✓
	'B' COMM.			D3-4		* BATT. NEED	
37	FREIGHT AREA			TTB 25 A/B		AFC 100 (1)	✓
	'B' COMM			D3-4 (1)		* BATT. NEED	
36	FREIGHT AREA					AFC 100 (1)	✓
	'B' COMM					* BATT. NEEDED.	
36	SOUTH SIDE			TTB/OPP. South (1)			✓
	(WALL CLOSET)			D1-2 # 15 A-B			
35	FREIGHT AREA					AFC 100 (1)	✓
	'B' COMM					* BATT. NEEDED	
34	COPY PHOTO RM			TTB D3-4		AFC (100)	✓
	'B' COMM.			24A/B		AFC (102)	✓
	CONF/RM EAST					AFC (10)	✓
33	FREIGHT AREA					AFC 100	✓
	'B' COMM.					* BATT. NEEDED	
33	CORE	HER	*	TTB (N/A) PENDING. –			

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.I.
	DATE SCHEDULED 6-21-00
CONTRACT # S/C 00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

- [x] MAINTENANCE
- [x] TEST
- [ ] JOB COMPLETE
- [ ] JOB INCOMPLETE
- [ ] SYSTEM ON LINE
- [ ] SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [illegible signature]
SERVICEMAN SIGNATURE: [illegible signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT.
PREV. MAINTENANCE CHECK OF TTB'S WITH RISER'S & STROBE PNL'S
ON FLOOR'S 38/33 AS LISTED LOCATIONS. –
NOTE: BATTERIES (LOW VOLTAGE) NEEDED ON 38/37/36/35/33 FLOOR'S (SEE ABOVE)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

to be Continued. —

FIRE SERVICE INCORPORATED

: 22335

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR			TTB'S		STROBE PANEL	TST MAINT
44	FREIGHT ELEV. 'B' COMM			(1)	AFC 100	✓
43	FREIGHT AREA 'B' COMM		TTB 29A/B D3/4	(1)	PAD2 (SPRE)	(1) ✓ ✓
42	OPPSITE RECEPTN. CLOSET WALL		TTB D1/2	(1)		✓
	FREIGHT AREA 'B' COMM.		TTB D3/4 28A/B	(1) (1)	PAD2 (SPRE)	✓ ✓
41	FREIGHT AREA 'B' COMM.			(1)	PAD2 (SPRE)	✓
40	FREIGHT AREA 'B' COMM.		TTB 27A/B	(1) D3/4	PAD2 (1) (SPRE)	✓
39	FREIGHT AREA 'B' COMM.				AFC 100 PAD2 (100)	(1) ✓
39	OPP. AUDTH ENT. (WALL CLOSET)		TTB	(1) D1/2		✓

INVOICE TO: 2W.T.C.
N.Y.C.
J. CARRIGAN

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	FS-7
	DATE SCHEDULED: 6-20-00
CONTRACT #: S/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	810 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection services by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of all authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME
DATE
TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT.
(A) PREVENTIVE MAINTENANCE CHECK FOR OPERATING VOLTAGE LEVELS / WIRING ON TTB'S RISER & STROBE PANEL'S AS LISTED (ABOVE) — UNITS ALSO WERE DUSTED OFF / CLEANED. — OLD WIRES (DEVOTED) PULL OUT CABINETS. —
TO BE CONTINUED. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22339

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS	DEVICES
48	PLANT HER	STROBE PANEL CHECK. OK (KEY CYLINDER NEEDED)
		— 0 —
47	W. HER.	TTB DATA 3-4 #31A-31B ((EXISTING
47	A TENANT 'C' STEPS	TTB DATA 1-2 — STROBE PNL #19A-19B AFC 100
		— 0 —
46	'B' COMM. (FREIGHT)	STROBE PNL AFC 100 (1) CKT OUT TO REPAIR — KEY CYLINDER BROKEN.
		— 0 —
45	B COMM (FREIGHT)	TTB D3+4 #30A-30B STROBE PNL PID 2(1)
		TTB D1+2 (WALL CLOSET) #18A-18B AFC 100(1) AFC 100(1)
45	FREIGHT AREA/LOBBY	S/B REPLACED/INSTALLED (PREVIOUSLY REMOVED) CKT. 1 BACK IN OPERATION —

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.I.
	DATE SCHEDULED: 6-14-00
CONTRACT #: SC00818	TYPE OF SYSTEM: 3500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: S/CONTRACT. —
AS PER CONTRACT STARTED PREVENTIVE MAINT ON TTB'S (RISER) FROM 48 FL. TO 45 (SEE LIST ABOVE) — ALSO CHECK STROBES PNL'S ON FLOORS AS LISTED. — SYSTEM CHECK / RESTORED BACK TO OPERATION

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22338

REPORT OF FIELD SERVICE

LOCATIONS | DEVICES

FLOOR							
39	STROBE PNL TBLE - REPAIRS -						
	(2) 12VLTS BATTERIES REPLACED -						
	AFC 100 CKTS CHK O.K. -						
31	STROBE PANEL TBLE - REPAIRS						
	(2) CKTS A-B - DISABLED DUE TO						
	RENOVATION - TO RESTORE -						
22	STROBE PNL TBLE - SIGNAL TROUBLE						
	REPAIRS - O.K. -						
47	(3) STROBE'S LIGHTS S.W. CORNER CORRIDOR						
	WIRING CORRECTED & ALSO REPAIRED						
	BROKEN P.C. TERMINAL ON STROBE UNIT.						
	CHECK/TEST O.K. -						

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 6-13-00
CONTRACT #: S/C N 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	BATTERIES 12VLT.	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: [illegible] Position Check/Test Repairs on Strobes Units/Panel's as listed above - 39 Fl. (2) Batteries Replaced also at [illegible] Unit - Assisted F.S.D. as Requested Test Check of Door Release on 24 Fl. - System ok/Reseted back to operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representatives that it may be necessary to interrupt the fire protection services by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is intended and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SEᴦVICE INCORPORATᴱD

76788

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
RY.	S/COO 818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		6-7-00	AM	J. TORRES. / F. ROSARIO / D. MARCUS

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
1			HANUAL pull STATION HIRTANE	$40.00		
			— CAT # 47092-0260. —			
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	430						

- ☐ MAT RECD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR RECD
- I&T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 6-7-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED: S/CONTRACT / PREV MAINTENANCE. — [signature]

SERVICE PERFORMED: AS PER CONTRACT CHECK / any Repairs done on 37th Fl. Warden's Station — Call s/w Replaced. Audio O.K. — 36th Fl. Manual pull station 058 - 'A' STAIR Replaced Installed new One (old DEFECTIVE). — Check O.K. — 47th Fl Roof Plant Replaced Exchanged AFC 100 PANEL Strobe pnl (DEFECTIVE old one) Installed wiring Tested O.K. — Back in Operation. — Strobe panel Modification update performed by Firecom Eng. Dept. — 31st Fl Page / Speaker Trouble Condition due to open CKT / Found Electrician Forest Elect working on it. — Floor Under Construction — Secured Ok / Reset Back to Operation

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name ____ X ____ Date ____

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

76794

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C.
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.T.	S/C 00 818				F.S.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		6-6-00	A.M. –	J. Torres F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 6-6-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signatures]

PROBLEM—AS DESCRIBED S/CONTRACT. – MAINTENANCE.

SERVICE PERFORMED (1) As per F.S.D. Requested check Door Releases on 24th Fl. Facing Freight Door Entrance North (Wood) – NOT WIRING EXISTING FOR CLASS 'E' FIRE ALARM RELEASE FOR INTERCONNECTION. – AS Well South Pass Elev. Lby Entrance South Door (Wood). – 'A' STAIR EXIT (Solenoid) DEFECTIVE / STRIKE TO BE Replaced). – (BLD operating). –

2) Also As per Contract check strobe pull's on 41st Fl. – 40th Fl. 39th Fl for proper operation – Every O.K. – As well 16th Fl and 14th Floor. –

3) Repairs done on Warden's phone station 41st Fl. – (all s/w replaced) communication check OK

WORK REMAINING (*) 45th Fl. Elev. S/D 012 on alarm due to 'CUTTING' MACHINE (TILES INSTALLING) by ELEV. FREIGHT LBBY CAUSING S/D. ACTIVATION / UNIT REMOVED BLD. NOTIFIED / F.S.D. –

FCI 155
REV 8/96

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service, Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

X

Name

Date

FIRE SERVICE INCORPORATED

26065

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR				SPK/Page	W/STA	Strobe
32	Soloman Area			✓22	2	22
31	Soloman Area			✓25	2	25
30	Soloman Area			✓27	2	27
29	Soloman Area			✓22	2	22
28	Soloman Area			✓27	2	27
27	Soloman Area			✓29	2	29
26	Soloman Area			✓27	2	27
5	"		"	✓	5	
* 4	"		"	✓20	1	19*
* 3	Soloman Area			✓	—	-(2)9*
2	"		"	✓	—	4
1	"		"	✓	—	1
48	Roof/Plant			✓	✓	✓
* 47	Soloman Area			✓	✓	✓-(3)*

(Strobes light to be replaced N/G)

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	FSD
	DATE SCHEDULED: 6-3-00
CONTRACT #: 5/COO 818	TYPE OF SYSTEM: 8500
FEE SERVICE #: -	PO #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) [signature]
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: Per contract / Prev. Maintenance Test for proper operation activation of speaker audio/page - communications w/station phone + strobes lights on floors listed above (Soloman Area). — Also retested 48 + 47 floor's page speaker's / w/stations due to previous malfunction. - NOTE: 47 fl. strobe's 1/2 CKT active need's to be troubleshooted - 3rd fl. (2) lights

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

76786

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C
N.Y.C.

CALL AUTHORIZED BY	PHONE	EXT	CONTRACT #	DATE SCHEDULED	FEE SERVICE #	TIME SCHEDULED	FJ #	P O #	SEE AT JOB SITE	SERVICEMAN ASSIGNED
E.I.			5/C00818	5-31-00		A.M.			F.S.I.	J. Torres / F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			PREVENTIVE MAINTENANCE CONTRACT			

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	430						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 5-31-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED Service Contract / Prev. Maintenance / Repairs. —

SERVICE PERFORMED 14th Fl. Strobe panel Trouble 'A' CKT. — Traced Found Unit Strobe Light open wiring North Corridor. — Repaired / Tested Back to normal. — 16th Fl. Strobe panel (HER) Repaired. — P.O. modified updated — due to False Trouble Intermittent. — 'A' & 'B' CKT'S Restored Back to normal. — Test O.K. — 41st Fl. Strobe panel PAD-2 Trouble due to Battery discharged / to be Replaced For Next Visit. Also As per F.S.I. Requested Check For Door Release Activation on Several Locations as 3rd / 14th / 27th / 29 O.S. —

WORK REMAINING 41st Strobe panel Replace Batteries. —

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Date

Name

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED 76787

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C
N.Y.C.

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.V.	S/C 00 818				F.J.D.

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		5-30-00	AM	J. Torres, F. Rosario

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	800	4:30						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 5-30-00

WILL RETURN ON:

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED: S/CONTRACT REPAIRS. – PREV. MAINTENANCE. –

SERVICE PERFORMED: 45 Fl. STROBE PNL ~~[illegible]~~ AFC 100 Trou B LOOP- SHORT to BE TRACED STROBE LIGHTS / ZONE BYPASSED E.O.L. -TEMPORARILY. – N/ACCESS. – 41ST FL. REPLACED INSTALLED (2) NEW 12 VOLTS. BATTERIES PAD 2 PANEL (old dried out). – TROUBLE RESTORED BACK to NORMAL. – 47TH FL. CHECK TTB'S DATA 2 – For W/STATIONS & Floor PAGE INOPERABLE. – REPAIRED Mother Board / 792 P.C. – For OUTPUTS W/ PAGES. – WARDEN'S STATION REPAIRED CHECK O.K. – Floor PAGE CHECK O.K. – 48TH FL. ROOF PLANT REPAIRED W/STATIONS / P.A. PAGE. CHECK/TEST O.K. –

WORK REMAINING: CONTINUE S/C. REPAIRS. –

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned will notify the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary for the notification of the authorities and the protection during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name | Date

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

22337

REPORT OF FIELD SERVICE

LOCATIONS / DEVICES

FLOOR	'B' Riser			TMPR		RSET	CHK
47				155		OK	✓
46				154		OK	✓
45				147		closed	✓
44	'B'	Riser		146		OK	✓
44				146		OK	✓
44				142		OK	✓
43				140		closed	✓
42	'B'	Riser		139		closed	✓
41				138		OK	✓
40				137		OK	✓
39				136		OK	✓
38				135		OK	✓
37				134		OK	✓
36				133		OK	✓
35	'B'	Riser		132		OK	✓
34				131		OK	✓
33				130		OK	✓
32				129		closed	✓
31				128		closed	✓
30				127		closed	✓
29	B	Riser		126		OK	✓
28				125		OK	✓
27				124		OK	✓
26				123		OK	✓
7				130		OK	✓
6				129		OK	✓
5				128		OK	✓
3	'B'	Riser		126		OK	✓
3				125		OK	✓
2				123		OK	✓
2				123		OK	✓
1				123		OK	✓

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F-S-7
	DATE SCHEDULED: 5-24-00
CONTRACT #: 5/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING

Q I per F-S-7 request / Bldg retested check resets on tampers
S/W on 'B' Riser "As Listed" - (Print out presented). -
System ack / Inspected as requested. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection services during their service of the equipment.

NAME / DATE / TIME

FIRE SERVICE INCORPORATED

22336

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	'B' Riser		TMPR		RESET	CHK
25			122		OK	✓
24			121		OK	✓
23			120		OK	✓
22			150		OK	✓
21	'B' Riser		149		OK	✓
21	('B' E/WD)		149		OK	✓
20			146		OK	✓
20			145		OK	✓
20			144		OK	✓
20			143		OK	✓
19			142		OK	✓
			(ADDED)			
18	'B' Riser		141		OK	✓
17			140		O.K	✓
16			139		OK	✓
15			138		OK	✓
14			137		OK	✓
			(ADDED)			
13	'B' Riser		136		OK	✓
12			135		OK	✓
11			134		OK	✓
10			133		OK	✓
9	'B' Riser		132		OK	✓
8			131		O.K	✓
39	Strobe Pnl (Updated / Modified) AFC 100				OK	
	Back in operation. —					

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED: 5-23-00
CONTRACT #: 5/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☐ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instituted and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME — DATE — TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe.
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING
As per FSD Requested - do Prev. Maintenance Check for Alarm / Alm Reset above Floor's Tamper's Sw on Standpipe 'B' Riser (List / Print out Report).
Also - Repaired Strobe Pnl 39 Fl (Modification Update) Check out -

(A) INACCESSIBLE — (B) MISSING — (C) DEFECTIVE — (D) OTHER

Back in operation —

FIRE SERVICE INCORPORATED

22334

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR	AREAS		W/STA	SP/STD		P.A.
38	Solomon Bldg		2	18		OK
37	Solomon Smith		2	21		OK
36	Solomon Smith		2	22		OK
	'A' 'B' EXIT MANUAL P/I STA to Replace. - S/W BROKEN. -					
35	Solomon Smith B		2	14		O.K
34	Solomon Smith B		2	20		O.K
33	Solomon Smith B		2	23		OK.
	(1) Strobe (Light n/g) Front / w Hea- unit to replace -					

To be Continued

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7W.T.C Solomon Smith Barney N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / E. Rosario	F.S.D
	DATE SCHEDULED 5-20-00
CONTRACT # s/c 00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O #
CALL AUHTORIZED BY	PHONE / EXT

☐ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	11:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption [redacted] and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: As per Contract Continue Testing Activation of Audio page speakers and Strobes Lights on Solomon Smith Barney Floors as listed above. — Communications Warden's phone stations. - Units available for Test. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22333

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				CABK	ADDR	S/D	TST/CLEAN
3rd	ELECT A			1	166	BLK	
	ELECT B			1	166	D13	
	TELEP B			1	166	BLK	
	COMM A			1	166	BLK	
	COMM B			1	166	BLK	
	FIREM ELEV			01	002	BLK	
	~~[illegible]~~						
	SECURITY CLOSET			3	048	IEL3	
	KITCHEN Supply			3	042	EDWDS	✓
	WEST MEN AREA			3	006	PEC3T	✓
	WEST MEN AREA			3	006	PEC3T	✓
	WEST MEN D/D			3	040	EDWDS	✓
	WEST MEN D/D			3	041	EDWD	✓
	WEST MEN D/D Supply			3	040	EDWDS	✓
	WEST MEN D/D RET.			3	040	EDWDS	✓
3rd	RECEPTION AREA			1	077	D13	✓
	AREA S/D			1	077	D13	✓
	ELEV S/D Lbby			3	029	PEC3	✓
2nd	E.H.R.			3	005	PEC3T	✓
2nd	ELEV Lbby			3	028	PEC3	✓
1st	M.E.R. D/D			3	039	EDWD	✓
1	MEN AREA			1	012	PEC3T	✓
1	MEN D/D			3	037	EDWDS	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	I.J.D
	DATE SCHEDULED: 5-17-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: S/Contract Conducting Prev. Maintenance on Smoke Detecting Units Floors 3rd/2nd/1st As Listed Above (Division Smith Barney) only. — System OK / Service Completed / Back to Operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

22332

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR	AREA/CLOSET	CABLE	XTNDR	S/D	TST/CLEAN
5	ELECT A	1	169	BLK	✓
	ELECT B	1	169	BLK	✓
	ELECT C	1	169	BLK	✓
	ELECT F	1	169	BLK	✓
	TELEPH A	1	169	BLK	✓
	TELEPH B	1	169	BLK	✓
	COMM B	1	169	BLK	✓
	FREIGHT ELEV	1	004	BLK	✓
	MAIN/PASS ELEV	1	004	BLK	✓
	ROTO CLONE	3	013	PEC3T	✓
5	ROTO CLONE	3	013	PEC3T	✓
4	ELECT A	1	167	BLK	✓
	ELECT G	3	050	PEC3	✓
	TELEPH B	1	167	BLK	✓
	COMM B	1	167	BLK	✓
	FREIGHT ELEV.	1	003	BLK	✓
	PASS ELEV.	1	003	BLK	✓
	CHIEF OFFICE	3	043	EDWARDS	✓
	ELECT B	1	167	BLK	✓
4	TELEPH A	1	167	BLK	✓
44	SHUTTLE ELEV	4	018	PEC3	*
	MULTIPLE ALARMS (SENS UNIT/Replaced)				
	BACK IN OPERATION.				

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Turner / J. Rosario	FJD
	DATE SCHEDULED: 5/16/00
CONTRACT #: SC 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME ______ DATE ______ TIME ______

SERVICE PERFORMED & REMAINING: S/Contract - Preventive Maintenance on Smoke Detection on 5th/4th Fl. (Solomon floor) as listed. Also repairs on 44th Smoke Detector Unit (4-018) Elev. Bank Alarming Unit Removed (Replaced) for another existing unit back in operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

91421

#1

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7WTC NEW YORK
N.Y

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
SHOP	U.P.S = 818				F.S.P

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		5-16-00	AM	C. FORERO

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	9:30	11:30						
	AM	PM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 5-16-00

WILL RETURN ON:

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: CARLOS FORERO

PROBLEM—AS DESCRIBED U.P.S MAINTENANCE / SERVICE CONTRACT

SERVICE PERFORMED Checked U.P.S System, Took Reading for inputs - outputs, Battery Voltage, U.P.S System (OK) Also Cleaned Filters

Battery Amp .2

Total Battery Voltage = 140.7 V (#80 Batteries)

Out-Put HZ 62.5 HZ

Load #1 11.1

WORK REMAINING L #2 11.1

Output Voltage 246.V A/C

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

X

Name

Date

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

91680

SUBSIDIARY OF FIRECOM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
New York City

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
Ricky Trivino	UPS SC 818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		05/16/00		Marcos D

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
				PREVENTIVE MAINTENANCE CONTRACT		

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☐ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00	9:30	11:30						
Am	AM	AM						

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I&T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE

WILL RETURN ON

CUSTOMER SIGNATURE: Sean O'Keeffe

SERVICEMAN SIGNATURE: Marcos Llaverro D

PROBLEM—AS DESCRIBED

UPS Maintenance / service contract

SERVICE PERFORMED

Cleaned and checked UPS system for connections, input and output voltages readings and Battery voltages. Battery voltage range is 13.5 Vdc (normal range)

Battery Amp : 0.2 Amps
total battery voltage 140 Vdc
out put Hz : 62.5 Hz

WORK REMAINING

Load 1 : 11.0 Amps
Load 2 : 11.0 Amps
out put voltage 246 VAC

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.

The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name X Date

FIRE SERVICE INCORPORATED

22330

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				W/STA	SP/STROBES		P.A.
48	Solomon Smith B.			2	6		N/G.
47	"	"		2	17		N/G.
46	"	"		2	23		OK.
45	"	"		1	54		O.K
44	"	"		1	16		OK
43	"	"		1	OUT (UNDER CONST).		OUT
42	"	"		2	20		O.K
41	"	"		2	23		O.K.
40	"	"		2	22		OK
39	"	"		2	24		O.K.

To be continue

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C. Solomon Smith Barney N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED 5-13-00
CONTRACT # S/C 00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. # -
CALL AUTHORIZED BY	PHONE / EXT

☐ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 (AM)	430 (PM)	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

TIME / DATE / NAME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) Douglas Mazzone
CUSTOMER SIGNATURE [signature]
SERVICEMAN SIGNATURE [signature]

SERVICE PERFORMED & REMAINING S/CONTRACT - CHECK TESTED AUDIO/VISUAL ACTIVATION ON SPEAKER'S / STROBES LIGHTS BY ALARMING M/STATION ON FLOOR'S 48 TO 39° AS LISTED. ALSO TESTED COMMUNI-CATION DEVICES - WARDEN'S PHONES. -

NOTE: SPKR'S / page floor's 48 (PLANT + 47 E) DEFECTIVE N/G - TO BE TROUBLESHOOTED - REPAIR AUDIO/PAGE CKTS. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21309

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA		CABL	XTNDR	S/D	TST CLEAN
35	ELECT A-B	(2)	2	196	BLK	✓
	TELEPH A-B	(2)	2	196	BLK	✓
	COMM A-B	(2)	2	196	BLK	✓
	ELECT C-D	(2)	4	049	EDW/BLK.	✓
	ELECT F		4	049	BLK	✓
	ELECT F1		4	049	PEC3	✓
	ELECT G		4	073	PEC 3	✓
	SECURITY		4	073	PEC3	✓
	ELEV. PASS		2	012	BLK	✓
	FREIGHT ELEV		2	012	BLK	✓
	ELEV. SHUTLE		4	001	PEC 3	✓
	W. HER AREA		4	025	PEC3T	✓
	W. HER D/D.		4	097	EDWDS	✓
34	ELECT A-B	(2)	2	194	BLK	✓
	ELECT C-D	(2)	2	193	BLK	✓
	TELEPH A-B	(2)	2	194	BLK	✓
	TELEPH C-D	(2)	2	193	BLK	✓
	COMM A-B	(2)	2	194	BLK	✓
	COMM C		2	193	BLK	✓
	ELECT DW		2	193	BLK	✓
	ELECT F		4	048	PEC3	✓
	ELECT F1 A/C ROOM		4	048	PEC 3	✓
	ELECT G		4	072	PEC 3	✓
	SECURITY		4	072	PEC 3	✓
	FREIGHT ELEV		2	011	BLK	✓
	ELEV. LOBBY		2	011	BLK	✓
	ELEV. SHUTTLE		4	000	PEC 3	✓
	CORE HER AREA	(3)	2	252	PEC3T	✓
	CORE HER D/D.		2	251	HOCHIK	✓
	CORE HER D/D.		2	251	HOCHIK.	✓
	W. HER AREA		4	024	PEC3T	✓
	W. HER D/D		4	096	EDWDS	✓
	KITCHEN EXH.		4	121	EDWDS	✓

INVOICE TO: 2 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 4-19-00
CONTRACT #: S/00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: S/CONTRACT.
Conducting Prev. Maintenance Smoke Detection on Floors 35th/34th
Solution) - Areas listed - System ACK/RESET - Ind parts
Checked D.R. / Signal's / Page O.K. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representatives that it may be necessary to interrupt the fire protection services by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

21311

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR				Cable	xmodule	S/A	Test
33	Elect	A-B	(2)	2	191	BLK	✓
	Teleph	A-B	(2)	2	191	BRK	✓
	Comm	A-B	(2)	2	191	BLK	✓
	Elect	C-D	(2)	2	192	BLK	✓
	Teleph	C-D	(2)	2	192	BRK	✓
	Comm	C		2	192	BLK	✓
	Elect	D.W.		2	192	BLK	✓
	Elect	F		2	018	PEC3	✓
	Elec 'G' Closet			3	011	PEC3	✓
	Security Closet			3	011	PEC3	✓
	Elev Lobby Pass			2	010	BLK	✓
	Freight lobby Elev			2	010	BLK	✓
	Shuttle Elev.			3	027	PEC3	✓
	Core Mev Area		(3)	2	250	PEC3T	✓
	Core Mev D/D		(2)	2	249	Hochiki	✓
	W. Mev. Area		(2)	3	004	PEC3T	✓
	W. Mev D/D		(2)	3	036	Edwards	✓
32	Pass Elev.			2	009	BLK	✓
	Freight Elev.			2	009	BRK	✓
	Elect	A-B	(2)	2	190	BLK	✓
	Teleph	A-B	(2)	2	190	BRK	✓
	Comm	A-B	(2)	2	190	BRK	✓
	Elect	C-D	(2)	2	189	BLK	✓
	Teleph	C-D	(2)	2	189	BLK	✓
	Comm	C		2	189	BLK	✓
	Elect	D.W.		2	184	BLK	✓
	Elect	F		3	017	PEC3	✓
	Elect	G/Sec	(2)	3	010	PEC3	✓
	Shuttle Elev			3	026	PEC3	✓
	Core Mev Area		(3)	2	248	PEC3T	✓
	Core Mev D/D		(2)	2	247	Hochiki	✓
	W. Mev Area		(2)	3	003	PEC3T	✓
	W. Mev D/D		(2)	3	035	Edwards	✓

INVOICE TO: 2 W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. Torner / F. Rosario	F.S.D.	
	DATE SCHEDULED: 4-25-00	
CONTRACT #: 5/00 818	TYPE OF SYSTEM: 8500	
FEE SERVICE #	P.O. #	
CALL AUTHORIZED BY	PHONE	EXT
☒ MAINTENANCE	☒ TEST	
☐ JOB COMPLETE	☐ JOB INCOMPLETE	
☐ SYSTEM ON LINE	☐ SYSTEM OFF LINE	

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection services by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

TIME
DATE
NAME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: S/C
Prev. Maintenance Contract testing S/D Elect rm on (Polaris) floors as schedule - all areas tested listed / closets. Mer's - as listed.
System o.k. / Restored to proper operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21310

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	PLANT			CABLE	XNDE	S/D	TEST
48	ROOF						
	CEILING			4	086	PEC3T	✓
	CEILING			4	086	PEC3T	✓
	CEILING			4	086	PEC3T	✓
	CEILING			4	086	PEC3T	✓
	CEILING			4	086	PEC3T	✓
	CEILING			4	086	PEC3T	✓
48	DUCT	S/D		4	070	EDWDS	✓
48	DUCT	S/D		4	116	EDWDS	✓
48	DUCT	S/D		4	118	EDWDS	✓
48	DUCT	S/D		4	117	EDWDS	✓
48	DUCT	S/D		4	118	EDWDS	✓
48	DUCT	S/D		4	118	D138	✓

PREVENTIVE MAINTENANCE CONTRACT

41st TEST & DEVICES OUTPUTS FUNCTIONS. ALARM'S - SPK/PAGE - STROBES. / SHUTDOWN FANS.
(FOREST ELECTRIC - 41st Fl (SOFTWARE/INSTALLATION)) -

INVOICE TO: 7 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 4-26-00
CONTRACT #: SK00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature] - [signature]

SERVICE PERFORMED & REMAINING: S/CONTRACT
As per Contract check / test of Smoke Devices Detectors - Bsmt Ducts on Roof M.E.R. Plant. - As Listed. - (Solomon Brothers) Also Assisting Elect. Contractor Forest / G.C. / Solomon on Test of Shutdowns / SPK/ Strobes

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

on 41st Floor. —

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

21312

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES				
FLOOR				CABLE	XMDR	S/D	TEST
31	ELECT	A-B	(2)	2	187	BRK	✓
	TELEPH	A-B	(2)	2	187	BRK	✓
	COMM	A-B	(2)	2	187	BRK.	✓
	ELECT	C-D	(COAT) 2	2	186	BRK.	✓
	COMM	C-D	(COAT) 2	2	186	BRK	✓
	ELECT	D.W.	(2)	2	186	BRK	✓
	ELECT	F		3	016	PEC 3	✓
	ELECT	G		3	009	PEC 3	✓
	FREIGHT ELEV.			2	008	BRK	✓
	PASS ELEV.			2	008	BRK	✓
	SHUTTLE ELEV.			3	025	PEC 3	✓
	SECURITY CLOSET			3	009	PEC 3	✓
	CORE HER AREA (3)			2	244	PEC 3T	✓
	CORE HER D/D (2)			2	245	HOCHIKI	✓
	W. HER AREA (2)			3	002	PEC 3T	✓
	W. HER D/D (2)			3	034	EDWJ	✓
30th	PASS ELEV.			2	007	BRK	✓
	FREIGHT ELEV			2	007	BRK	✓
	ELECT	A-B	(2)	2	184	BRK	✓
	TELEPH	A-B	(2)	2	184	BRK	✓
	COMM	A-B	(2)	2	184	BRK	✓
	ELECT	C-D	(2)	2	183	BRK	✓
	ELECT	D.W.		2	193	BRK	✓
	ELECT	F		3	015	PEC 3	✓
	ELECT	G/SEC.	(2)	3	008	PEC 3	✓
	TELEPH	C/COAT		2	183	BRK	✓
	COMM	C/COAT		2	183	BRK	✓
	SHUTTLE ELEV.			3	024	PEC 3	✓
	CORE HER CEILING (3)			2	242	PEC 3T	✓
	CORE HER D/D (2)			2	243	HOCHIKI	✓
	W. HER AREA (2)			3	001	PEC 3T	✓
	W. HER D/D (2)			3	033	EDWJ	✓

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 5-2-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSON
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING
Continue S/C Prev. Maintenance on Smoke Detection Floor's 31/30 (Solomon Bros). - System Ok / Reset. -
To be Continued -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during that period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED 21313

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	AREAS			CABLE	XMNDR	S/D	TST
29	ELECT	A-B	(2)	2	182	BLK.	✓
	TELEPH	A-B	(2)	2	182	BLK	✓
	COMM	A-B	(2)	2	182	BLK	✓
	ELECT	C-D	(2)	2	181	BLK	✓
	ELECT	D.W.		2	181	BLK	✓
	ELECT	G		3	007	PEL3	✓
	SECURITY			3	007	PEL3	✓
	ELECT	F		3	014	PEL3	✓
	TELEPH	C		2	181	BLK	✓
	COMM	C		2	181	BLK	✓
	TELEPH	D/CORT		2	181	BLK	✓
	FREIGHT ELEV. LBBY			2	006	BLK	✓
	MAIN ELEV. LBBY			2	006	BLK	✓
	SHUTTLE ELEV			3	030	PEL3	✓
	CORE	HER	CEILING	2	240	PEL3T	✓
	CORE	HER	CEILING	2	240	PEL3T	✓
29	CORE	HER	CEILING	2	240	PEL3T	✓
	CORE	HER	D/D	2	241	HOCHIKI	✓
	CORE	HER	D/D.	2	241	HOCHIKI	✓
	WEST	HER	AREA	3	032	PEL3T	✓
	WEST	HER	AREA	3	032	PEL3T	✓
	WEST	HER	D/D.	3	000	EDWDS	✓
	WEST	HER	D/D	3	000	EDWDS	✓

6th Power Rack TEST/Repair (STATUS)

6th Fl Amplifier Rack Trouble/Repair STATUS

15 Warden Station (342-2) Light CKT Repair (grounded) - Unit disable - out Rack.

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 5-3-00
CONTRACT #: S/C00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature] Rosario

SERVICE PERFORMED & REMAINING: Prev. Maintenance / Service Contract Checked/Test duty on 29 Fl. (All Areas) Listed Also Repairs on 6 Fl / 15 Fl. System Ok / Restored Back to operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representatives that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

21314

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		Cable	XTNDR	S/D	TST
27	ELECT	A	2	178	BRK	✓
	ELECT	B	2	178	BRK	✓
	ELECT	C	2	177	BRK	✓
	ELECT	D	2	177	BRK	✓
	TELEPH	A	2	178	BRK	✓
	TELEPH	B	2	178	BRK	✓
	TELEPH	C	2	177	BRK	✓
	TELEPH	D	2	177	BRK	✓
	COMM	A	2	178	BRK	✓
	COMM	B	2	178	BRK	✓
	COMM	C	2	177	BRK	✓
	COMM	D	2	177	BRK	✓
	FREIGHT ELEV.		2	004	BRK	✓
	PASS ELEV.		2	004	BRK	✓
	CORE MEN D X/DT.		2	237	Hochiki	✓
	CORE MEN DX DUCT		2	237	Hochiki	✓
	LADIES D/D RET.		2	236	Hochiki	✓
	RETURN SOUTH.		2	236	Hochiki	✓
	RETURN NORTH		2	236	Hochiki	✓
26	ELECT A-B (x2)		2	176	BRK	✓
	TELEPH A-B (x2)		2	176	BRK	✓
	COMM A-B (x2)		2	176	BRK	✓
	ELECT C-D (x2)		2	175	BRK	✓
	TELEPH C-D (x2)		2	175	BRK	✓
	COMM C-D (x2)		2	175	BRK	✓
	FREIGHT ELEV.		2	003	BRK	✓
	PASS ELEV Lbby		2	003	BRK	✓
	CORE MEN D/D		2	235	Hochiki	✓
	CORE MEN D/D		2	235	Hochiki	✓
	LADIES Rm D/D RET		2	234	Hochiki	✓
	RETURN SOUTH D/D		2	234	Hochiki	✓
	RETURN NORTH D/D		2	234	Hochiki	✓

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.I.
	DATE SCHEDULED: 5-9-00
CONTRACT #: SFC 00818	TYPE OF SYSTEM: 8800
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Continue S/contract – Prev. Maintenance on Smoke Detection (Solomon Floors) areas listed above. – System OK/Tested as per operation
& also Repaired/Installed (1) Epson LX 810 Printer Replaced at 44 Fl. Security office Solomon Brothers. – (Cold and wasn't printing.) P.C. Action. – Back in operation –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

TIME
DATE
NAME

FIRE SERVICE INCORPORATED

21315

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	Areas		Cable	XTNDR	S/D	TEST
28	Elect	A	2	180	BRK	✓
"	Elect	B	2	180	BRK	✓
"	Elect	C	2	179	BRK	✓
"	Elect	D	2	179	BRK	✓
"	Elect	DW	2	179	Dec3	✓
"	Elect	F	3	179	Dec3	✓
"	Elect	G	3	180	Dec3	✓
"	Tel	A	2	180	BRK	✓
"	Tel	B	2	180	BRK	✓
"	Tel	C	2	179	BRK	✓
"	Comm	A	2	[illegible]	BRK	✓
"	Comm	B	2	180	BRK	✓
"	Comm	C	2	179	BRK	✓
"	Comm	D	2	179	BRK	✓
"	Freight Elev		2	005	Edwards	✓
"	Pass Elev		2	005	Edwards	✓
"	Shuttle Elev		3	005	Dec3	✓
"	Core MER		2	239	Hochiki	✓
"	Core MER		2	239	Hochiki	✓
"	West MER Ceiling		3	057	Dec3T	✓
"	West MER Ceiling		3	057	Dec3T	✓
"	West MER Ceiling		3	057	Dec3T	✓
"	West MER FD/D		3	047	DI3D	✓

(D) No Detector in Security Closet.

INVOICE TO: 7W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D
	DATE SCHEDULED: 5-10-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:00 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Continued S/Contract - Prev. Maintenance. Performed [illegible] Smoke Detector [illegible] areas listed above. System OK Re-tested - As per operation.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

12047

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR	Area			Cable	XTUDN	S/D	TST
40	Elect	A			207	BRK	✓
"	Elect	B			207	BRK	✓
"	Elect	C			"	Apollo	✓
"	Elect	D			"	Apollo	✓
"	Elect	F	(B)			—	—
"	Elect	G			078	FEC3	✓
40	Tel	A			207	BRK	✓
	Tel	B			207	BRK	✓
"	Storage Closet					Apollo	✓
"	Coat Closet					Apollo	✓
"	Comm	A			207	BRK	✓
"	Comm	B			207	BRK	✓
"	Storage					Apollo	✓
"	Storage					Apollo	✓
40	Freight Elev	(D)			017	BRK	✓
"	Pass Elev				017	BRK	✓
"	Shuttle Elev				006	DI3	✓
"	Security Closet				078	FEC3	✓
"	Core MER Ceiling				208	Apollo	✓
"	Core MER Ceiling				208	Apollo	✓
"	Core MER D/D				271	Apollo	✓
"	Core MER D/D				271	Apollo	✓

(B) Head Missing
(D) Head Inside the Ceiling

INVOICE TO: 7 WTC
NYC

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Kesari	F.S.D.
	DATE SCHEDULED: 5-10-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 (AM)	4:30 (PM)	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Continue H/Contract - Prev Maintenance Ord. Smoke Detector Sections, Floors, areas listed above. System OK Restored to Normal Operation.

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SE[illegible]ICE INCORPORAT[illegible] 91762

SUBSIDIARY OF FIRECOM INC.

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718)899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WTC
NY NY

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
R.T Shop	SC# 0818				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		4/26/00	AM	C. Tabar

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	F C I NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 AM	9:00 AM	4:30 PM		8:00				

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE

WILL RETURN ON

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

PROBLEM—AS DESCRIBED

Preventive Maintenance

SERVICE PERFORMED

I Assisted To Jimmy Torres Cleaned & Tested of Smoke detectors (Duct and Areas Located on 48th floor M.E.R. All Smoke detector Tested Work properly.
Also Assisted Techs. To Test 47th floor Devices Solomon floor

WORK REMAINING

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

Date

Name

FCI 155
REV 8/88

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

26061

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	AREA / CLOSET			CABLE	ZONE	S/D	TESTED
36	ELEV. Lobby			2	013	BLK	✓
	FREIGHT ELEV			2	013	BLK	✓
	ELEV SHUTTLE			4	002	PEC 3	✓
	6' ELECTRIC			4	074	PEC 3	✓
	SECURITY CLOSET			4	074	PEC 3	✓
	CORE HER Ceiling			2	256	PEC 3T	✓
	CORE HER	"		2	256	PEC 3T	✓
	CORE HER	"		2	256	PEC 3T	✓
	CORE DUCT DET.			2	255	Hochiki	✓
	CORE DUCT DET.			2	255	Hochiki	✓
	CORE DUCT DET.			2	255	Hochiki	✓
	ELECT.	A		2	198	BLK	✓
	COMM	A		2	198	BLK	✓
	TELEPH	A		2	198	BLK	✓
	TELEPH	B		2	198	BLK	✓
	ELECT	B		2	198	BLK	✓
	COMM	B		2	198	BLK	✓
	ELECT	C		2	197	BLK	✓
	COMM	C		2	197	BLK	✓
	TELEPH	C		2	197	BLK	✓
	ELECT	D		2	197	BLK	✓
	TELEPH	D		2	197	BLK	✓
	ELECT	D1		2	197	BLK	✓
	ELECT	F		4	050	PEC 3	✓
36	WEST	HER	AREA	4	026	PEC 3T	✓
	WEST	HER	AREA	4	026	PEC 3T	✓
	WEST	HER	D/D	4	098	EDWARDS	✓
	WEST	HER	D/D	4	098	EDWARDS	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 4-18-00
CONTRACT #: 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P O #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): NEUERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature] Frank Rosario

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME ______ DATE ______ TIME ______

SERVICE PERFORMED & REMAINING: CONTINUE S/CONTRACT.
PREV. MAINTENANCE ON SMOKE DETECTION UNITS ON VARIOUS FLOORS AREAS / CLOSETS - ELEV LOBBIES - HER'S / DUCTS UNITS AS LISTED ABOVE. - SYSTEM OK / RESTORED BACK TO OPERATION. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

.26063

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS				DEVICES			
FLOOR				CABLE	XTNDR	S/D	TST
38	ELECT	A-B	(2)	2	202	BRK	✓
	TELEPH	A-B	(2)	2	202	BRK	✓
	COMM	A-B	(2)	2	202	BRK	✓
	ELECT	C		2	203	BRK	✓
	ELECT	D		2	203	BRK	✓
	ELECT	D1		2	203	EDWDS	✓
	ELECT	'G'		4	076	PEC3	✓
	SECURITY			4	076	PEC3	✓
	ELECT	'F'		4	052	PEC3	✓
	FREIGHT ELEV			2	015	BRK	✓
	PASS ELEV.			2	015	BRK	✓
	ELEV SHUTTLE			4	004	PEC3	✓
	CORE HEL AREA (3)			2	260	PEC3/T	✓
	CORE HER D/D (2)			2	261	HOCHIKI	✓
	W. HER AREA			4	028	PEC3T	✓
	W. HER D/D			4	100	EDWDS	✓
38	W. HER AREA AUDTH			4	046	PEC3T	✓
38	W. HER D/D AUDTH			4	127	EDWDS	✓
37th	PASS/FREIGHT (2)			2	014	BRK	✓
	TELEPH	A-B	(2)	2	200	BRK	✓
	ELECT	A-B	(2)	2	200	BRK	✓
	COMM	A-B	(2)	2	200	BRK	✓
	TELEPH	C-D	(2)	2	199	BRK	✓
	ELECT	C-D	(2)	2	199	BRK	✓
	COMM	C		2	199	BRK	✓
	ELECT	D1		2	199	BRK	✓
	ELECT	F		4	051	PEC3	✓
	ELECT	G		4	075	PEC3	✓
	SECURITY			4	075	PEC3	✓
	ELEV. SHUTTLE			4	003	PEC3	✓
	CORE HER AREA (3)			2	258	PEC3T	✓
	CORE HER D/D (2)			2	257	HOCHIKI	✓
	W. HER AREA	(2)		4	027	PEC3T	✓
	W. HER D/D	(2)		4	099	EDWDS	✓

INVOICE TO: 2 W.T.C. (Silverstein Props)
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres F. Rosario	F.S.D.
	DATE SCHEDULED: 4-12-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	8:00 AM	4:00 PM	AM/PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representatives that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME

DATE

TIME

X

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Continue S/Contract / Preventive Maintenance of Smoke Detection on Floors 38/37 - Areas listed. - Units cleaned / tested / recorded - Any unit found rejected properly - to Cont S/C

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 21920

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			Cable	XTNDR	S/D	TST CLEAN
39	E/ECT	A		2	205	BRK	✓
	TE/EPH	A		2	205	BRK	✓
	COMM	A		2	205	BRK	✓
	E/ECT	B		2	205	BRK	✓
	COMM	B		2	205	BLK	✓
	TE/EPH	B		2	205	BRK	✓
	E/ECT	C		2	204	BLK	✓
	E/ECT	D		2	204	BLK	✓
	E/ECT	DW-1		2	205	BLK	✓
	E/ECT	F		4	053	PEC 3	✓
	E/ECT	G		4	077	PEC3	✓
	SECURITY			4	077	PEC 3	✓
	E/EV. PASS			2	016	BRK	✓
	FREIGHT ELEV.			2	016	BRK	✓
	E/EV. SHUTTLE			4	005	PEC3	✓
	CORE	HER AREA		2	262	PEC3	✓
	CORE	HER AREA		2	262	PEC 3	✓
	CORE	HER AREA		2	262	PEC3T	✓
	CORE	HER D/D		2	263	Hochiki	✓
	CORE	HER D/D		2	263	Hochiki	✓
39	WEST	HEr D/D		4	101	EDWDS	✓
	W. HER	AREA		4	029	PEC3T	✓
	D/D	Ceiling	Recp.T.	2	254	S-5022 Apollo	✓
	D/D	"	"	2	254	"	✓
	D/D	"	"	2	254	"	✓
	D/D	"	"	2	254	"	N/A
	D/D	"	"	2	254	"	N/A

INVOICE TO: 7 W.T.C. (Solomon Brothers) N.Y.C.

SERVICEMAN ASSIGNED: J. Torres, F. Rosario	SEE AT JOB SITE: F.S.D
	DATE SCHEDULED: 4-11-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☐ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	800 AM	330 PM	330 PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE:
SERVICEMAN SIGNATURE:

SERVICE PERFORMED & REMAINING: S/CONTRACT – Prev. Maintenance Smoke Detection Class E Equipment – on 39th Floor – (Areas Listed). – System Tested/Restored As per operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

TIME

DATE

NAME

(39)

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11784

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR				S/D	C Nk	STNDR	TST
23	MECH	RM	D/D	Apollo	2	264	✓
23	MECH	RM	D/D	Apollo	2	264	✓
23	MECH	RM. AREA	HEAT	Apollo	2	268	✓
23	MECH	RM AREA	HEAT	Apollo	2	268	✓
23	BUNK	RM	AREA	Apollo	2	269	✓
23	BUNK	RM	AREA	Apollo	2	269	✓
23	CONF. RM / CLASS RM			(4)	2	265	✓
	(S. WEST CORNER)		UNDERFLOOR				
23	CONF RM / CLASS RM			(4)	2	265	✓
	(S. W CORNER)		U/F.				
23	QUARTER'S MASTER			(3)	2	266	✓
	UNDER/FLOOR -						
23	MOTOROLA RM			(4)	2	266	✓
	U/FLOOR						
23	WATCH COMMAND CENTER			(4)	2	266	✓
	UNDER/FLOOR. -						
7	TANK	RM	AREA	COMBO (2)	1-110		✓
7	GENERATOR RM			(5)	1-110		✓
47	RADIO COMM. ROOM.			(2) Apollo	2-270		✓
	(ROOF)			AREA / COMBO			
23	MANUAL	PULL	STATIONS	(3)	-2-032		✓

INVOICE TO: 7 W.T.C
N.Y.C MAYOR'S OFFICE
23rd Fl.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED 4-7-00
CONTRACT #	TYPE OF SYSTEM 8500
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM/PM	9:00 AM/PM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE Ray Lynch J.J.

SERVICEMAN SIGNATURE [signatures]

SERVICE PERFORMED & REMAINING: Creating S/Contract Prev. Maintenance / Located / Search of Smoke Detectors U/Floor's Areas. - (As Listed) on 23rd 47th Fl & 7th Floors - (As Listed). -
Also Tested (3) Manual pull stations - (2-032). - Check / Strobe Panel Alarm/Trouble Verified O.K. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SERVICE INCORPORATED

26064

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

(SHAFT'S)

LOCATIONS	DEVICES					
FLOOR		CABLE	XTNDR	S/D	TST	
47	SHUTTLE ELEV WEST	4	037	PEC 3T	✓
47	SHUTTLE ELEV. EAST	4	037	PEC 3T	✓
43	E.H.R. PE 1.2 (BATH RM ENT.)	4	064	PEC 3	✓
16	E.H.R AREA EAST	1	195	BRK	✓
16	E.H.R AREA EAST	1	195	BRK	✓
16	E.H.R D/D EAST	1	254	EDWDS	✓
16	EHR AREA WEST	1	195	BRK	✓
16	E.H.R D/D WEST	1	254	EDWDS	✓
15	E.H.R AREA WEST	1	192	BRK	✓
15	E.H.R AREA EAST	1	192	BRK	✓
15	E.HR AREA EAST	1	192	BRK	✓
3rd	SHUTTLE ELEV. SHAFT	3	049	PEC 3T	✓
2	E.H.R HE 1+2	3	005	PEC 3T	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.J.J
	DATE SCHEDULED 4-7-00
CONTRACT # S/C00 818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☐ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
4:00 PM	4:30 PM	8:30 PM	AM PM	

P.M.

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) PAT. Kinsella (For J. Corrigan)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signatures]

SERVICE PERFORMED & REMAINING

Prev. Maintenance Elevators Shaft's - S/Detection (as listed) Assisted by Otis Mechanic - And E.H.R's Areas. - System Ack/Reset Back to operation. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

(16)

FIRE SERVICE INCORPORATED

26059

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS | **DEVICES**

FLOOR	PRESS	RH	XTNDR	S/D	SERIAL	TEST
23	U/Floor		2-266	DIA-3	E6112A3	✓
	U/F		2-266	"	E9412A3	✓
	U/F		2-266	"	E6112A3	✓
	U/F		2-266	"	E8112A3	✓
*	U/F		N/A - Location needed			—
23	E.O. Centr					
	Podium U/F		2-267	DIA-3	E943044	✓
	Podium U/F		2-267	DIA-3	E943844	✓
	Podium U/F		2-267	DIA-3	E94384Y41	✓
23	E.O.C. Hdqtrs					
	#1-4 TWR		2-267	DIA3		✓
	#5-8 TWR		2-267	DIA3		✓
	#9-12 TWR		2-267	DIA3		✓
	#13-16 TWR		2-267	DIA-3		✓
	#17-20 TWR		2-267	DIA-3		✓
	#21-24 TWR		2-267	DIA-3		✓
	#25-28 TWR		2-267	DIA3		✓
	#29-32 TWR		2-267	DIA3		✓

Non Resettable

to be Continued

INVOICE TO:
7 W.T.C.
O.E.M. - 23rd Fl.
N.Y.C.
Mayor's Office

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.D. / Ray Lynch
	DATE SCHEDULED: 4-6-00 / 4-7-00
CONTRACT #: 5/1 00	TYPE OF SYSTEM: 8100
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8:00 AM	9:00 AM	4:30 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE: Ray Lynch D.T.S.

SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: Prev. Maintenance on Smoke Detectors Units -- Located on 23rd Fl. - Areas Underfloor - (As listed above) Units terminated directly to class "E" system.
Note: Units under Dis. Floor's - Tiles / Rugs needed to be lifted. - & units search / located. - Escort needed.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 26060

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS / DEVICES						
47	Elev Shaft Car 44/47 Shuttle						
			Cable 4	XTNDR 037	S/D PEC 3T		
46	Kitchen Shuttle # 38 Car						
			Cable 4	036		PEC 3T	
46	Freight Shuttle HKE1 Room						
			4 - 036			PEC 3T	
47	EHR	Car 21-28					
		Cable 2 - 220			BAK		
47	EHR	Car 21-28					
		Cable 2 - 220			BLK.		
47	EHR	Car 21-28					
		Cable 4 067			PEC 3		
46	EHR	HKE 2-3					
		Cable 4 065			PEC 3		
46	EHR	HKE1					
		Cable 4 - 066			PEC 3		
31	EHR	Area					
		Cable 2 - 188 (2) BAK.					
31	EHR	DID ECR					
		Cable 2 246 (1) Hochiki SIF24					
31	EHR	Area - Cable 1 - 188 (1) BLK -					
	EHR	DID ECR Cable - 2 - 246 Hochiki (1)					

(Margin notes: Solomon; SPLV; Solomon; SPLV)

INVOICE TO: 7 W.T.C
N.Y.C.
(OTIS)

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	FSI / OTIS
	DATE SCHEDULED: 4-6-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	430 PM	830 PM	AM PM	4 P.H.

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Pat Kinsella (For J. Cornyea)
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is released and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING
Check test of Elevator Shaft / EHR's Areas S/Detectors listed above as per Contract.
System ock [illegible] — To be continued.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11756

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES			
FLOOR		CABLE	XTNDR	S/D	TST CLEAN
45	SHUTTLE E/EV	4	011	PEC3	✓
	PASS E/EV.	2	022	BRK	✓
	FREIGHT E/EV	2	022	BRK	✓
	SHUTTLE KITCH	4	012	PEC3T	✓
	COMM 'B'	2	217	BRK	✓
	TELEPH B	2	217	BRK	✓
	ELECT B	2	217	BRK	✓
	'G' ELECT. CLOSET	4	013	PEC3	✓
	SECURITY CLOSET	4	083	PEC3	✓
	ELECT A	2	217	BRK	✓
	COMM A	2	217	BRK	✓
	AREA 'D' STAIR	4	063	PEC3T	✓
	'F' ELECTRIC	4	059	PEC3T	✓
	EAST A/V PROJECT	4	091	PEC3T	✓
	SHAFT/PROJ. ROOM	4	089	PEC3	✓
	D/D AHU 45-1	4	123	EDWDS	✓
	D/D TF 45-3	4	094	EDWDS	✓
45	E/EV SHUTTLE	4	019	PEC3	✓
	D/D TF 45-1	4	092	EDWDS	✓
	D/D AHU 45-2	4	124	EDWDS	✓
	AREA STAIR	4	003	PEC3	✓
44	ELECT A-B (2)	2	215	BRK	✓
	COMM A-B (2)	2	215	BRK	✓
	TELEPH A-B (2)	2	215	BRK	✓
	E/EV PASS.	4	021	BRK	✓
	FREIGHT E/EV	4	021	BRK	✓
	E/EV. SHUTTLE	4	010	PEC3	✓
	E/EV. SHUTTLE	4	010	PEC3	✓
	ELECT. 'F'	4	058	PEC3	✓
	ELECT 'G'	4	082	PEC3	✓
	SEC. CLOSET	4	082	PEC3	✓
	WEST-HER CEILING	4	834	PEC3T	✓
	WEST HER D/D	4	112	EDWDS	✓

INVOICE TO: 7 W.T.C
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D. 4-5-00
	DATE SCHEDULED: 4-5-00
CONTRACT #: S/C 008/8	TYPE OF SYSTEM: 8100
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN.
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection service during their service of the equipment.

TIME / DATE / NAME

SERVICE PERFORMED & REMAINING: Preventive Maintenance on Smoke Detection Units (Silverstein Floors (Lister Areas). – Floors 45 & 44th Units Tested ACK/RESET at Fire Console – To Continue –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

11770

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS	CABLE	XMDR	S/D	TST CLEAN
47	W HER D/D	4	069	EDWDS	✓
	W. HER D/D	4	115	EDWDS	✓
	W HER D/D	4	113	EDWDS	✓
	ELECT G.	4	085	PEC3T	✓
	SECURITY	4	085	PEC3T	✓
	VERTICAL SHAFT	4	068	PEC3T	✓
	ELEV. SHUTTLE Lbby	4	016	PEC3T	✓
	ELECT 'F'	4	061	PEC3T	✓
	ELECT A-B (2)	2	223	BRK	✓
	COMM A-B (2)	2	223	BRK	✓
	ELECT 'C' CLOSET	2	223	BRK	✓
	COMM 'D' CLOSET	2	223	BRK	✓
	STAIR 'B' LANDING	2	221	EDWDS	✓
	CORE HER D/D	2	279	EDWDS	✓
	CORE HER AREA (3)	2	278	PEC3T	✓
46th	FREIGHT Lbby	2	023	BRK	✓
	ELECT G	4	084	PEC3	✓
	SEC. CLOSET	4	084	PEC3	✓
	ELECT B	2	218	BRK	✓
	COMM B	2	218	BRK	X DEFECT.
	ELECT A	2	218	BRK	✓
	COMM A	2	219	BRK	✓
	TELEPH A	2	218	BRK	✓
	TELEPH D	2	219	BRK	✓
	ELECT D	2	219	BRK	✓
	COMM D	2	219	BRK.	✓
	ELEV. SHUTTLE 'H'	4	015	PEC3T	✓
	ELEV. SHUTTLE F.	4	014	PEC3	✓
	CORE HER. D/D (2)	2	277	HONEB	✓
	CORE AREA. (3)	2	276	PEC3T	✓
	ELECT F	4	060	PEC3	✓
	ELECT C	2	219	PEC3	✓
	KITCHEN SHUTTLE ELEV.	4	013	PEC3	✓

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSORIO	F.S.D.
	DATE SCHEDULED: 4-4-00
CONTRACT #: S/C 00 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection service during their service of the equipment.

NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Prev. Maintenance as per Service Contract - Cleaned TESTED SMOKE DETECTORS Units on areas LISTED Floors 47 & 46th (Solomon S.B. Floors). - System OK, RESETTED AS PER OPERATION. -
(*) 'B COMM. = S/D. DEFECTIVE/CHECK replace pending. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15753

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S		S/D	CABLE	XTNDR	
6	SWITCHGEAR		BRK	1	171	
	"		BRK	1	171	
	"		BRK	1	171	
	"		BRK	1	171	
	"		BRK	1	171	
6	H.V. VAULT	(X4)	BRK	1	171	
	H.V. VAULT	(X4)	BRK	1	171	
	H.V. VAULT	(X4)	BRK	1	171	
	H.V. VAULT	(1)	BRK	1	171	
5	SWITCH GEAR	AREA	BRK	1	170	North
	"	"	BRK	1	170	North
	"	"	BRK	1	170	North
	"	"	BRK	1	170	North
	SWITCH GEAR		BRK	1	170	South
	"	"	BRK	1	170	South
	"	"	BRK	1	170	South
	"	"	BRK	1	170	South
	H.V. VAULT	AREA	(X6)	1	170	
	H.V. VAULT	AREA	(X6)	1	170	
46	STROBE PANEL	AFL 100	Repairing (Batteries)			

Silverstein

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / E. Rosario	F.S.D.
	DATE SCHEDULED: 3-29-00
CONTRACT #: S1C00790	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
8 Noon AM/PM	9 Noon AM/PM	4:30 AM/PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	Batteries 12 Volts.	

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): Silverstein
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Continuing S/Contract - Prev. Maintenance on Smoke Detection Floor's 6th / 5th Fl (Silverstein) High Voltage Room's / Vault. — * Repairing on 46th Fl. Strobe Panel AFL 100 Replacing (2) Batteries 12 Volts. Also Back in operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15751

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S		CABLE	XTNDR	S/D.	TST CLEAN
9	ELECT A		1	179	BRK	✓
	COMM B		1	179	BRK	✓
	COMM A		1	179	BRK	✓
	ELECT B		1	179	BRK	✓
	TELEPH A		1	179	BRK	✓
	TELEPH B		1	179	BRK	✓
	PASS ELECT		1	008	BRK	✓
	FREIGHT ELECT.		1	008	BRK.	✓
	COMM C		1	178	BRK	✓
	ELECT C		1	178	BRK	✓
	TELEPH C		1	178	BRK	✓
	ELECT D		1	178	BRK	✓
	COMM D		1	178	BRK	✓
	TELEPH D		1	178	BRK	✓
	RETURN D/D	NORTH	1	238	Hochiki	✓
	RETURN D/D	EAST	1	238	Hochiki	✓
	RETURN D/D	SOUTH	1	238	Hochiki	✓
	CORE HER D/D.		1	239	Hochiki	✓
	CORE HER. D/D.		1	239	Hochiki	✓
6	PASS/FREIGHT ELEV (2)		1	005	BRK	✓
	COMM. 'A'		1	172	BRK	✓
	ELECT 'A'		1	172	BRK	✓
	TELEPH 'A'		1	172	BRK	✓
	ELECT 'B'		1	172	BRK	✓
	COMM 'B'		1	172	BRK	✓
	TELEPH 'B'		1	172	BRK	✓
	FAN RM. AREA		1	173	BRK	✓
	FAN RM. AREA		1	173	BRK	✓
	FAN RM. AREA		1	173	BRK	✓
	DUCT S/D. FAN RM		1	231	Hochiki	✓
	DUCT S/D. FAN RM		1	229	Hochiki	✓
	DUCT S/D FAN RM		1	232	Hochiki	✓
	DUCT S/D FAN RM		1	233	Hochiki	✓

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. TORRES / F. ROSARIO	F.S.D.	
	DATE SCHEDULED 3-22-00	
CONTRACT # 5/C00 818	TYPE OF SYSTEM 8500	
FEE SERVICE #	P.O. #	
CALL AUHTORIZED BY	PHONE	EXT

☐ MAINTENANCE ☐ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM PM	430 AM PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is imposed and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME ______ DATE ______ TIME ______

SERVICE PERFORMED & REMAINING: Preventive Maintenance on Smoke Detection Devices / Class-E System on Floors 9 & 6th fl areas above (Listed). — System OK'd Restored —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15750

REPORT OF FIELD SERVICE

FLOOR	AREA'S		CABLE	XTUDE	S/D	TEST TEAM
8	ELEV. PASS		1	007	BLK	✓
	FREIGHT ELEV		1	007	BLK	✓
	ELECT "A"		1	177	BLK	✓
	COMM A		1	177	BLK	✓
	TELEPH A.		1	177	BLK	✓
	COMM B		1	177	BLK	✓
	ELECT B		1	177	BLK	✓
	TELEPH B		1	177	BLK	✓
	RETURN D/D North		1	236	Hochiki	✓
*	RETURN D/D South		N/A	—		—
	RETURN D/D EAST (Side)		1	236	Hochiki	✓
	CORE HER D/D		1	237	Hochiki	✓
	CORE HER D/D		1	237	Hochiki	✓
	COMM C-D (2)		1	176	Hochiki	✓
	ELECT C-D (2)		1	176	Hochiki	✓
	TELEPH C-D (2)		1	176	Hochiki	✓
7	COMM A		1	175	BLK	✓
	ELECT A		1	175	BLK	✓
	TELEPH A.		1	175	BLK	✓
	PASS/FREIGHT ELEV		1	006	BLK	✓
	COMM B		1	175	BLK	✓
	ELECT B		1	175	BLK	✓
	TELEPH B		1	175	BLK	✓
	COMM C		1	174	BLK	✓
	ELECT C		1	174	BLK	✓
	TELEPH C		1	174	BLK	✓
	TELEPH D		1	174	BLK	✓
	ELECT D		1	174	BLK	✓
	COMM D		1	174	BLK	✓
	CORE HER D/D		1	235	Hochiki	✓
	CORE HER D/D		1	235	Hochiki	✓
	RETURN D/D North		1	234	Hochiki	✓
	RETURN D/D South		1	234	Hochiki	✓

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED: J. Turner; F. Rosario
SEE AT JOB SITE: F.S.D.
DATE SCHEDULED: 3-21-00
CONTRACT #: 5/2 00 818
TYPE OF SYSTEM: 8500
FEE SERVICE #:
P.O. #:
CALL AUHTORIZED BY:
PHONE:
EXT:

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): Sean O'Keeffe
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING

Quarterly Contract Preventive Maintenance on Smoke Area Detectors
Floors 7 & 8 (Listed Areas). — System Ack/Reseted Properly.
* NOTE (8th FL) Return Unit South Side Unavailable / No Location. —
(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER
As Previously Reported.

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15749

REPORT OF FIELD SERVICE

LOCATIONS / **DEVICES**

FLOOR	AREAS		CABLE	XTNDR	S/D	TST CLEAN
11th	COMM 'A'		1	182	BLK	✓
	ELECT A		1	182	BLK	✓
	TELEPH A		1	182	BLK	✓
	PASS ELEV		1	010	BLK	✓
	COMM 'B'		1	182	BLK	✓
	ELECT 'B'		1	182	BLK	✓
	TELEPH 'B'		1	182	BLK	✓
	FREIGHT ELEV		1	010	BLK	✓
	RETURN PLENUM South		1	244	Hochiki	✓
	RETURN D/D North		1	244	Hochiki	✓
	CORE HER D/D		1	243	Hochiki	✓
	CORE HER D/D		1	243	Hochiki	✓
	ELECT RM 'C'		1	183	BLK	✓
	COMM 'C'		1	183	BLK	✓
	TELEPH 'C'		1	183	BLK	✓
	TELEPH 'D'		1	183	BLK	✓
	ELECT 'D'		1	183	BLK	✓
	COMM 'D'		1	183	BLK	✓
10	PASS/FREIGHT (2)		1	009	BLK	✓
	ELECT A-B (2)		1	181	BLK	✓
	TELEPH A-B (2)		1	181	BLK	✓
	COMM A-B (2)		1	181	BLK	✓
	CORE HER D/D		1	241	Hochiki	✓
	CORE HER D/D		1	241	Hochiki	✓
	RETURN D/D North		1	240	Hochiki	✓
	RETURN D/D South		1	240	Hochiki	✓
	RETURN D/D EAST		1	240	Hochiki	✓
	ELECT C-D (2)		1	180	Hochiki	✓
	COMM C-D (2)		1	180	Hochiki	✓
	TELEPH C-D (2)		1	180	Hochiki	✓

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D
	DATE SCHEDULED: 3-15-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: Continue Prev. Maintenance as per Contract — Test (Manual) Smoke Detectors Check on Areas (Listed) Floors 11th Fl & 10th. Safety Corrected Back to Operation.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

TIME
DATE
NAME

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15748

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S		CABLE	VINDR	S/D	TST CLEAN
13	COMM A-B	(2)	1	186	BLK	✓
	ELECT A-B	(2)	1	186	BLK	✓
	TELEPH A-B	(2)	1	186	BLK	✓
	PASS FREIGHT	(2)	1 (012)	012	BLK	✓
	CORE HER D/D		1	247	Hochiki	✓
	CORE HER D/D		1	247	Hochiki	✓
	ELECT C		1	187	BLK	✓
	COMM C		1	187	BLK	✓
	TELEPH C.		1	187	BLK	✓
	RETURN D/D	North	1	246	Hochiki	✓
	RETURN D/D	South	1	246	Hochiki	✓
	COMM D		1	187	BLK	✓
	TELEPH D		1	187	BLK	✓
	ELECTRIC D		1	187	BLK	✓
12	PASS LOBBY		1	011	BLK	✓
*	COMM A	(Cover n/g)	1	184	BLK	✓
	ELECT A		1	184	BLK	✓
	TELEPH A		1	184	BLK.	✓
	FREIGHT ELEV		1	011	BLK.	✓
	COMM B		1	184	BLK	✓
	ELECT B		1	184	BLK	✓
	TELEPH B		1	184	BLK	✓
*	CORE HER D/D LED		1	245	Hochiki	✓
*	CORE HER D/D LED		1	245	Hochiki	✓
	RETURN PLENUM D/D N		1	244	Hochiki	✓
	RETURN PLENUM D/D S		1	244	Hochiki	✓
	COMM 'C'		1	185	BLK	✓
	ELECT 'C'		1	185	BLK	✓
	TELEPH 'C'		1	185	BLK	✓
	COMM 'D'		1	185	BLK	✓
	ELECT 'D'		1	185	BLK	✓
	TELEPH 'D'		1	185	BLK	✓

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 3-14-00
CONTRACT #: SPC 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #: 3-14-00
CALL AUHTORIZED BY	PHONE / EXT

☐ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:20 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING

Courtesy S/Contract Prev. Maintenance on class E System - Smoke Detectors Tested / Cleaned on Floor's 13/12 Above Listed. -

(*) NOTE: Core HER D/D 'LED's - n/g Need to Replace. 'A' Comm. closet - Unit Cover n/g to Replace -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15746

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES				
FLOOR	AREAS		CABLE	XTNDR	S/D	TST CLEAN
15	COMM A		1	190	BLK	✓
	ELECT A		1	190	BLK	✓
	TELEPH A		1	190	BLK	✓
	COMM B		1	190	BLK	✓
	ELECT B		1	190	BLK	✓
	TELEPH B		1	190	BLK	✓
	PASS FREIGHT (2)		1	014	BLK	✓
(*)	CORE HER D/D		1	251	Hochi	✓ LED
	CORE HER D/D		1	251	Hochi	✓
	RETURN PLENUM D/D		1	250	Hochi	✓
(*)	RETURN SOUTH	NO ACCESS			U/N	*
(*)	COMM C-D	(2)	1	191	BLK	✓
	ELECT C-D	(2)	1	191	BLK	✓
	TELEPH C-D	(2)	1	191	BLK	✓
(*)	D COMM. CLOSET	NO ACCESS/FURNITURE				
14	PASS FREIGHT (2)		1	013	BLK	✓
	COMM A		1	188	BLK	✓
	ELECT A		1	188	BLK	✓
	TELEPH A		1	188	BLK	✓
	TELEPH B		1	188	BLK	✓
	COMM B		1	188	BLK	✓
	ELECT B		1	188	BLK	✓
	CORE HER D/D		1	249	Hochi	✓
	CORE HER D/D		1	249	Hochi	✓
	RETURN D/D		1	248	Hochi	✓
(*)	RETURN D/D North	NO ACCESS				*
	COMM C		1	189	BLK	✓
	ELECT C		1	189	BLK	✓
	TELEPH C		1	189	BLK	✓
	ELECT D		1	189	BLK	✓
	TELEPH D		1	189	BLK	✓
	COMM D		1	189	BLK	✓
18	TELCOM [illegible]		1	198	[illegible]	✓
18	TELCOM / D/D FAN		1	108	DI8-3	✓

INVOICE TO: 7 W.T.C
N.Y.C

SERVICEMAN ASSIGNED: J. Torres, F. Rosario	SEE AT JOB SITE: F.S.D.
	DATE SCHEDULED: 3-8-00
CONTRACT #: 5/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	PO #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

TIME
DATE
NAME

SERVICE PERFORMED & REMAINING: CONTINUE S/CONTRACT - PREV. MAINTENANCE SMOKE DETECTION 15/14 FLOOR'S (SEE ABOVE). —

* NOTE: 15 FL. 'D' COMM. CLOSET = NO ACCESS DOOR (BLOCKED) FURNITURE ON WAY.
* CORE HER D/D. L.E.D. TO BE REPLACE/DAMAGE, — 15 FL.
* RETURN DUCTS/DETECTOR (AS PREVIOUS REPORT) NO ACCESS - (SOLID CEILING) 15 FL

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

* 14 FL. RETURN DUCT'S/DETECTOR (AS PREVIOUS REPORT) NO ACCESS (SOLID CEILING) NORTH SIDE

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15747

REPORT OF FIELD SERVICE

FLOOR	AREAS			CABLE	XTNDN	S/D	TST/Clean
17	COMM	A-B	(2)	1	197	BLK	✓✓
	ELECT	A-B	(2)	1	197	BLK	✓✓
	TELEPH	A-B	(2)	1	197	BLK	✓✓
	PASS ELEV			1	016	BLK	✓✓
	FREIGHT ELEV			1	016	BLK	✓✓
	CORE HER D/D			1	256	Hochik	✓
	CORE HER D/D			1	256	Hochik	✓
(*)	RETURN PLENUM D/D			NO ACCESS			CLOSE
	ELECT	C-D	(2)	1	196	BLK	✓✓
	COMM	C-D	(2)	1	196	BLK	✓✓
	TELEPH	C-D	(2)	1	196	BLK	✓✓
16	COMM	A-B	(2)	1	193	BLK	✓✓
	ELECT	A-B	(2)	1	193	BLK	✓✓
	TELEPH	A-B	(2)	1	193	BLK	✓✓
	TELEPH	C-D	(2)	1	194	BLK	✓✓
	ELECT	C-D	(2)	1	194	BLK	✓✓
	COMM	C-D	(2)	1	194	BLK	✓✓
	PASS LBBY			1	015	BLK	✓
	FREIGHT LBBY			1	015	BLK	✓
	CORE HER D/D			1	253	Hochik	✓
	CORE HER D/D			1	253	Hochik	✓
	PLENUM RETURN D/D			1	252	Hochiki	✓
(*)	" RETURN SOUTH		NO ACCESS				UNAVAILABLE

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.I.D
	DATE SCHEDULED: 3-7-00
CONTRACT #: 5/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING

CONTINUE S/CONTRACT PREV. MAINTENANCE ON FLOOR'S 17° 16° (AS LISTED)
(*) NOTE: 17TH FL. RETURN DUCT'S DET. UNAVAILABLE / NO ACCESS. CEILING
16TH RETURN D/D SOUTH SIDE NO ACCESS / [illegible] AS PREVIOUSLY REPORTED

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15722

REPORT OF FIELD SERVICE

INVOICE TO: W.T.C
N.Y.C.

LOCATIONS			DEVICES			
FLOOR	AREA'S/ELEV		CABLE	XTNDR	S/D	TST/CLEANED
19	ELECT B		1	201	BLK	✓
	COMM B		1	201	BLK	✓
	TELEPH B		1	201	BLK	✓
	PASS/FREIGHT ELEV.		1	018	BLK	✓
	ELECT A		1	201	BLK	✓
	COMM A		1	201	BLK	✓
	TELEPH A		1	201	BLK	✓
	RETURN D/D NORTH		1	259	Hochiki	✓
	RETURN D/D SOUTH		1	259	Hochiki	✓
	CORE HER SUPPLY		1	260	Hochiki	✓
	CORE HER SUPPLY		1	260	Hochiki	✓
	ELECT C-D	(2)	1	200	BRK	✓
	COMM C-D	(2)	1	200	BRK	✓
	TELEPH C-D	(2)	1	200	BRK	✓
18	COMM A-B	(2)	1	197	BRK	✓
	ELECT A-B	(2)	1	197	BRK	✓
	TELEPH A-B	(2)	1	197	BRK	✓
(*)	PASS/FREIGHT ELEV.	(2)	1	016	BLK	✓
	COMM C-D	(2)	1	196	BRK	✓
	ELECT C-D	(2)	1	196	BLK	✓
	TELEPH C-D	(2)	1	196	BRK	✓

(*) FREIGHT 18th Fl. ELEV. Lobby S/D UNIT (DEFECTIVE to be Replaced)

PREVENTIVE MAINTENANCE CONTRACT

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / L. ROSARIO	F.S.D
	DATE SCHEDULED 3-1-00
CONTRACT # S/C 00818	TYPE OF SYSTEM 8500
FEE SERVICE #	P.O #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT) SILVERSTEIN
CUSTOMER SIGNATURE
SERVICEMAN SIGNATURE

SERVICE PERFORMED & REMAINING
Continue S/C. Preventive Maintenance on Floors 19 & 18th (as listed)
Units TEST/CLEANED — Alarms ACK/RESET — Function OUTPUTS O.K. —
SYSTEM (RESET) — BACK TO OPERATING. —
(*) NOTE: 18th Fl FREIGHT Lobby S/D to be replaced. — TO Follow up. —

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

88032

SUBSIDIARY OF FIF ,M INC

39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
Silverstein.
7 WTC
Emergency Service.

SATURDAY

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P O #	SEE AT JOB SITE
Service.						S/O Lawrence
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		15 JANUARY 2000				Newell

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
			TROUBLE CALL			
			Construction			
			BILLABLE	CONTRACT TROUBLE CALL		

CHECK APPROPRIATE BOX

- ☐ Q C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☐ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
200	245	350		150				

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☐

SERVICE DATE: 15 JANUARY 2000

WILL RETURN ON:

CUSTOMER SIGNATURE: Leslie Lawrence

SERVICEMAN SIGNATURE: B. C. Newell

PROBLEM—AS DESCRIBED

Emergency Service.

SERVICE PERFORMED 200 rcvd beep. Contact service and customer. Customer report 43rd FL speaker going in and out of trouble. Floor under construction. 2:45 arrived at Jobsite. Met with Security. Check F.C.S. 43rd FL speaker in trouble, then trouble reset. Met with Engineer. Access 38th FL and 42nd FL. Construction floors gutted. Speaker open and grounded circuit disconnected grounded field wires 41st FL and 43rd FL. to stabilized F.C.S. Checked F.C.S. -ok speaker in trouble 40-43. Call completed.

WORK REMAINING

* Must clear grounded speakers 41st and 43rd FL

FCI 155
REV 6186

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc and its employees regarding interruption of fire protection service during their service of the equipment.

Date

Name

FIRE SERVICE INCORPORATED

88043

SUBSIDIARY OF F[illegible]OM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 WORLD TRADE CENTER
NEW YORK, N.Y

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
		SC-00818				
PHONE	**EXT**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		1-17-00				T. TRONCOSO

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
2			12VDC/7AH BATTS	69.95		

TROUBLE CALL

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I&T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☑ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
12:30 PM	1:30 PM	2:00 PM		1.5				

- ☐ MAT. REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD

SERVICE DATE: 1-17-00

CUSTOMER SIGNATURE: Sean O'Keef

I&T COMPLETE ☐ CALL COMPLETE ☑

WILL RETURN ON:

SERVICEMAN SIGNATURE: Troncoso

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name: X Date:

PROBLEM—AS DESCRIBED

TROUBLE CALL

SERVICE PERFORMED

REPLACE TWO 12VDC/7AH BATTS. IN AFC-100 STROBE PANEL 20TH FL. MER. ROOM.
PANEL BACK ON LINE.

WORK REMAINING

JOB DONE.

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

21937

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS	DEVICES
FLOOR	
6	STROBE PANEL ACTIVATION (1) AFC 100 - B COMM. - (1) STROBE - 5 SPEAKERS.
3rd	STROBE PNL ACTIVATION (1) AFC 100 'B' COMM. - STROBES = 10 UNITS
2nd	STROBE PANEL ACTIVATION (1) AFC 100 FREIGHT/ENTRANCE AREA - STROBES = 6 UNITS.
1st	STROBE PANEL ACTIVATION (1) AFC 100 PUMP ROOM. - STROBES = 2 UNITS. -
* 26	STROBE PANEL PYRO SYSTEM 3 CORE HE[illegible] TROUBLE / NEED (2) BATTERY 6 VOLTS (LOW OUTPUT)
* 12	REPAIRED (1) AFC 101 PANEL - REPLACED (1) BATTERY 12 VOLTS - (LOW OUTPUT) - 'B' COMM. CLOSET
* 11	REPAIRED (1) AFC 101 PANEL (1) BATTERY REPLACED LEAKING UNIT / DEFECTIVE. - 'B' COMM. CLOSET -
16	REPAIRED (1) AFC 100 PANEL - 'A' CKT OUT CHECK / RESISTANCE - O.K. - BACK TO OPERATIONS -

INVOICE TO: 7 WTC. N.Y.C.

SERVICEMAN ASSIGNED: J. TORRES, F. ROSARIO

SEE AT JOB SITE:

DATE SCHEDULED: 1-12 00

CONTRACT #: S/C 00 313

TYPE OF SYSTEM: 8500

FEE SERVICE #:

P.O. #:

CALL AUTHORIZED BY:

PHONE: EXT:

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
2	BATTERIES 12 VOLTS	69⁹⁵ each

PREVENTIVE MAINTENANCE CONTRACT

CUSTOMER NAME (PRINT): [illegible]

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING

As per contract check tested strobes panels (light on floors areas (above listed). - Also repairing / replaced (1) battery unit on 12th floor and (1) unit batteries / on 11th (low output) leaking unit.

(A) 26th fl panel pyro strobe need (2) units — pending —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION — The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component(s) in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during the service of the equipment.

NAME DATE TIME

FIRE SE[illegible]VICE INCORPORA[illegible]ED 70080 0/199

SUBSIDIARY OF F[illegible]OM INC
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
4 WTC
NY | NY

CALL AUTHORIZED BY	CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
R. Trivitto	Sch CE/8				F.S.D

PHONE	EXT	DATE SCHEDULED	TIME SCHEDULED	SERVICEMAN ASSIGNED
		10/13/99	AM	C. Tabue

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/Q	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT
2.			BATERIES 12 VOC	$69.95		

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ O C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
8:00 AM	9:00 AM	4:30 PM		8:00				

☐ MAT REQD ☐ PARTIAL ☐ OTHER ☐ LABOR REQD

I & T COMPLETE ☐ CALL COMPLETE ☐

SERVICE DATE: 10/13/99

WILL RETURN ON

CUSTOMER SIGNATURE: Sean OKeeffe

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name   Date

PROBLEM—AS DESCRIBED

Preventive Maintenance

SERVICE PERFORMED

Cleaned and Tested Sensitivity of smoke detector on 2nd and 3rd floor Areas Closets Elevator Lobbys All detector tested work OK. Also. Repairs on The 45th floor Strobe Panel

Not Delivery To WTC four Batterys for Replacement on strobe panel

WORK REMAINING

FCI 155
REV 6/86

FIRE SERVICE INCORPORATED

89235

SUBSIDIARY OF FIR. JM INC.
39-27 FIFTY NINTH STREET
WOODSIDE, NEW YORK 11377
(718) 899-2311

REPORT OF FIELD SERVICE

INVOICE TO

SERVICED
7 W.T.C
New York . N.Y

CALL AUTHORIZED BY		CONTRACT #	FEE SERVICE #	FJ #	P.O. #	SEE AT JOB SITE
SHOP		U.P.S= 218				FSP
PHONE	**EXT.**	**DATE SCHEDULED**	**TIME SCHEDULED**			**SERVICEMAN ASSIGNED**
		2-23-00	300 AM			C. Forero C. Tabares

MATERIAL RECORD

QUANTITY ISSUED	QUANTITY B/O	FCI NO	DESCRIPTION	UNIT PRICE	PER	TOTAL AMOUNT

PREVENTIVE MAINTENANCE CONTRACT

CHECK APPROPRIATE BOX

- ☐ Q.C
- ☐ I & T
- ☐ FEE CALL
- ☐ DELIVERY
- ☐ DEMO
- ☐ EMERGENCY CALL
- ☒ CONTRACT CALL
- ☐ PICK UP
- ☐ DEMO OWNER
- ☐ SURVEY

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS	START MILEAGE	END MILEAGE	MISC EXPENSE	CAR FARE
	12.30	300	430					
	PM	AM	PM					

- ☐ MAT REQD
- ☐ PARTIAL
- ☐ OTHER
- ☐ LABOR REQD
- I & T COMPLETE ☐
- CALL COMPLETE ☒

SERVICE DATE: 2-23-00

WILL RETURN ON:

CUSTOMER SIGNATURE: Tony Rubino

SERVICEMAN SIGNATURE: C. Forero

PROBLEM—AS DESCRIBED Preventive maintenance / U.P.S System (10 K)

SERVICE PERFORMED Cleaned and checked U.P.S System took readings
cleaned cabinet, checked 24V mini fans all runing on. Cleaned filters
and batteries, (U.P.S it's operational)
Battery amps = 2A
Total battery voltage 140.9 V. D/C
Output voltage 6.2 HZ
(Load) L-1 = 11.4
L-2 = 11.1

WORK REMAINING Output voltage 250V
Input volts 208V A/C

AUTHORIZATION FOR FIRE ALARM INTERRUPTION

The undersigned has been advised by Fire Service, Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

Name

Date

FCI 155
REV 6186

FIRE SERVICE INCORPORATED

21928

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

FLOOR	LOCATIONS			S/D	CABLE	XMTR	TEST CLEAN
24	CORE	HER D/D		Hochiki	2	231	✓
	CORE	HER D/D.		Hochiki	2	231	✓
	ELEV.	LOB.		BRK	2	001	✓
	FREIGHT ELEV.			BRK	2	001	✓
	COMM	A		BRK	2	172	✓
	ELECT	A		BRK	2	172	✓
	TELEPH	A		BRK	2	172	✓
	COMM	B		BRK	2	172	✓
	ELECT	B		BRK	2	172	✓
	TELEPH	B		BRK	2	172	✓
	RETURN D/D		South	Hochiki	2	230	✓
	RETURN D/D		NORTH.	Hochiki	2	230	✓
	COMM	C		BRK	2	171	✓
	ELECT	C		BRK	2	171	✓
	TELEPH	C		BRK	2	171	✓
	TELEPH	D		BRK	2	171	✓
	ELECT	D		BRK	2	171	✓
	COMM	D		BRK.	2	171	✓
22	PASS ELEV.			BRK	1	021	✓
	FREIGHT ELEV.			BRK.	1	021	✓
	TELEPH.	A		BRK	1	207	✓
	ELECT	A		BRK	1	207	✓
	COMM	A		BRK	1	207	✓
	ELECT	B		BRK	1	207	✓
	COMM	B		BRK	1	207	✓
	TELEPH	B		BRK	1	207	✓
	COMM	C		BRK	1	206	✓
	ELECT	C		BRK	1	206	✓
	TELEPH	C		BRK	1	206	✓
	TELEPH	D		BRK	1	206	✓
	ELECT	D		BRK.	1	206	✓
	COMM	D		BRK	1	206	✓
	CORE	HER D/D	(2)	Hochiki	1	264	✓
	RETURN D/D		(2)	Hochiki	1	265	✓

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 2-23-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☒ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT)

CUSTOMER SIGNATURE [signature]

SERVICEMAN SIGNATURE [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is instituted and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: Contract S/Contract — Test cleaning of Area's Smoke Detectors (Closet's) + H-E-R Duct S/D. + Elevator's Lobbies on Floors (Listed Above). — System Acknowledged Properly. — To continue. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

21927

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREAS		S/D	CABLE	XTNDR	TST CLEAN
25	COMM A		BRK	2	174	✓
	ELECT A		BRK	2	174	✓
	TELEPH A		BRK	2	174	✓
	ELECT B		BRK	2	174	✓
	COMM B		BRK	2	174	✓
	TELEPH B		BRK	2	174	✓
	PASS ELEV.		BRK	2	002	✓
	FREIGHT ELEV		EDW(I)	2	002	✓
	COMM C		BRK	2	174	✓
	ELECT C		BRK	2	174	✓
	TELEPH C		BRK	2	174	✓
	ELECT D		BRK	2	174	✓
	COMM D		BRK	2	174	✓
	TELEPH D		BRK	2	174	✓
	RETURN D/D NORTH		HOCHIKI	2	232	✓
	RETURN D/D SOUTH		HOCHIKI	2	232	✓
	CORE MER D/D		HOCHIKI	2	233	✓
25	CORE MER D/D		HOCHIKI	2	233	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. TORRES / F. ROSARIO	F.S.D.
	DATE SCHEDULED: 2-22-00
CONTRACT #: 51C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM/PM	800 AM	430 PM	AM/PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT):
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

SERVICE PERFORMED & REMAINING: Starting year 2000 / First Semi cleaning testing of smoke detectors which in areas closets / elev lobbies / fan rooms - MER(-) ducts. - As listed. - Check Simulation (ALL) (RESET) bypass function O.K. - Back to normal.

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED

21926

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR			W/STA	Cable	XTNDR	SPK Page
14	HALLWAY		✓	1	325	✓
	CORE HER		✓	1	325	✓
13						
12	HALLWAY		✓	1	323	✓
	CORE HER		✓	1	323	✓
11	HALWAY		✓	1	322	✓
	CORE HER		✓	1	322	✓
10	HALLWAY		✓	1	321	✓
	CORE HER		✓	1	321	✓
9	HALLWAY		✓	1	320	✓
	CORE HER		✓	1	320	✓
8	HALLWAY		✓	1	319	✓
	CORE HER		✓	1	319	✓
7	HALLWAY		✓	1	318	✓
	CORE HER		✓	1	318	✓
6	HALLWAY		✓	1	317	✓
6	HER (FAN RM)		✓✓	1	338	✓
6	ENGNRS- RAN II		✓	1	335	●
5	HALLWAY/SERV. ELEV.		✓	1	336	✓
5	SW GEAR H.V.		✓	1	336	✓
5	HER	NORTH	✓	1	337	✓
5	"	SOUTH	✓	1	337	✓
5	HER	N.W	✓	1	316	
4	'B' EXIT/AREA		✓	1	315	✓
3	F.D. OFF RAN I		✓	1	314	●
2	'A' EXIT (AREA)		✓	1	313	✓
2	HER WEST		✓	1	334	✓
2	T/FRAME AREA		✓	1	334	✓
1	PUMP RM		✓	1	341	✓
1	GROUND ENTRANCE		X	OUT/SERV.		—

INVOICE TO: 7 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. Tokker / F. Rosario	F.D.	
	DATE SCHEDULED: 2.18.00	
CONTRACT #: S/C00 818	TYPE OF SYSTEM: 8500	
FEE SERVICE #	P.O. #	
CALL AUHTORIZED BY	PHONE	EXT

☐ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	330 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN

CUSTOMER SIGNATURE: [signature]

SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME | DATE | TIME

SERVICE PERFORMED & REMAINING: As per contract check/tested for operation warden's phones stations + spkr page on floors 14 to 1st Fl. as listed above) — ④ Ground Floor entrance unit (disabled due to grounded wiring. — (as previous informed)

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE UNIT - OUT — (D) OTHER

FIRE SERVICE INCORPORATED

21925

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS FLOOR			W/STA	SPKRS Page	XDUCR
25	Hallway		✓	✓	282
	Core Her		✓		282
24	Hallway		✓	✓	281
	Core Her		✓		281
23	N/A		No Access		—
22	Hallway		✓	✓	333
	Core Her		✓		333
21	Hallway		✓	✓	332
	Core Her		✓		332
* 20	Hallway		✓	✓	331
	Core Her. *		✓		331
*	Low audibility phone. —				
19	Hallway		✓	✓	330
	Core Her		✓		330
18	Hallway		✓	✓	329
	Core Her		✓		329
17	Hallway		✓	✓	328
	Core Her		✓		328
* 16	Hallway		✓	✓	327
	Core Her *		✓		327
	Low audibility phone. —				
15	Hallway		✓	✓	326
	Core Her		✓		326

To be continued.

INVOICE TO: W.T.C
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.D.
	DATE SCHEDULED: 2-17-00
CONTRACT #: S/C 00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☑ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
800 AM	900 AM	1230 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): [illegible]WEISTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signatures]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME DATE TIME

SERVICE PERFORMED & REMAINING: As per contract - check/test for operations on warden's stations and P.A/Page on floors 25 to 15 as listed above. Floors 20/16 low audibility on phones to be check/increased.
(+) Also as per Firecom — started replacing I.C.'s prom's at F.C.Sta — to delete points on (solomon riser points). — to be continued. —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED 21921

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS		DEVICES					
FLOOR	EXITS		CABLE	M/STA	TST		
25	A		2	036	✓		
	B		2	037	✓		
24	A		2	034	✓		
	B		2	035	✓		
23	A	ACCESS NEEDED					
	B		4	-	MAYOR'S OFFICE		
22	A		2	070	✓		
	B		2	071	✓		
21	A		-	068	✓		
	B			069	✓		
20	A			066	✓		
	B			067	✓		
19	A			064	✓		
	B			065	✓		
18	A			062	✓		
	B			063	✓		
17	A			060	✓		
	B			061	✓		
16	A			058	✓		
	B			059	✓		
15	A			056	✓		
	B			057	✓		
14	A			054	✓		
	B			055	✓		
13	A			052	✓		
	B			053	✓		
12	A			050	✓		
	B			051	✓		
11	A			048	✓		
	B			049	✓		
10	A			046	✓		
	B			047	✓		

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 2-10-00
CONTRACT #: S/C 818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUHTORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☑ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [illegible]
SERVICEMAN SIGNATURE: [illegible]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work.
The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.
NAME / DATE / TIME

SERVICE PERFORMED & REMAINING: Continue S/C. Check/Tested for proper operation manual pull stations (as listed) floors 25 to 10th. - Alarms acknowledged/reset/output functions O.K. - To be continued. -

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

15721

REPORT OF FIELD SERVICE

LOCATIONS			DEVICES			
FLOOR	AREA'S –		S/D	CABLE	XTNDR	TST CLEAN
21	PASS ELEV		BRK	1	020	✓
	FREIGHT ELEV		EDWDS	1	020	✓
	COMM A		BRK	1	204	✓
	ELECT A		BRK	1	204	✓
	TELEPH A		BRK	1	204	✓
	ELECT B		BRK	1	204	✓
	COMM B		BRK	1	204	✓
	TELEPH B		BRK	1	204	✓
	ELECT C		BRK	1	205	✓
	COMM C		BRK	1	205	✓
	TELEPH C		BRK	1	205	✓
	COMM D		BRK	1	205	✓
	ELECT D		BRK	1	205	✓
	TELEPH D		BRK	1	205	✓
	CORE HEF D/D (2)		Hochiki	1	264	✓
	RETURN D/D NORTH		Hochiki	1	263	✓
(+)	RETURN D/D SOUTH		Hochiki	1	263	LED
20	COMM A-B	(2)	BRK	1	203	
	ELECT A-B	(2)	BRK	1	203	
	TELEPH A-B	(2)	BRK	1	203	
	TELEPH C-D	(2)	BRK	1	202	
	COMM C-D	(2)	BRK	1	202	
	ELECT C-D	(2)	BRK	1	202	
	PASS ELEV.		BRK	1	019	✓
	FREIGHT ELEV.		EDWDS	1	019	
	PLENUM RETURN NORTH		Hochiki	1	261	
	PLENUM D/D RET SOUTH		Hochiki	1	261	
	PLENUM D/D RET EAST		Hochiki	3	045	✓

PREVENTIVE MAINTENANCE CONTRACT

INVOICE TO: 2 W.T.C.
N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE
J. Torres / F. Rosanio	F.S.D
	DATE SCHEDULED: 2-29-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O #
CALL AUTHORIZED BY	PHONE / EXT

☑ MAINTENANCE ☑ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during this period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of fire protection service during their service of the equipment.

NAME

DATE

TIME

SERVICE PERFORMED & REMAINING: Continuing S/Contract on Smoke Detection units on FLRS 21 + 20 (Above Listed Locations) – Cleaned + Tested. –
(+) NOTE: Return duct detector South side on 21st Fl. (Need LED - Broken). –
(+) Also check/Bypass function on duct S/D Return unit 20th Fl (Cable 3 – Code 045 East Side. – System Ack/Reset Back to Operation

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

FIRE SERVICE INCORPORATED
Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

21919

REPORT OF FIELD SERVICE

FLOOR	A	B	C		MANUAL STA.	CABLE	XTNDR TST
35	056	057	195		✓✓	2	✓
34	054	055			✓✓	2	✓
33	053	052			✓✓	2	✓
32	051	050			✓✓	2	✓
31	048	049			✓✓	2	✓
30	046	047			✓✓	2	✓
29	044	045			✓✓	2	✓
28	042	043			✓✓	2	✓
27	040	041			✓✓	2	✓
27	040 → EAST Corridor				✓	2	✓
26	038	039			✓✓	2	✓
26	038 → EAST Corridor				✓	2	✓

41st "B" EXIT M/STATION 069 N/G – FIELD WIRING OPEN. – FOREST ELECT. NOTIFIED TO RUN WIRING / to TTB on 42nd Fl. – (Floor under Construction). –

INVOICE TO: 7 W.T.C.
N.Y.C

SERVICEMAN ASSIGNED	SEE AT JOB SITE
G. Torres / F. Rosario	F.S.D.
	DATE SCHEDULED: 2-2-00
CONTRACT #: S/C00818	TYPE OF SYSTEM: 8500
FEE SERVICE #	P.O. #
CALL AUTHORIZED BY	PHONE / EXT

☐ MAINTENANCE ☒ TEST
☒ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	800 AM	430 PM	AM PM	

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: Contract Stewart Check / Testing Manual pull Stations Alarm's / activation on Floors (above Listed). –
NOTE: 41st Fl. "B" EXIT UNIT Removed / Wiring Cut / Floor Under Construction. – Forest Electric Notified Unit to be Restored / Rewired on Location. –

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold harmless Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

FIRE SERVICE INCORPORATED 21918

Subsidiary of Firecom, Inc.
39-27 Fifty Ninth Street
Woodside, New York 11377
(718) 899-2311

REPORT OF FIELD SERVICE

LOCATIONS	DEVICES						
FLOOR	EXIT A	EXIT B	EXIT C		CABLE	XTNDR	M/STA
48	147				2	147	✓✓
47	080	081	082		2		✓✓✓
47	FITNESS AREA				2	084	✓✓
46	079	078	—		2		✓✓
45	076	077	—		2		✓✓
44	074	075	—		2		✓✓
43	072	073			2		✓✓
42	071	070	199-4		2		✓✓✓
41	068	069	198-4		2		X✓✓
40	067	066	197-4		2		✓✓✓
39	065	064	193-4		2		✓✓✓
39	AUDITORIUM EXIT				4	194	✓✓
38	062	063	192-4		2		✓✓✓
37	060	061	145-4		2		✓✓✓
36	058	059	144-4		2		✓✓✓
	* → 058 A EXIT - N/G - BROKEN S/W.						
		TAMPER'S			TEST	OK	
46	PUMP RM	153 - 152			✓		
46	"	151 - 150			✓		
46	"	149 - 148			✓		
41st	M/STA 069 'B' EXIT WIRING CUT / OPEN FIELD WIRING OPEN / UNIT ZENERED. —						

INVOICE TO: 7 W.T.C. N.Y.C.

SERVICEMAN ASSIGNED	SEE AT JOB SITE	
J. TORRES / F. ROSARIO	7-5-4	
	DATE SCHEDULED: 2-1-00	
CONTRACT #: 5/C00 818	TYPE OF SYSTEM: 8500	
FEE SERVICE #	P.O. #	
CALL AUTHORIZED BY	PHONE	EXT

☒ MAINTENANCE ☒ TEST
☐ JOB COMPLETE ☐ JOB INCOMPLETE
☐ SYSTEM ON LINE ☐ SYSTEM OFF LINE

DEPARTED SHOP	TIME IN	TIME OUT	RETURNED SHOP	TOTAL HOURS
AM PM	8:00 AM	4:30 PM	AM PM	

AUTHORIZATION FOR FIRE ALARM INTERRUPTION
The undersigned has been advised by Fire Service Inc. representative that it may be necessary to interrupt the fire protection service by disconnecting the system and/or a component in the performance of their assigned work. The undersigned hereby assumes the responsibility for the notification of the authorities at the time the interruption is initiated and will take all of the precautions deemed necessary during the period of interruption and hold [illegible] Fire Service Inc. and its employees regarding interruption of the protection service during their service of the equipment.

NAME DATE TIME

MATERIAL RECORD

QUANTITY	DESCRIPTION	COST
	PREVENTIVE MAINTENANCE CONTRACT	-

CUSTOMER NAME (PRINT): SILVERSTEIN
CUSTOMER SIGNATURE: [signature]
SERVICEMAN SIGNATURE: [signature]

SERVICE PERFORMED & REMAINING: As per Contract check tested for proper alarm / reset operating manual pull stations on floors 48 to 36 at listed location / cable - XTNDR'S - codes - amount —
NOTE: 36th FL. 'A' EXIT UNIT #058 NOT OPERATING - BROKEN S/W - MUST BE REPAIRED. — SYSTEM ALL TESTED. —
ALSO TESTED TAMPER'S ON 46th FL PUMP ROOM - —

(A) INACCESSIBLE (B) MISSING (C) DEFECTIVE (D) OTHER

124-5



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT EP = EXPLOSION PROOF
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR EP = EXPLOSION PROOF
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
(J)	JUNCTION BOX
LPC	LOW PRESSURE COMPRESSURE
LP	LOW PRESSURE SWITCH
H	HORN EP = EXPLOSION PROOF

REV	DATE	BY	DESCRIPTION
3	11/10/98	C.S.	ADDED (1) INTERGIN FIRE SYS. CONTROL PANEL ON 1ST FL. FOR "MAYORS OFFICE" PER FJ-64637-02.
2	9/29/98	C.S.	ADDED (1) HORN, (1) STROBE & (1) HEAT DET. ON 1ST FL. PER FJ-64637.
1	8/25/98	C.S.	RISER REDRAWN. SEE DWG# E-504111-1 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
~~1ST FLOOR~~

CONTRACTOR | ENGINEER

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	8/25/98
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-01
REV	3

OOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT EP = EXPLOSION PROOF
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR EP = EXPLOSION PROOF
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
J	JUNCTION BOX
LPC	LOW PRESSURE COMPRESSURE
LP	LOW PRESSURE SWITCH
H	HORN EP = EXPLOSION PROOF

REV	DATE	BY	DESCRIPTION
2	05/04/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 1ST FL. PER LJ-80208.
1	8/25/98	CS	RISER REDRAWN. SEE DWG# E-504111-1 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
1ST FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	8/25/98
SCALE	N.T.S.
SHEET	2
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-01

1ST FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
PH	PHOTO HEAT/SMOKE DETECTOR

REV	DATE	BY	DESCRIPTION
1	05/01/00	JM	RISER REDRAWN. SEE DWG# E-504111-1 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
2ND FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	05/01/00
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-02
REV	1

2ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT EP = EXPLOSION PROOF
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR EP = EXPLOSION PROOF
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
J	JUNCTION BOX
ER	ELEVATOR RECALL JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
2	05/04/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 2ND FL. PER LJ-80208.
1	05/02/00	JM	RISER REDRAWN. SEE DWG# E-504111-1 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
2ND FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	05/02/00
SCALE	N.T.S.
SHEET	2
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-02

2ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

REV	DATE	BY	DESCRIPTION
4	10/10/00	JM	ADDED (5) SPKR/STRBS. FOR 'STANDARD CHARTER' PER LJ-80452.
3	8/30/99	CS	ADDED (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN & (1) AREA SMK. DET. ON 13TH FL. FOR 'STANDARD CHARTER' PER FJ-65220-01.
2	7/9/99	CS	ADDED (6) SPEAKERS, (5) STROBES & (1) RELAY FOR DOOR RELEASE ON 13TH FL. FOR 'STANDARD CHARTER' PER FJ-65220.
1	7/9/99	CS	RISER REDRAWN. SEE DWG# E-504111-2 SH. 2 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
13TH FLOOR

DWN	L.H.
APP'D	
ENGR	C.S.
CKD	
DATE	7/9/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	4
JOB#	FJ-26840
DWG#	B-504111-13

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377



7TH FLOOR

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
PH	PHOTO HEAT/SMOKE DETECTOR

REV	DATE	BY	DESCRIPTION
2	9/13/99	C.S.	ADDED (1) SPKR./STRB. & (1) RELAY FOR DOOR RELEASE ON 7TH FL. FOR "AMEX" PER FJ-65298.
1	9/13/99	C.S.	EXT. TTB#22A (D-506284-A) & ASSOCIATED DEVICES TRANFERRED FROM DWG. B-504111-07 SH. #1 TO THIS DWG

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

~~PARTIAL RISER DIAGRAM~~
7TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
CHKR	C.S.
CKD	
DATE	9/13/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-07



7TH FLOOR

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
PH	PHOTO HEAT/SMOKE DETECTOR

REV	DATE	BY	DESCRIPTION
6	11/15/99	C.S.	ADDED (4) SPKR./STRBS., (1) PHOTO HEAT/ SMK. DET., (1) DUCT SMK. DET., (1) RELAY FOR FAN SHUTDOWN & (2) RELAYS FOR DAMPER CONTROL ON 7TH FL. FOR "AMEX" PER FJ-65418.
5	9/15/99	C.S.	EXT. TTB #22A (D-506284-A) & ASSOCIATED DEVICES TRANSFERRED FROM THIS DWG. TO DWG #B-504111-07 SH #2
4	1/20/99	C.S.	ADDED (5) SPKR./STRBS. (5) STRBS.,(1) MANUAL-PULL STATION (1) RELAY FOR DOOR RELEASE & (1) AREA SMK. DET. ON 7TH FL. FOR "MAYORS OFFICE" PER FJ-64918.
3	11/21/98	C.S.	REPLACED (2) HEAT DETECTORS WITH (7) PHOTO HEAT/SMK DETS. & ADDED (1) SPKR. STROBE ON 7TH FL. PER FJ-64637.
2	9/9/98	C.S.	ADDED (2) HEAT DETS. & (3) SPKR./STRBS ON 7TH FL PER FJ-64637.
1	8/25/98	C.S.	RISER REDRAWN. SEE DWG# E-504111-1 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
7TH FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	8/25/98
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-07
REV	6



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
1	7/7/99	C.S	RISER REDRAWN SEE DWG# E-504111-2 SH. 2 FOR REFERENCING PAST REVISIONS

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
13TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
CHKD	C.S.
CKD	
DATE	7/9/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-13
REV	1

CONTRACTOR
ENGINEER

13TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
SS	SUB-SYSTEM
CD	COMBINATION SMOKE & HEAT DETECTOR
J	JUNCTION BOX

REV	DATE	BY	DESCRIPTION
1	03/02/01	JM	RISER REDRAWN. SEE DWG# E-504111-2 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR: | ENGINEER:

PARTIAL RISER DIAGRAM
20TH FLOOR
"SALOMON SMITH BARNEY"

FIRECOM, INC.
CASE/ACME
30-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	03/02/01
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-20
REV	

20TH FLOOR





LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

REV	DATE	BY	DESCRIPTION
2	03/02/01	JM	ADDED (2) SPEAKER/STROBES PER LJ-80656.
1	03/02/01	JM	RISER REDRAWN. SEE DWG# E-504111-2 SH. 2 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
20TH FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	03/02/01
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-20
REV	2

20TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

REV	DATE	BY	DESCRIPTION
1	04/11/01	JM	RISER REDRAWN. SEE DWG# E-504111-2 SH. 3 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
22ND FLOOR

DSN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	04/11/01
SCALE	N.T.S.
SHEET	1
OF	2
REV	1
JOB#	FJ-26840
DWG#	B-504111-22

CONTRACTOR | ENGINEER

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

22ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
(J)	JUNCTION BOX
(CD)	COMBINATION SMOKE & HEAT DETECTOR
SS	SUB-SYSTEM

REV	DATE	BY	DESCRIPTION
2	04/11/01	JM	ADDED (1) DUCT SMK. DET. & (1) RELAY FOR FAN SHUTDOWN FOR "FEDERAL HOME LOAN" PER LJ-80739.
1	04/11/01	JM	RISER REDRAWN. SEE DWG# E-504111-5 SH. 3 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
22ND FLOOR

DRN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	04/11/01
SCALE	N.T.S.
SHEET	2
OF	2
REV	7
JOB#	FJ-26840
DWG#	B-504111-22

CONTRACTOR | ENGINEER

FIRECOM, INC. CASE/ACME

22ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
UF	UNDER FLOOR DETECTOR
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
ER	ELEVATOR RECALL JUNCTION BOX
EA	ELEVATOR ADVANCE
	REMOTE INDICATING LAMP

REV	DATE	BY	DESCRIPTION
8	10/6/99	C.S.	REPLACED (1) RELAY FOR DOOR RELEASE ON 23RD FL. FOR "OEM" PER FJ-64914-01.
7	1/20/99	C.S.	ADDED (1) RELAY FOR DOOR RELEASE ON 23RD FL. FOR "OEM" PER FJ-64914.
6	12/28/98	C.S.	ADDED (2) MANUAL PULL STATIONS ON 23RD FL. FOR 'MAYORS OFFICE' PER FJ-64899.
5	12/11/98	C.S.	REPLACED (3) DUCT DETS WITH (3) HIGH VELOCITY AREA DETS. PER FJ-64637
4	11/20/98	C.S.	DELETED (1) PRESSURE SWITCH, (2) TAMPER SWITCH & (2) WATER FLOW SWITCH. REPLACED (7) PHOTO HEAT/SMK DETS. WITH (2) HEAT DETS. ADDED (2) ELEV. LOB. DETS. & (1) AREA SMK. DET. ADDED PRESSURE SWITCH (TROUBLE) CONN TO PRE-ACTION SYSTEMS ON 23RD FL. FOR 'MAYORS OFFICE' PER FJ-64637
3	11/10/98	C.S	ADDED (1) PRE-ACTION SYSTEM ON 23RD FL. FOR 'MAYORS OFFICE' PER FJ-64637-02.
2	9/29/98	C.S.	ADDED (1) PAD-2 STRB PNL., (28) SPKR./STROBES., (7) STRBS., (6) DUCT SMK. DETS., (6) RELAYS FOR AC SHUTDOWN, (1) RELAY FOR DOOR RELEASE, (1) PRESSURE SWITCH, (2) TAMPER SWITCH, (2) WATER FLOW, SWITCH, (42) UNDER FLOOR DETS., (1) PRE-ACTION SYSTEM, (2) AREA SMK. DETS., (7) PHOTO HEAT/SMK. DETS. & (42) INDICATING LAMPS ON 23RD FLOOR PER FJ-64637
1	8/26/98	C.S.	RISER REDRAWN SEE DWG# E-504111-3 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
23RD FLOOR

DRN	L.H.
APPVD	
CHKR	C.S.
CKD	
DATE	8/26/98
SCALE	N.T.S.
SHEET	1
OF	1
JOB	FJ-26840
DWG#	B-504111-23
REV	8

CONTRACTOR | ENGINEER

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER

REV	DATE	BY	DESCRIPTION
2	09/20/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 24TH FL. PER LJ-80431
1	09/20/00	JM	RISER REDRAWN. SEE DWG# E-504111-2 SH. 2 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
24TH FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DRN	L.H.
APP'D	
ENGR	J.M.
CKD	
DATE	09/20/00
SCALE	N.T.S.
SHEET	1
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-24

24TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR

24TH FLOOR

REV	DATE	BY	DESCRIPTION
1	09/20/00	JM	RISER REDRAWN. SEE DWG# E-504111-3 SH. 3 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
24TH FLOOR

DWN	L.H.
APPVD	
CHKR	J.M.
CKD	
DATE	09/20/00
SCALE	N.T.S.
SHEET	2
OF	2
REV	1
JOB#	FJ-26840
DWG#	B-504111-24

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
ER	ELEVATOR RECALL JUNCTION BOX
EA	ELEVATOR ADVANCE

MAY 1 8 2000

REV	DATE	BY	DESCRIPTION
1	05/16/00	JM	RISER REDRAWN. SEE DWG# E-504111-3 FOR REFERENCING PAST REVISIONS

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DRWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	05/16/00
SCALE	N.T.S.
SHEET	1
OF	2
REV	1

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
30TH FLOOR
"SILVERSTEIN"

FIRECOM, INC. CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-30

30TH FLOOR



THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
(SS)	SUB-SYSTEM
(CD)	COMBINATION SMOKE & HEAT DETECTOR
(J)	JUNCTION BOX

MAY 18 2000

REV	DATE	BY	DESCRIPTION
2	05/16/00	JM	ADDED (1) RELAY DAMPER CONTROL & (6) STROBES. REPLACED (1) EXIST. STRB. WITH (1) NEW STRB. FOR 'SALOMON SMITH BARNEY' PER LJ-80228.
1	05/16/00	JM	RISER REDRAWN. SEE DWG# E-504111-3 FOR REFERENCING PAST REVISIONS.

THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
30TH FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	05/16/00
SCALE	N.T.S.
SHEET	2
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-30

30TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
ER	ELEVATOR RECALL JUNCTION BOX
EA	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
1	04/26/00	JM	RISER REDRAWN. SEE DWG# E-504111-4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
31ST FLOOR
'SILVERSTEIN'

DWN: L.H.
APPVD:
ENGR: J.M.
CKD:
DATE: 04/26/00
SCALE: N.T.S.
SHEET: 1 OF 2
REV: 1

CONTRACTOR: ENGINEER:

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB#: FJ-26840
DWG#: B-504111-31

31ST FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
(SS)	SUB-SYSTEM
(CD)	COMBINATION SMOKE & HEAT DETECTOR
(J)	JUNCTION BOX

REV	DATE	BY	DESCRIPTION
3	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 31ST FL. PER LJ-80208.
2	04/26/00	JM	ADDED (6) STROBES & (1) RELAY FOR DAMPER CONTROL FOR 'SALOMON SMITH BARNEY' PER LJ-80205.
1	04/26/00	JM	RISER REDRAWN. SEE DWG# E-504111-4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
31ST FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	04/26/00
SCALE	N.T.S.
SHEET	2
OF	2
REV	3
JOB#	FJ-26840
DWG#	B-504111-31

CONTRACTOR | ENGINEER

31ST FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
ER	ELEVATOR RECALL JUNCTION BOX
EA	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
1	04/26/00	JM	RISER REDRAWN. SEE DWG# E-504111-4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
32ND FLOOR
'SILVERSTEIN'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	04/27/00
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-32
REV	1

32ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
▷□◁	BI-DIRECTIONAL SPEAKER
(SS)	SUB-SYSTEM
(CD)	COMBINATION SMOKE & HEAT DETECTOR
(J)	JUNCTION BOX

REV	DATE	BY	DESCRIPTION
3	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 32ND FL. PER LJ-80208.
2	04/26/00	JM	ADDED (6) STROBES & (1) RELAY FOR DAMPER CONTROL FOR 'SALOMON SMITH BARNEY' PER LJ-80204.
1	04/26/00	JM	RISER REDRAWN. SEE DWG# E-504111-4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
32ND FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	J.M.
CKD	
DATE	04/27/00
SCALE	N.T.S.
SHEET	2
OF	2
REV	3
JOB	FJ-26840
DWG	B-504111-32

32ND FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

33RD FLOOR

REV	DATE	BY	DESCRIPTION
1	9/13/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
33RD FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	9/13/99
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-33
REV	1



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR
SS	SUB-SYSTEM

REV	DATE	BY	DESCRIPTION
4	05/05/00	J.M.	ADDED (1) RELAY FOR DOOR RELEASE ON 33RD FL. PER LJ-80208.
3	12/2/99	J.M.	ADDED (1) SPKR/STRB. ON 33RD FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65307-01.
2	9/13/99	C.S.	ADDED (3) SPKR/STRBS. & (2) STROBES FOR "SOLOMON SMITH BARNEY" PER FJ-65307.
1	9/13/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
33RD FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	9/13/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-33
REV	4

33RD FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

REV	DATE	BY	DESCRIPTION
6	06/08/00	JM	TRANFERRED (4) SPKR./STRBS. FROM SH.1 TO SH. 2 PER FIELD CONDITIONS
5	9/23/99	CS	DELETED (2) AREA SMK. DETS., (1) DUCT SMK. DETS., (1) RELAY FOR FAN SHUTDOWN, (1) PRE-ACTION PNL. & (1) STRB. FROM TTB #15 D-504319 & TRANSFERRED TO TTB #25B D-505652. DELETED (1) MANUAL STATION FROM TTB #15 D-504319 & TRANSFERRED TO TTB #25A D-504948-11 PER FJ-65149.
4	9/23/99	CS	CORRECTED FLOOR PAGE CKTS. FROM 'A' & 'B' TO 'C' & 'D' PER FIELD CONDITIONS.
3	6/25/99	CS	ADDED (4) SPKR./STRBS. ON 36TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65150.
2	6/24/99	CS	ADDED (2) AREA SMK. DETS., (1) DUCT SMK. DET., (1) RELAY FOR FAN SHUTDOWN, (1) MANUAL PULL STATION, (1) PRE-ACTION PNL. & (1) STRB. ON 36TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65149.
1	6/24/99	CS	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
36TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
CHKR	C.S.
CKD	
DATE	6/24/99
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-36
REV	6

36TH FLOOR



THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

JUN 0 9 2000

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR
SS	SUB-SYSTEM

REV	DATE	BY	DESCRIPTION
5	06/08/00	JM	ADDED (5) STRBS. FOR "SALOMON SMITH BARNEY" PER LJ-80277.
4	06/08/00	JM	TRANSFERRED (4) SPKR./STRBS. FROM SH. 1 TO SH. 2 PER FIELD CONDITIONS.
3	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 36TH FL. PER LJ-80208.
2	9/23/99	CS	TRANSFERRED (2) AREA SMK. DETS., (1) DUCT SMK. DETS., (1) RELAY FOR FAN SHUTDOWN, (1) PRE-ACTION PNL. & (1) STRB. FROM TTB#15 D-504319 TO TTB #25B D-505652. TRANSFERRED (1) MANUAL STATION FROM TTB#15 D-504319 TO TTB #25A D-504948-11 PER FJ-65149.
1	6/24/99	CS	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
36TH FLOOR

DRWN	L.H.
APPVD	
CHGR	C.S.
CKD	
DATE	6/24/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	5
JOB	FJ-26840
DWG	B-504111-36

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

36TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
ER	ELEVATOR RECALL JUNCTION BOX
SS	SUB-SYSTEM
EA	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
1	6/24/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
37TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-37

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	6/24/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	1

37TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
6	09/11/00	JM	ADDED (2) SPKR/STRBS., (1) STROBE FOR 'SALOMON SMITH BARNEY' PER LJ-80417.
5	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 37TH FL. PER LJ-80208.
4	7/2/99	CS	ADDED (2) STROBES ON 37TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65204.
3	7/2/99	CS	CORRECTED FLOOR PAGE CKTS. FROM 'A & 'B' TO 'C' & 'D' PER FIELD CONDITIONS.
2	6/24/99	CS	ADDED (1) STROBE ON 37TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65147.
1	6/24/99	CS	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
37TH FLOOR

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	6/24/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-37.
REV	6

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

37TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
(J)	JUNCTION BOX
(CD)	COMBINATION SMOKE & HEAT DETECTOR
SS	SUB-SYSTEM

REV	DATE	BY	DESCRIPTION
3	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 38TH FL. PER LJ-80208.
2	7/2/99	CS	ADDED (2) STROBES ON 38TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65204.
1	7/2/99	CS	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
38TH FLOOR

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/2/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-38
REV	3

38TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH

REV	DATE	BY	DESCRIPTION
5	11/14/00	JM	ADDED (3) SPKR./STRBS. & REPLACED (14) EXIST. SPKR./STRBS. FOR 'SALOMON SMITH BARNEY' PER LJ-80504.
4	9/23/99	C.S.	DELETED (2) AREA SMK. DETS., (1) DUCT SMK. DETS., (1) RELAY FOR FAN SHUTDOWN, (1) PRE-ACTION PNL. & (1) STRB. FROM TTB #16 D-504320 & TRANSFERRED TO TTB #26B D-504948-14. DELETED (1) MANUAL STATION FROM TTB#16 D-504320 & TRANSFERRED TO TTB #26A 504948-13 PER FJ-65149.
3	6/25/99	C.S.	ADDED (1) STROBE, (2) AREA SMK. DETS., (1) DUCT SMK. DET., (1) RELAY FOR FAN SHUTDOWN, (1) MANUAL PULL STATION & (1) PRE-ACTION PNL. ON 39TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65149.
2	6/16/99	C.S.	ADDED (3) SPEAKER/STROBES, (2) STROBES, (6) DUCT SMK. DETS., (6) RELAYS FOR FAN SHUTDOWN & (2) RELAYS FOR DAMPER CONTROL ON 39TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65162.
1	6/16/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
39TH FLOOR

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	6/16/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	5
JOB#	FJ-26840
DWG#	B-504111-39

CONTRACTOR — ENGINEER

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

39TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
SS	SUB-SYSTEM
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
4	11/22/00	JM	ADDED (1) SPKR/STRB., (1) STRB., (3) DUCT SMK. DETS., (3) RELAYS FOR FAN SHUTDOWN & (3) RELAYS FOR DAMPER CONTROL FOR "SALOMON SMITH BARNEY" PER LJ-80504-01.
3	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 39TH FL. PER LJ-80208.
2	9/23/99	CS	TRANSFERRED (2) AREA SMK. DETS., (1) DUCT SMK. DETS., (1) RELAY FOR FAN SHUTDOWN, (1) PRE-ACTION PNL. & (1) STRB. FROM TTB#16 D-504320 TO TTB #26B D-504948-14. TRANSFERRED (1) MANUAL STATION FROM TTB#16 D-504320 TO TTB #26A D-504948-13 PER FJ-65149.
1	6/16/99	CS	RISER REDRAWN. SEE DWG# E-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DRN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	6/16/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	4

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
39TH FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-39

39TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
▷□◁	BI-DIRECTIONAL FLOOR SPEAKERS
FS	FAN STATUS

40TH FLOOR

REV	DATE	BY	DESCRIPTION
2	3/13/00	JM	MODIFIED AS PER FJ-65296.
1	7/2/99	JM	RISER REDRAWN. SEE DWG# 2-504111-4 SH. 4 FOR REFERENCING PAST REVISIONS

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
40TH FLOOR
"SILVERSTEIN"

FIRECOM, INC.
CASE/ACME
[redacted]
WOODSIDE, NEW YORK 11377

DWN	L.H.
APP'D	
ENGR	C.S.
CKD	
DATE	7/2/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-40



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
11	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE PER LJ-80208.
10	04/24/00	JM	ADDED (2) PRE-ACTION PNLS. FOR 'SALOMON SMITH BARNEY' PER LJ-80202.
9	03/13/00	JM	MODIFIED AS PER FJ-65296.
8	03/09/00	JM	DELETED FIRE ALARM CONTROL PNL. WITH UNDER FLOOR DETS. & GRAPHIC ANN. PNL. FOR UNDER FLOOR DET. PER LJ-80051.
7	02/02/00	JM	ADDED (3) SPKR/STRB ON 40TH FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80045-01.
6	01/31/00	JM	DELETED SUB-SYSTEM, FAN STATUS & FAN SHUTDOWN FROM 40TH FL. PER LJ-80061.
5	01/07/00	JM	ADDED (1) DUCT SMK. DET. & (1) RELAY FOR FAN SHUTDOWN ON 40TH FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80049.
4	01/06/00	CS	ADDED (18) SPKR/STRBS, (1) AREA SMK. DET., (5) RELAYS FOR DAMPER CONTROL & (1) RE-LAY FOR DOOR RELEASE ON 40TH FL. FOR 'SALO-MON SMITH BARNEY' PER LJ-80045.
3	9/18/99	CS	ADDED (1) PAD-2 STRB. PNL., (4) SPKR/STRBS, (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN, (17) AREA SMK. DETS. & (1) WARDEN STATION ON 40TH FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65296.
2	7/2/99	CS	ADDED (2) STROBES ON 40TH FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65204.
1	7/2/99	CS	RISER REDRAWN. SEE DWG# E-50410-4 SH. 4 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/2/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	11

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
40TH FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-40

40TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
FS	FAN STATUS

41ST FLOOR

REV	DATE	BY	DESCRIPTION
2	3/13/00	JM	MODIFIED AS PER FJ-65296.
1	7/6/99	CS	RISER REDRAWN. SEE DWG# B-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
41ST FLOOR
"SILVERSTEIN"

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/6/99
SCALE	N.T.S.
SHEET	1
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-41



41ST FLOOR

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER
Ⓐ	AREA SMOKE DETECTOR
Ⓔ	ELEVATOR LOBBY DETECTOR
Ⓗ	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
Ⓓ	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
9	05/05/00	J.M.	ADDED (1) RELAY FOR DOOR RELEASE ON 41ST FL. PER LJ-80208.
8	04/24/00	J.M.	ADDED (2) PRE-ACTION PANELS FOR 'SALOMON BARNEY' PER LJ-80202.
7	03/13/00	J.M.	MODIFIED AS PER FJ-65296.
6	03/09/00	J.M.	DELETED PRE-ACTION PNL. & ANSUE SYSTEM ON 41ST FL. PER LJ-80061.
5	01/31/00	J.M.	DELETED SUB-SYSTEM, DUCT DETS., FAN SHUT-DOWN & COMBINATION SMK. & HEAT DETS. FROM 41ST FL. PER LJ-80061.
4	01/06/00	J.M.	ADDED (21) SPKR./STRBS., (1) AREA SMK. DETS. & (5) RELAYS FOR DAMPER CONTROL ON 41ST FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80046
3	9/18/99	C.S.	ADDED (1) PAD-2 STRB. PNL., (4) SPKR./STRBS., (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN, (17) AREA SMK. DETS. & (1) WARDEN STATION ON 41ST FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65296.
2	7/6/99	C.S.	ADDED (2) STROBES ON 41ST FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65204.
1	7/6/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
41ST FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

DSN	L.H.
APP'D	
CHGR	C.S.
CKD	
DATE	7/6/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-41
REV	9



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
FS	FAN STATUS

42ND FLOOR

REV	DATE	BY	DESCRIPTION
2	3/13/00	JM	MODIFIED AS PER FJ-65296.
1	7/6/99	CS	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DWN: L.H.
APP'D:
ENGR: C.S.
CHKD:
DATE: 7/6/99
SCALE: N.T.S.
SHEET: 1
OF: 2
REV: 2

CONTRACTOR: | ENGINEER:

PARTIAL RISER DIAGRAM
42ND FLOOR
'SILVERSTEIN'

FIRECOM, INC.
CASE/ACME
WOODSIDE, NEW YORK 11377

JOB#: FJ-26840
DWG#: B-504111-42



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□⊗	COMB. SPKR/STROBE
▷□	SPEAKER
Ⓐ	AREA SMOKE DETECTOR
Ⓔ	ELEVATOR LOBBY DETECTOR
Ⓗ	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
Ⓓ	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
⊣	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
Ⓙ	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR

REV	DATE	BY	DESCRIPTION
10	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 42ND FL. PER LJ-80208.
9	04/24/00	JM	ADDED (2) PRE-ACTION PANELS FOR 'SALOMON SMITH BARNEY' PER LJ-80202.
8	03/13/00	JM	MODIFIED AS PER FJ-65296.
7	02/02/00	JM	ADDED (2) RELAYS FOR DAMPER CONTROL, DELETED (2) AREA SMK. DETS. & (3) SPKR./STROBES FROM 42ND FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80048-01.
6	01/31/00	JM	DELETED SUB-SYSTEM, FAN STOP STATUS & FAN SHUTDOWN FROM 42ND FL. PER LJ-80061.
5	01/10/00	JM	ADDED (1) DUCT SMK. DET. & (1) RELAY FOR FAN SUTDOWN ON 42ND FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80049.
4	01/07/00	JM	ADDED (21) SPKR./STRBS., (3) AREA SMK. DETS., (4) RELAYS FOR DAMPER CONTROL, (19) DAMPERS,(1) RELAY FOR DOOR RELEASE & (1) EXT. TTB ON 42ND FL. FOR 'SALOMON SMITH BARNEY' PER LJ-80048.
3	9/18/99	CS	ADDED (1) PAD-2 STRB. PNL., (4) SPKR./STRBS., (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN, (17) AREA SMK. DETS. & (1) WARDEN STATION ON 42ND FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65296.
2	7/6/99	CS	ADDED (2) STROBES ON 42ND FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65204.
1	7/6/99	CS	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

DWN	L.H.
APPD	
ENGR	C.S.
CKD	
DATE	7/6/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	10

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
42ND FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

JOB# FJ-26840
DWG# B-504111-42



LEGEND	
SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR R = RETURN
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
FS	FAN STATUS

REV	DATE	BY	DESCRIPTION
3	03/23/00	JM	ADDED (2) MANUAL PULL STATIONS PER LJ-8043
2	03/13/00	JM	MODIFIED AS PER FJ-65296.
1	07/09/99	CS	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
43RD FLOOR
"SILVERSTEIN"

DRWN	L.H.
APPVD	
ENGR	C.S.
CKD	
CONTRACTOR	
ENGINEER	
DATE	7/9/99
SCALE	N.T.S.
SHEET	1
OF	2
JOB#	FJ-26840
DWG#	B-504111-43
REV	3

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

43RD FLOOR

124-5



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□⊗	COMB. SPKR/STROBE
▷□	SPEAKER
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
┤	END OF LINE RESISTOR
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
(CD)	COMBINATION SMOKE & HEAT DETECTOR
(ER)	ELEVATOR RECALL JUNCTION BOX
(EA)	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
9	05/05/00	J.M.	ADDED (1) RELAY FOR DOOR RELEASE ON 43RD FL. PER LJ-80208.
8	04/24/00	J.M.	ADDED (2) PRE-ACTION PANELS FOR 'SALOMON SMITH BARNEY' PER LJ-80202.
7	03/22/00	J.M.	ADDED (1) PAD-2 STRB. PNL., (24) SPKR./STRBS., (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN, (5) AREA SMK. DETS. & (1) TAMPER SWITH, (1) WATERFLOW SWITCH, (1) RELAY FOR DOOR RELEASE & (5) RELAYS FOR DAMPER CONTROL FOR SALOMON SMITH BARNEY' PER LJ-80143.
6	03/13/00	J.M.	MODIFIED AS PER FJ-65296.
5	03/09/00	C.S.	DELETED PRE-ACTION PNL. (SUB-SYSTEM) FROM THE 43RD FL. PER LLLJ-80061.
4	01/31/00	C.S.	DELETED FAN SHUTDOWN, DUCT SMK. DETS., SUB-SYSTEM & COMBINATION SMK. & HEAT DETS. FROM 43RD FL. PER LJ-80061.
3	9/18/99	C.S.	ADDED (1) PAD-2 STRB. PNL., (4) SPKR./STRBS., (2) DUCT SMK. DETS., (2) RELAYS FOR FAN SHUTDOWN, (17) AREA SMK. DETS. & (1) WARDEN STATION ON 43RD FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65296.
2	7/9/99	C.S.	ADDED (2) STROBES ON 43RD FL. FOR 'SALOMON SMITH BARNEY' PER FJ-65204.
1	7/9/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
43RD FLOOR
'SALOMON SMITH BARNEY'

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/9/99
SCALE	N.T.S.
SHEET	2
OF	2
JOB#	FJ-26840
DWG#	B-504111-43
REV	9

124-5



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
▷□ ⊗	COMB. SPKR/STROBE
▷□	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
⊠	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
—{	END OF LINE RESISTOR
▶□	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
▷□◁	BI-DIRECTIONAL SPEAKER
(ER)	ELEVATOR RECALL JUNCTION BOX
(J)	JUNCTION BOX
(EA)	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
3	8/23/99	C.S.	TRANSFERRED ALL EQUIPMENT ADDED IN REV. #2 FROM TTB D-504304 TO TTB D-504948-21 ON 45TH FL. PER FIELD CONDITIONS OF FJ-65133.
2	5/25/99	C.S.	ADDED (1) PAD-2 STROBE PNL W/ASSOC. (18) SPKR/STROBES & (19) STROBES, (6) RELAYS FOR DOOR RELEASE & (1) AREA SMOKE DET. ON 45TH FL. PER FJ-65133.
1	5/25/99	C.S.	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
45TH FLOOR

DRN	A.S.
APPD	
CHCK	C.S.
CKD	
DATE	5/25/99
SCALE	N.T.S.
SHEET	1
OF	2
JOB	FJ-26840
DWG	B-504111-45
REV	3

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

45TH FLOOR



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR
SD	DUCT SMOKE DETECTOR
F/C	FUSE CUT-OUT
	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
J	JUNCTION BOX
CD	COMBINATION SMOKE & HEAT DETECTOR
SS	SUB-SYSTEM

REV	DATE	BY	DESCRIPTION
7	05/05/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON 45TH FL. PER LJ-80208.
6	12/20/99	JM	ADDED (1) SPKR./STRB., (1) AREA SMK. DET. & (1) RELAY FOR DAMPER CONTROL ON 45TH FL. FOR 'SOLOMON SMITH BARNEY' PER LJ-80021.
5	9/17/99	CS	ADDED (2) SPKR./STRBS. ON 45TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65320.
4	9/17/99	CS	CORRECTED FLOOR PAGE CKTS. FROM 'A' & 'B' TO 'C' & 'D' PER FIELD CONDITIONS.
3	8/23/99	CS	ADDED (1) STROBE ON 45TH FL. FOR 'SOLOMON SMITH BARNEY' PER FJ-65133-01.
2	8/23/99	CS	TRANFERRED (1) PAD-2 STB. PNL. W/ASSOC. CONN. (18) SPKR./STRBS., (19) STRBS. (6) RELAYS FOR DOOR RELEASE & (1) AREA SMK. DET. FROM TTB D-504304 TO TTB D-504948-21 ON 45TH FL. FOR 'SOLOMON SMITH BARNEY' PER FIELD CONDITIONS OF FJ-65133.
1	8/23/99	CS	RISER REDRAWN. SEE DWG# E-504111-5 SH. 5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
45TH FLOOR

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	7/2/99
SCALE	N.T.S.
SHEET	2
OF	2
REV	7
JOB	FJ-26840
DWG	B-504111-45

CONTRACTOR / ENGINEER

FIRECOM, INC.
CASE/ACME
39-27 STREET
WOODSIDE, NEW YORK 11377

12Y-5



THIS DRAWING IS NOT SUITABLE FOR FILING WITH THE NYC FIRE DEPT. OR BUILDING DEPT.

LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
A	AREA SMOKE DETECTOR
E	ELEVATOR LOBBY DETECTOR F = FLUSH
H	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
D	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
ER	ELEVATOR RECALL JUNCTION BOX
J	JUNCTION BOX
EA	ELEVATOR ADVANCE

SEP 09 2000

REV	DATE	BY	DESCRIPTION
4	09/08/00	JM	ADDED (4) AREA SMK. DETS. PER LJ-B0393.
3	9/23/99	CS	CORRECTED FLOOR PAGE CKTS. FROM 'A' & 'B' TO 'C' & 'D' PER FIELD CONDITIONS.
2	9/9/98	CS	ADDED (2) AREA SMK. DETS. & (1) SPKR./STROBE ON 47TH FL. PER FJ-64637.
1	9/9/98	CS	RISER REDRAWN. SEE DWG# E-504111-5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

PARTIAL RISER DIAGRAM
47TH FLOOR

DWN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	9/9/98
SCALE	N.T.S.
SHEET	1
OF	2
REV	4
JOB	FJ-26840
DWG#	B-504111-47.

CONTRACTOR | ENGINEER

FIRECOM, INC. CASE/ACME
WOODSIDE, NEW YORK 11377

124-S



LEGEND

SYMBOL	DESCRIPTION
TTB	TRANSMISSION TERMINAL BOX
⊗	STROBE LIGHT
	COMB. SPKR/STROBE
	SPEAKER F = FLUSH
(A)	AREA SMOKE DETECTOR
(E)	ELEVATOR LOBBY DETECTOR F = FLUSH
(H)	HEAT DETECTOR
SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN
F/C	FUSE CUT-OUT
☒	FAN SHUTDOWN
R	RELAY
(D)	DAMPER
DR	DOOR RELEASE
F	MANUAL STATION
WS	WARDEN STATION S = SURFACE F = FLUSH
	END OF LINE RESISTOR
	STAIR SPEAKER
WF	WATERFLOW SWITCH
TS	TAMPER SWITCH
	BI-DIRECTIONAL SPEAKER
(ER)	ELEVATOR RECALL JUNCTION BOX
(J)	JUNCTION BOX
(EA)	ELEVATOR ADVANCE

REV	DATE	BY	DESCRIPTION
2	05/05/00	JM	ADDED (RELAY FOR DOOR RELEASE ON 47TH FL. PER LJ-80208.
1	9/9/98	JM	RISER REDRAWN. SEE DWG# E-504111-5 FOR REFERENCING PAST REVISIONS.

OFFICE BUILDING
7 WORLD TRADE CENTER
N.Y.C.

CONTRACTOR | ENGINEER

PARTIAL RISER DIAGRAM
47TH FLOOR

FIRECOM, INC. CASE/ACME
39-27 STREET WOODSIDE, NEW YORK 11377

DRN	L.H.
APPVD	
ENGR	C.S.
CKD	
DATE	9/9/98
SCALE	N.T.S.
SHEET	2
OF	2
REV	2
JOB#	FJ-26840
DWG#	B-504111-47

47TH FLOOR



QTY	SYMBOL	DESCRIPTION	CAT. NO.	BSA NO.	WIRE SIZE
		FLOOR SPEAKER LETTER (A,B) INDICATES CKT. F = FLUSH W = UNI-DIR. S = SURFACE (BRACKET MTD.) BI-DIR.	6348-11 6343-11 6346-11 6343-21	379-73-SA	1 PR #16 TW
		STAIR SPEAKER LETTER (A,B) INDICATES CKT.	6345-11	379-73-SA	1 PR #16 TW
	E	ELEVATOR LOBBY SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1 PR #18 TW/SH
	A	AREA SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1 PR #18 TW/SH
	SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN	AL-DH1	840-76-SA	1 PR #18 TW/SH
	H	AREA HEAT DETECTOR	DT-135R	258-72-SA	1 PR #20 TW
	HD	DUCT HEAT DETECTOR	DTD-6	378-73-SA	1 PR #20 TW
	CD	COMBIN. SMOKE & HEAT DETECTOR SURFACE MTD			1 PR #18 TW/SH
	M	MANUAL STATION S = SURFACE F = FLUSH	250	378-73-SA	1 PR #20 TW
	WS	WARDEN STATION PR = PUMP ROOM S = SURFACE F = FLUSH	250-11 294-11	379-73-SA	1 PR #20 TW/SH 1 PR #20 TW
	MWS	COMBIN. MANUAL & WARDEN STATION S = SURFACE F = FLUSH	215	379-73-SA	2 PR #20 TW, 1 PR #20 TW/SH 1 PR #16 TW
	WF	WATERFLOW SWITCH			1 PR #20 TW
	TS	TAMPER SWITCH			1 PR #20 TW
	SS	SUB-SYSTEM	F.B.O.		1 PR #20 TW
	TTB	TRANSMISSION TERMINAL BOX SURFACE MTD		379-73-SA	SEE WIRING DIAGRAM
	RAN I	REMOTE ANNUNCIATOR S = SURFACE F = FLUSH	CR-281	379-73-SA	2 PR #16, 1 PR #20 TW 1 PR #20 TW/SH
	RAN II	REMOTE ANNUNCIATOR	9000	379-73-SA	1 PR #20 TW/SH, 1 PR #20 TW 3 PR #22 TW/SH, 2 PR #12
	PS	POWER SUPPLY RACK		379-73-SA	SEE WIRING DIAGRAM
	AMP	AMPLIFIER RACK		379-73-SA	SEE WIRING DIAGRAM
	FCS	FIRE COMMAND STATION	8510/8520	379-73-SA	SEE WIRING DIAGRAM
		FAN CONTROL (START, STOP, STATUS)	F.B.O.		2 PR #14 1 PR #18 (status)
	R	INTERFACE RELAY (ONE PER FUNCTION)			1 PR #20 TW
	ER	ELEVATOR RECALL JUNCTION BOX	F.B.O.		1 PR #16
	F/C	FUSE CUTOUT BOX			
		STROBE LIGHTS			
	D	DAMPER CONTROL	F.B.O.		1 PR #16
		END OF LINE RESISTOR FOR SPEAKER CIRCUITS USE 4.7K FOR MANUAL, WARDEN, SMOKE DETECTOR AND OTHERS USE 1.8K			

NOTE: FOR TENANT WIRING OF SPKRS & STROBES CONNECTION REFER TO DWG. 6-103114

NOTE: FOR CROSSED-OUT FLOORS SEE DWG. # B-504111-01,07,02,

REV.	DATE	BY	DESCRIPTION
23	5/4/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON THE FOLLOWING FLOORS: 3RD THRU 5TH PER LJ-80208.
22	11/19/99	CS	ADDED (1) AREA SMK. DET. & (1) RELAY FOR FAN SHUTDOWN ON 3RD FL. FOR "SPI" PER FJ-64746.
21	1/20/98	C.S	ADDED (1) RELAY FOR DOOR RELEASE ON THE 3RD FL. FOR "SPI" PER FJ-64217.
20	7/17/96	L.G	ADDED (2) SMOKE DET. ON 3RD FL PER FJ-63094
19	6/14/96	L.G	ADDED (4) SPKR/STROBES TO EXISTING CKTS ON 3RD FL PER FJ-63044
18	4/18/96	LE	ADDED (5) SPKRS./STROBES TO EXIST. CKTS., (2) DUCT SMK. DETECTORS, (2) FAN SHUTDOWN & (1) AREA SMK. DETECTOR ON 3RD FL. PER FJ-62932.
17	3/9/95	TT	ADDED (6) STROBES ON 10TH FL PER FJ-61990-01
16	10/25/94	TT	ADDED STRB SYST-3 PANEL W/ASSOC. (7) SPEAKER/STRBS, (8) STRBS, (3) DUCT DET., (3) RELAY FOR FAN SHUTDOWN, (3) RELAY FOR DOOR RELEASE & (1) RELAY FOR DAMPER RELEASE ON 9TH FL., & (6) SPKR/STRB, (6) STRBS, (1) DUCT DET, (1) RELAY FOR FAN SHUTDOWN, (3) RELAYS FOR DOOR RELEASE & (1) RELAY FOR DAMP. RELEASE ON 10TH FL. PER FJ-61990
15	4/25/94	T.T.	ADDED (3) SPEAKERS AND (3) STROBES ON 8TH FLOOR AS PER FJ-61453
14	1/28/94	L.E	ADDED RELAYS TO DOOR RELEASE RISER ON 7TH & 8TH FLOORS AS PER FJ-61536
13	12/22/93	TT	REVISED PER AS BUILT
12	12/21/93	TT	ADDED AFC101 W/ASSOC 9 STROBES 5 SPKRS, 1 HEAT DET, 1 DUCT DETECTOR & 1 RELAY FOR FAN SHUTDOWN ON 8TH FL. ADDED AFC101 W/ASSOC 14 STROBES, 9 SPKRS, SUB SYSTEM, MANUAL STATION, DUCT DET, FAN SHUTDOWN PER FT 61453
11	1/4/93	BD	ADDED POWER SUPPLY & TTB RISER AS PER FJ-60844.
10	9/15/92	TS	ADDED DOOR RELEASE ON 3RD FL PER FJ-60710 (SALOMON BROTHERS INC.)
9	5/19/92	BD	ADDED DOOR RELEASE RELAY ON 5TH FL. PER FJ-60497
8	4/27/92	BD	ADDED WATERFLOW & TAMPER SWITCH NEW ZONE ON 5TH FL PER FJ-60497.
7	6/10/91	BD	ADDED AFC-100, F/C, 6" T-BELL ON 6TH FL AS PER FJ-29876.
6	01/16/91	BD	ADDED TTB, RELAY ON 5TH FL., ANSUL SYSTEM, PREACTION SYSTEM, RELAY (PURGE) ON 4TH FL. RELAY (PURGE) RELAY (PRESS) ON 3RD FL. RELAY (PURGE) ON THE 2ND FLOOR PER FJ-28829-16.
5	10 10 90	BD	ADDED 2 DET 1ST FL, 2 MS & 2 SPKR/STROBE 2ND FL, 1 MS & 1 SPK & STROBE 36TH FL, 1 MS & 19 SPKR/STROBE 37TH FL FJ 29247
4	6-21-90	BD	ADDED MANUAL STA, SMOKE DET ON NEW ZONE & SPKRS/STROBE TO EXISTING PANEL ON 4TH FL PER FJ 29097
3	6-21-90	BD	ADDED DOOR RELEASE ON 3RD FL PER FJ 29353
2	4-4-90	JP	REVISED PER RETURN SUBMISSION
1	10-26-89	JP	REVISED PER FJ-28829
		JP	REDRAWN / GENERAL REVISION

7 WORLD TRADE CENTER
NEW YORK, NEW YORK
1ST FL. — 10TH FL.

FIRE ALARM SYSTEM
RISER DIAGRAM

DWN. SJ
APPVD.
ENGR. JP
CKD.
DATE 9-6-89
SCALE
SHEET 1 OF 5
REV 23

FIRECOM INCORPORATED
☐ FIRE CONTROLS DIV.
☐ COMMERCIAL RADIO-SOUND DIV.

JOB NO. FJ-26840
DWG. E-504111-1

WTCI-124-S



QTY	SYMBOL	DESCRIPTION	CAT. NO.	BSA NO.	WIRE SIZE
	A, B	FLOOR SPEAKER LETTER (A,B) INDICATES CKT. F = FLUSH W = UNI-DIR. S = SURFACE (BRACKET MTD.) BI-DIR.	6348-11 6343-11 6345-11 6343-21	379-73-SA	1 PR # 16 TW
	A, B	STAIR SPEAKER LETTER (A,B) INDICATES CKT.	6345-11	379-73-SA	1 PR # 16 TW
	E	ELEVATOR LOBBY SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1 PR # 18 TW/SH
	A	AREA SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1 PR # 18 TW/SH
	SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN	AL-DH1	840-76-SA	1 PR # 18 TW/SH
	H	AREA HEAT DETECTOR	DT-135R	258-72-SA	1 PR # 20 TW
	HD	DUCT HEAT DETECTOR	DTD-6	378-73-SA	1 PR # 20 TW
	CD	COMBIN. SMOKE & HEAT DETECTOR SURFACE MTD.			1 PR # 18 TW/SH
	M	MANUAL STATION S = SURFACE F = FLUSH	230	378-73-SA	1 PR # 20 TW
	WS	WARDEN STATION PR = PUMP ROOM S = SURFACE F = FLUSH	250-11 254-11	379-73-SA	1 PR # 20 TW/SH 1 PR # 20 TW
	MWS	COMBIN. MANUAL & WARDEN STATION S = SURFACE F = FLUSH	215	379-73-SA	2PR # 20 TW, 1PR # 20 TW/SH 1PR # 16 TW
	WF	WATERFLOW SWITCH			1 PR # 20 TW
	TS	TAMPER SWITCH			1 PR # 20 TW
	SS	SUB-SYSTEM	F.B.O.		1 PR # 20 TW
	TTB	TRANSMISSION TERMINAL BOX SURFACE MTD.		379-73-SA	SEE WIRING DIAGRAM
	RAN I	REMOTE ANNUNCIATOR S = SURFACE F = FLUSH	CR-251	379-73-SA	2PR # 16, 1 PR # 20 TW 1 PR # 20 TW/SH
	RAN II	REMOTE ANNUNCIATOR	9000	379-73-SA	1 PR # 20 TW/SH, 1 PR # 20 TW 3PR # 22 TW/SH, 2PR # 12
	PS	POWER SUPPLY RACK		379-73-SA	SEE WIRING DIAGRAM
	AMP	AMPLIFIER RACK		379-73-SA	SEE WIRING DIAGRAM
	FCS	FIRE COMMAND STATION	6510/6520	379-73-SA	SEE WIRING DIAGRAM
	(fan control symbol)	FAN CONTROL (START, STOP, STATUS)	F.B.O.		2 PR # 14 1 PR # 18 (status)
	R	INTERFACE RELAY (ONE PER FUNCTION)			1 PR # 20 TW
	ER	ELEVATOR RECALL JUNCTION BOX	F.B.O.		1 PR # 16
	F/C	FUSE CUTOUT BOX			
	(strobe symbol)	STROBE LIGHTS			
	RL	REMOTE LAMP			
	AFC	AFC-100 PNL. TYPICAL 14TH FL THRU 18TH FL REFER DWG. C-505456			
	(resistor symbol)	END OF LINE RESISTOR FOR SPEAKER CIRCUITS USE 4.7K FOR MANUAL, WARDEN, SMOKE DETECTOR AND OTHERS USE 1.8K			
	(comb. symbol)	COMB. SPKR./STROBE			

NOTE: FOR TENANT WIRING SPKRS & STROBES CONNECTION. REFER TO DWG C-103114

NOTE: FOR CROSSED-OUT FLOORS SEE DWG. # B-504111-13, 20,

REV.	DATE	BY	DESCRIPTION
18	11/5/97	CS	ADDED (1) DUCT SMOKE DET. & (1) RELAY FOR FAN SHUTDOWN ON 18TH FL. PER FJ-64087
17	12/9/96	T.T.	ADDED (2) SPEAKE-STROBES (1) DUCT SMOKE DETECTOR & (1) FAN SHUTDOWN ON 18TH FLOOR PER FJ-63401
16	6/24/96	L.E	ADDED (2) DUCT DETECTORS (2) RELAYS FOR FAN SHUTDOWN ON 20TH FL PER FJ-63063
15	5/6/96	L.G	ADDED (9) SPKR/STROBES (3) STROBE LIGHTS (1) RELAY FOR FAN SHUTDOWN (1) DUCT DET. (1) RELAY FOR DOOR REL. ON 19TH FL PER FJ-62947
14	8/2/95	L.G	ADDED (3) SPKR/STROBES (1) WATER FLOW ON 20TH FL PER FJ-63449
13	8/02/95	LE	DELETED (1) SPKR. & (1) STROBE ON 13TH FL. ADDED (1) SPKR./STROBE ON 13TH FLOOR PER FJ-62413-01 FOR S.E.C.
12	7/7/95	LE	ADDED (1) SPEAKER AND (1) STROBE TO EXISTING CIRCUIT ON 13TH FLOOR PER FJ-62413.
11	4/26/95	JD	ADDED (1) COMB. SPKR./STROBE AND (1) STROBE TO EXISTING CIRCUITS ON 13TH FLOOR PER FJ-62282.
10	6-14-93	JFR	ADDED DOOR RELEASE RELAY 18th Floor per FJ-60911-01
9	1-11-93	JFR	ADDED AFC-101 STROBE PNL W/ASSOC. (12) STROBE LIGHTS - ADDED (14) SPKRS TO EXISTING CKT ON 18TH FL. PER FJ-60911
8	1/4-93	BD	ADDED TTB RISER AS PER FJ-60849.
7	9/23/92	BD	REVISED FJ-60656 PER RETURNED SUBMISSION.
6	9/3/92	BD	ADDED (2) AFC-101, 34 SPEAKER/STROBE, AREA DET & RELAY FOR DOOR RELEASE ON 11TH FLOOR. ADDED (2) AFC-101, 36 SPEAKER/STROBE, AREA DETECTOR, RELAY FOR DOOR RELEASE, DUCT DETECTOR, FAN SHUTDOWN & TTB EXTENDER ON 12TH FLOOR. ADDED AFC-101 (9) SPEAKER/STROBE, (2) DUCT DET. (2) FAN SHUTDOWN ON 13TH FLOOR PER FJ-60656.
5	9/30/91	BD	ADDED AREA DET. ON 18TH FL. FJ-60131.
4	8/22/91	BD	ADDED COMBINATION SPEAKER/STROBE (2) ON 19TH FL & (5) ON 20TH FL AS PER FJ-29865-03.
3	4/29/91	BD	ADDED FAN SHUTDOWN, DUCT DET., TTB, STROBE PNLS PER FJ 29865
2	11/09/90	B.D.	ADDED STR PNL, SPKRS/STROBES, FAN SHUTDOWN ON 14TH THRU 18TH FL, SUB-SYSTEM TO 14TH FL PER FJ-29486
1		JP	REDRAWN/GENERAL REVISION

7 WORLD TRADE CENTER

NEW YORK, NEW YORK

11TH - 20TH FL.

FIRE ALARM SYSTEM RISER DIAGRAM

DWN.	S J
APPVD.	
ENGR.	J P
CKD.	
DATE	9-6-89
SCALE	
SHEET	2 OF 5
REV.	18

FIRECOM INCORPORATED
- ☐ FIRE CONTROLS DIV.
- ☐ COMMERCIAL RADIO-SOUND DIV.

JOB NO. FJ-26840

DWG E-504111-2



QTY	SYMBOL	DESCRIPTION	CAT. NO	BSA NO	WIRE SIZE
		FLOOR SPEAKER LETTER (A,B) INDICATES CKT. F = FLUSH W = UNI-DIR. S = SURFACE (BRACKET MTD.) BI-DIR.	6348-11 6343-11 6345-11 6343-21	379-73-SA	1 PR # 16 TW
		STAIR SPEAKER LETTER (A,B) INDICATES CKT.	6345-11	379-73-SA	1 PR # 16 TW
	E	ELEVATOR LOBBY SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1 PR # 18 TW/SH
	A	AREA SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1 PR # 18 TW/SH
	SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN	AL-DH1	840-76-SA	1 PR # 18 TW/SH
	H	AREA HEAT DETECTOR	DT-135R	258-72-SA	1 PR # 20 TW
	HD	DUCT HEAT DETECTOR	DTD-6	378-73-SA	1 PR # 20 TW
	CD	COMBIN. SMOKE & HEAT DETECTOR SURFACE MTD.			1 PR # 18 TW/SH
	M	MANUAL STATION S = SURFACE F = FLUSH	230	378-73-SA	1 PR # 20 TW
	WS	WARDEN STATION PR = PUMP ROOM S = SURFACE F = FLUSH	250-11 254-11	379-73-SA	1 PR # 20 TW/SH 1 PR # 20 TW
	MWS	COMBIN. MANUAL & WARDEN STATION S = SURFACE F = FLUSH	215	379-73-SA	2PR # 20TW, 1PR # 20TW/SH 1PR # 16 TW
	WF	WATERFLOW SWITCH			1 PR # 20 TW
	TS	TAMPER SWITCH			1 PR # 20 TW
	SS	SUB-SYSTEM	F.B.O.		1 PR # 20 TW
	TTB	TRANSMISSION TERMINAL BOX SURFACE MTD.		379-73-SA	SEE WIRING DIAGRAM
	RAN I	REMOTE ANNUNCIATOR S = SURFACE F = FLUSH	CR-251	379-73-SA	2PR # 16, 1 PR # 20 TW 1 PR # 20 TW/SH
	RAN II	REMOTE ANNUNCIATOR	9000	379-73-SA	1 PR # 20 TW/SH, 1 PR # 20 TW 3PR # 22 TW/SH, 2PR # 12
	PS	POWER SUPPLY RACK		379-73-SA	SEE WIRING DIAGRAM
	AMP	AMPLIFIER RACK		379-73-SA	SEE WIRING DIAGRAM
	FCS	FIRE COMMAND STATION	8510/8520	379-73-SA	SEE WIRING DIAGRAM
		FAN CONTROL (START, STOP, STATUS)	F.B.O.		2 PR # 14 1 PR # 18 (status)
	R	INTERFACE RELAY (ONE PER FUNCTION)			1 PR # 20 TW
	ER	ELEVATOR RECALL JUNCTION BOX	F.B.O.		1 PR # 16
	F/C	FUSE CUTOUT BOX			
		STROBE LIGHTS			1PR # 14
		COMB. SPKR./STROBE			1PR # 14
		END OF LINE RESISTOR FOR SPEAKER CIRCUITS USE 4.7K FOR MANUAL, WARDEN, SMOKE DETECTOR AND OTHERS USE 1.8K			

NOTE: FOR TENANT WIRING SPKRS & STROBES CONNECTION REFER TO DWG. 6.103114

NOTE: FOR CROSSED-OUT FLOORS SEE DWG.# B-504111-23, 30, 24, 22,

REV.	DATE	BY	DESCRIPTION
33	5/4/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON THE FOLLOWING FLOORS 21ST & 26TH THRU 30 PER LJ-80208.
32	4/22/98	CS	ADDED (3) SPKR./STROBES ON THE 22ND FL., PER FJ-64400.
31	8/15/97	CS	ADDED (1) STROBE LIGHT ON 21ST FL. PER FJ-63964
30	7/22/97	CS	ADDED (4) SPEAKERS & (6) STROBES ON 25TH FL PER FJ-63887
29	5/20/97	T.T.	ADDED (1) SPKR/STROBE ON 21ST FL. PER FJ-63762
28	4/6/97	LE	ADDED (4) SPKRS./STROBES ON 21ST FLOOR PER FJ-63685 FOR 'SOLOMON BROS' (F.B.O.).
27	4/7/97	CS	ADDED (1) RELAY FOR DOOR RELEASE ON 21ST FL PER FJ-63677
26	9/19/96	L.G.	ADDED (1) SPKR ON 21ST FL PER FJ-63243
25	7/9/96	JD	ADDED (4) SPKR./STROBES, (4) STROBES, (2) SPEAKERS TO EXIST. CKT. ADDED (1) DUCT SMK. DET. (1) FAN SHUTDOWN & DOOR RELEASE ON 21ST FLR. FOR FIRST STATE MNGT. PER FJ-63102.
24	5/17/96	LE	ADDED (2) SPKR./STROBES, (2) STROBES ON 22ND FLOOR PER FJ-62997 FOR FEDERAL HOME.
23	3/27/96	TT	ADDED (2) COMB. SPKR/STRBS, (1) DUCT DET., (1) RELAY FOR FAN SHUTDOWN ON 21ST FLOOR AS PER FJ-62858
22	11/16/95	JD	ADDED PREACTION PANEL TBL. AND ALARM ON 26TH FLOOR PER AS BUILT.
21	11/10/95	JD	ADDED (2) STROBES ON 26TH & 27TH FL. PER FJ 62532-02.
20	11/2/95	JD	CHANGED WF & TS DESIG. TO PREACTION ALARM & TROUBLE RESP. PER FJ-62532-01.
19	10/19/95	JD	ADDED DUCT SMOKE DET. W/ASSOC. FAN START/STOP ON 26TH & 27TH FLOORS PER FJ-62532-01 FOR STD. CHARTERED BANK
18	9/12/95	JD	PER FJ-62532 26TH & 27TH FLOOR: ADDED STROBE PANEL WITH ASSOCIATED STROBE LIGHTS - ADDED SPEAKERS TO EXISTING CIRCUITS - ADDED MANUAL PULL STATION TO EXISTING ZONE - ADDED NEW ZONE FOR FAN SHUTDOWN - ADDED DOOR RELEASE - 27TH FLOOR: ADDED NEW ZONE FOR DUCT DETECTOR, FAN SHUTDOWN, WF & TAMPER SW, PREACT. PNL. ALM & TBL.
17	5/10/94	L.E.	ADDED PRE-ACTION PANEL ON 22ND FLOOR AS PER FJ-61655-01
16	4/24/94	L.E.	ADDED (2) STROBE PNL. W/ASSOC. (33) STROBES, (2) TROUBLE BELLS (2) FUSE CUT-OUT. ALSO ADDED (3) SMK. DUCT DETS., (3) FAN SHUTDOWN AND PRE-ACTION PANEL FOR ALARM & TBL. ON 22ND FL. PER FJ-61655
15	3/24/93	J.D.	ADDED (10) COMBINATION SPEAKERS/STROBES ON 28TH FLR. FOR SALOMON BROTHERS PER FJ-61296-03
14	11/2/93	LE	REPLACED (3) DUCT DETS WITH COMB. SMOKE/HEAT DET. ON 28TH FLR AS PER FJ-61296-04
13	8-31-93	AS	ADDED (6) COMB. SPKR/STROBES TO EXIST. CKTS - ADDED (4) DUCT SMK DET ON NEW ZONES & (1) RELAY FOR FAN START/STATUS / STOP PER FJ-61296 ON 28TH FL
12	1/4/93	BD	ADDED TTB RISER AS PER FJ-60844.
11	1/30/92	AS	ADDED (2) SMOKE DETECTOR ON 28TH FL PER FJ-60288.
10	8/23/91	BD	ADDED AREA DET. ON 21ST FL, AS PER FJ-29865-09.
9	7/22/91	BD	ADDED (2) SUB-SYSTEM PRE-ACTION PANEL ON 28TH FL. AS PER FJ-29994.
8	4/26/91	BD	ADDED AFC-100, F/C, 6" T-BELL, 15 COMB. SPKR/STROBES ON 21ST FL. AS PER FJ-29865.
7	4/1/91	BD	ADDED 21 COMB. SPKR/STROBE ON THE 28TH FLOOR PER FJ-29814.
6	11-12-90	BD	ADDED PRE-ACTION SYST. ON 29TH FL thru 32ND FL 34TH, 35TH FL, 38TH FL thru 47TH FL & 4TH FL. PER FJ-28229
5	6-21-90	BD	ADDED 17 SPKRS/STROBE ON 30TH FL PER FJ 29099
4	6/21/90	BD	ADDED 17 SPEAKERS/STROBE ON 29TH FL PER FJ 29099
3	6-21-90	B.D.	ADDED DOOR RELEASE ON 28TH FL PER FJ 29353
2	4-4-90	JP	REVISED PER RETURN SUBMISSION
1	10-27-89	JP	REVISED PER FJ-28829
		JP	REDRAWN / GENERAL REVISION

7 WORLD TRADE CENTER
NEW YORK, NEW YORK
21ST FL - 30TH FL.

FIRE ALARM SYSTEM RISER DIAGRAM

DWN. SJ
APPVD.
ENGR. JP
CHD.
DATE 3-6-89
SCALE

FIRECOM INCORPORATED
☐ FIRE CONTROLS DIV.
☐ COMMERCIAL RADIO-SOUND DIV.

JOB NO. FJ-25840
DWG. E504113
SHEET 3 OF 5
33

124-5



QTY	SYMBOL	DESCRIPTION	CAT. NO.	BSA NO.	WIRE SIZE
	▽ A / ▽ B / ▷□◁	FLOOR SPEAKER LETTER (A,B) INDICATES CKT. F = FLUSH W = UNI-DIR. S = SURFACE (BRACKET MTD.) BI-DIR.	6348-11 6343-11 6345-11 6343-21	379-73-SA	1PR # 16 TW
	▼ A / ▼ B	STAIR SPEAKER LETTER (A,B) INDICATES CKT.	6345-11	379-73-SA	1PR # 16 TW
	(E)	ELEVATOR LOBBY SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1PR # 18 TW/SH
	(A)	AREA SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1PR # 18 TW/SH
	SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN	AL-DHI	840-76-SA	1PR # 18 TW/SH
	(H)	AREA HEAT DETECTOR	DT-138R	256-72-SA	1PR # 20 TW
	HD	DUCT HEAT DETECTOR	DTD-6	378-73-SA	1PR # 20 TW
	(CD)	COMBIN. SMOKE & HEAT DETECTOR SURFACE MTD.			1PR # 18 TW/SH
	M	MANUAL STATION S = SURFACE F = FLUSH	230	378-73-SA	1PR # 20 TW
	WS	WARDEN STATION PR = PUMP ROOM S = SURFACE F = FLUSH	250-11 254-11	379-73-SA	1PR # 20 TW/SH 1PR # 20 TW
	MWS	COMBIN. MANUAL & WARDEN STATION S = SURFACE F = FLUSH	215	379-73-SA	2PR # 20TW, 1PR # 20TW/SH 1PR # 16 TW
	WF	WATERFLOW SWITCH			1PR # 20 TW
	TS	TAMPER SWITCH			1PR # 20 TW
	SS	SUB-SYSTEM	F.B.O.		1PR # 20 TW
	TTB	TRANSMISSION TERMINAL BOX SURFACE MTD.		379-73-SA	SEE WIRING DIAGRAM
	RAN I	REMOTE ANNUNCIATOR S = SURFACE F = FLUSH	CR-251	379-73-SA	2PR # 16, 1PR # 20 TW 1PR # 20 TW/SH
	RAN II	REMOTE ANNUNCIATOR	9000	379-73-SA	1PR # 20 TW/SH, 1PR # 20 TW 3PR # 22 TW/SH, 2PR # 12
	PS	POWER SUPPLY RACK		379-73-SA	SEE WIRING DIAGRAM
	AMP	AMPLIFIER RACK		379-73-SA	SEE WIRING DIAGRAM
	FCS	FIRE COMMAND STATION	8510/8520	379-73-SA	SEE WIRING DIAGRAM
	⊠	FAN CONTROL (START, STOP, STATUS)	F.B.O.		2PR # 14 1PR # 18 (status)
	R	INTERFACE RELAY (ONE PER FUNCTION)			1PR # 20 TW
	(ER)	ELEVATOR RECALL JUNCTION BOX	F.B.O.		1PR # 16
	F/C	FUSE CUTOUT BOX			
	⊗	STROBE LIGHTS			
		END OF LINE RESISTOR FOR SPEAKER CIRCUITS USE 4.7K FOR MANUAL, WARDEN, SMOKE DETECTOR AND OTHERS USE 1.8K			

NOTE: FOR TENANT WIRING OF SPKRS/STROBES CONNECTION REFER TO DWG. 6-103114

NOTE:
FOR CROSSED-OUT FLOORS SEE DWG. # E-504111-39, 37, 38, 40, 31, 32, 33, 36,

REV.	DATE	BY	DESCRIPTION
20	5/4/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON THE FOLLOWING FLOORS 34TH & 35TH PER LJ-80208.
19	5/28/97	TT	ADDED NEW AFC-102 STROBE PNL & (16) SPEAKER/STROBES ON 34TH FL. PER FJ-63788.
18	3/13/97	JD	ADDED CONNECTIONS FOR PRESSURIZATION/PURGE ON 39TH FL. PER AS BUILT.
17	12/5/94	JD	ADDED (2) SPKRS./STROBES TO EXIST. CKT. ON 37TH FLOOR PER FJ-62066.
16	8-31-93	AS	ADDED STROBE PANEL & 8-COMB/SPKR STROBES & 1-P.E. DETECTOR ON 34TH FLOOR AS PER FJ-61296 AND FJ-61296-02
15	9-17-90	B.D	ADDED 14 COMB/SPEAKERS/STR ON 38TH FL & 14 COMB/SPKRS/STR ON 39TH FL PER FJ-29485
14	7-9-90	BD	ADDED MANUAL STATION ON 36th, 37th FL PER FJ 29027
13	7-9-90	BD	ADDED 11 SPKS/STR ON 35TH FL PER FJ-29143
12	"	"	ADDED 25 SPKS/STROBE ON 34TH FL PER FJ-29098
11			
10	7-9-90	B.D	ADDED 19 SPKRS STROBES ON 36TH, 37TH FL PER FJ-29247
9	7-9-90	B.D	ADDED 14 SPKRS STROBES ON 40TH FL PER FJ-1247
8			
7	6-21-90	B.D	ADDED 20 SPEAKERS/STROBE ON 33TH FL PER FJ 29099
6	6-21-90	BD	ADDED 19 SPEAKERS/STROBE ON 31ST, 32ND FLOOR PER FJ 29099
5	6-1-90	BD	CLASS "E" DOOR RELEASE RELAYS (PER DWG EB-7)
4	6-21-90	BD	ADDED DOOR RELEASE ON 32ND & 33RD FL PER FJ 24353
3	4-4-90	JP	REVISED PER RETURN SUBMISSION
2	1-17-90	JP	REVISED PER CONTRACT DWG C-340 ON 40TH FLR. PER FJ-29027
1	10-26-89	JP	REVISED PER FJ-28829
		JP	REDRAWN / GENERAL REVISION

7 WORLD TRADE CENTER
NEW YORK, NEW YORK
31ST FL - 40TH FL.

FIRE ALARM SYSTEM
RISER DIAGRAM

DWN. SJ
APPVD
ENGR. JP
CKD
DATE 9-6-89
SCALE

FIRECOM INCORPORATED
☐ FIRE CONTROLS DIV.
☐ COMMERCIAL RADIO-SOUND DIV.

JOB NO. FJ-26840
DWG. E-504111-4
SHEET 4 OF 5
REV 20

124-5



QTY	SYMBOL	DESCRIPTION	CAT. NO.	BSA NO.	WIRE SIZE
	A / B / ▷□◁	FLOOR SPEAKER LETTER (A,B) INDICATES CKT. F = FLUSH W = UNI-DIR. S = SURFACE (BRACKET MTD.) BI-DIR.	6348-11 6343-11 6345-11 6343-21	379-73-SA	1 PR # 16 TW
	A / B	STAIR SPEAKER LETTER (A,B) INDICATES CKT.	6345-11	379-73-SA	1 PR # 16 TW
	E	ELEVATOR LOBBY SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1 PR # 18 TW/SH
	A	AREA SMOKE DETECTOR S = SURFACE F = FLUSH	PID-C	840-76-SA	1 PR # 18 TW/SH
	SD	DUCT SMOKE DETECTOR S = SUPPLY R = RETURN	AL-DH1	840-76-SA	1 PR # 18 TW/SH
	H	AREA HEAT DETECTOR	DT-135R	258-72-SA	1 PR # 20 TW
	HD	DUCT HEAT DETECTOR	DTD-6	378-73-SA	1 PR # 20 TW
	CD	COMBIN. SMOKE & HEAT DETECTOR SURFACE MTD.			1 PR # 18 TW/SH
	M	MANUAL STATION S = SURFACE F = FLUSH	230	378-73-SA	1 PR # 20 TW
	WS	WARDEN STATION PR = PUMP ROOM S = SURFACE F = FLUSH	250-11 254-11	379-73-SA	1 PR # 20 TW/SH 1 PR # 20 TW
	MWS	COMBIN. MANUAL & WARDEN STATION S = SURFACE F = FLUSH	215	379-73-SA	2 PR # 20 TW, 1 PR # 20 TW/SH 1 PR # 16 TW
	WF	WATERFLOW SWITCH			1 PR # 20 TW
	TS	TAMPER SWITCH			1 PR # 20 TW
	SS	SUB-SYSTEM	F.B.O.		1 PR # 20 TW
	TTB	TRANSMISSION TERMINAL BOX SURFACE MTD.		379-73-SA	SEE WIRING DIAGRAM
	RAN I	REMOTE ANNUNCIATOR S = SURFACE F = FLUSH	CR-251	379-73-SA	2 PR # 16, 1 PR # 20 TW 1 PR # 20 TW/SH
	RAN II	REMOTE ANNUNCIATOR	9000	379-73-SA	1 PR # 20 TW/SH, 1 PR # 20 TW 3 PR # 22 TW/SH, 2 PR # 12
	PS	POWER SUPPLY RACK		379-73-SA	SEE WIRING DIAGRAM
	AMP	AMPLIFIER RACK		379-73-SA	SEE WIRING DIAGRAM
	FCS	FIRE COMMAND STATION	8510/8520	379-73-SA	SEE WIRING DIAGRAM
	⊠	FAN CONTROL (START, STOP, STATUS)	F.B.O.		2 PR # 14 1 PR # 18 (status)
	R	INTERFACE RELAY (ONE PER FUNCTION)			1 PR # 20 TW
	ER	ELEVATOR RECALL JUNCTION BOX	F.B.O.		1 PR # 16
	F/C	FUSE CUTOUT BOX			
	⊗	STROBE LIGHTS			
		END OF LINE RESISTOR FOR SPEAKER CIRCUITS USE 4.7K FOR MANUAL, WARDEN, SMOKE DETECTOR AND OTHERS USE 1.8K			

NOTE: FOR TENANT SPKRS. & STROBES CONNECTIONS REFER TO DWG C-103114

NOTE: FOR CROSSED-OUT FLOORS SEE DWG #B-504111-47, 45, 41, 42, 43

4#16 TIE TO EXIST. SPKR. CKT. 'A' ON THIS FLOOR
4#16 TIE TO EXIST. STROBE CKT. 'A' ON THIS FLOOR

REV.	DATE	BY	DESCRIPTION
18	5/4/00	JM	ADDED (1) RELAY FOR DOOR RELEASE ON THE FOLLOWING FLOORS: 44TH & 46TH PER LJ-80208.
17	1-15-98	CS	ADDED (1) MANUAL PULL STATION ON THE 47TH FL. FOR "SOLOMON BROTHERS", PER FJ-64222.
16	6/2/97	TT	ADDED (15) SPEAKER/STROBES & (2) MANUAL PULL STATIONS ON 47TH FLOOR PER FJ-63789.
15	3/13/97	JD	ADDED CONNECTIONS FOR PRESSURIZATION/PURGE ON 42ND FL. SHOWN CONNECTIONS FOR DAMPER CTL. ON 47TH FL. PER AS BUILT
14	02/25/97	C.S.	ADDED (1) SPEAKER STROBE ON 47TH FL. PER FJ-63574
13	7/24/96	JD	REVISED PER AS BUILT.
12	5/19/92	BD	ADDED COMB. SMOKE & HEAT DET. ON 41ST & 43RD FLOORS PER FJ-60493.
11	1-31-92	JFR	ADDED DOOR RELEASE RELAY ON 45TH FL. PER FJ-60271.
10	02/12/91	BD	REVISED AS PER FJ-28829-20
9	9-10-90	BD	ADDED 18 COMB/SPKRS/STR. ON 46 FL. 47 FL. PER FJ-29483
8	9-10-90	B.D	ADDED AFC-100, COMB/SPKS/STROBES, MANUAL STA, SMK DET, ON 45TH FL PER FJ-29484
7	9-9-90		ADDED WARDEN STATION 41 & 42ND FL PER FJ-29027
6	7-9-90	BD.	ADDED 11 SPKS/STR ON 44TH FL PER FJ-29143
5	7-9-90	BD	ADDED 38 SPKS STR. ON 41ST FL. PER FJ-29027 " 14 " " ON 42ND " PER FJ- " "
4	6-21-90	BD	ADDED DOOR RELEASE ON 42ND FL & 43RD FL PER FJ29353
3	4-4-90	JP	REVISED PER RETURN SUBMISSION
2	1-17-89	JP	REVISED PER CONTRACT DWG C-341-C-343 REV.1 & 41ST-43RD FL AND 42ND FL PER CONTRACT DWG C-342, PER FJ-28027
1	10-26-89	JP	REVISED PER FJ-28829
		JP	REDRAWN/GENERAL REVISION

7 WORLD TRADE CENTER

NEW YORK, NEW YORK

41ST FL. – ROOF

FIRE ALARM SYSTEM RISER DIAGRAM

DWN. SJ
APPVD.
ENGR. JP
CKD.
DATE 9-6-89
SCALE

FIRECOM INCORPORATED
FIRE CONTROLS DIV.

JOB NO. FJ-26840 SHEET 5 OF 5

124-5